

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	4	1	4	1	4			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	1	9	1	9	1	9	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		16		16		16			
3	MDK	107	933		1		1		1			
4	SDPT			3	9	3	9	3	9			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	27	3	27	3	27	0	0	
	Grand Total	1082	6468	4	36	4	36	4	36	0	0	

TSSPDCL - LMRC / Corporate office

Date: 08.08.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDP	Habsipur	Peddacheekode	33KV	Siddipet	15.35	16.15	00.40		Heavey wind and gale	Peddacheekode	-
2		Habsipur	Ragothampally	33KV	Siddipet	15.45	17.15	01.30		Heavey wind and gale	Ragothampally	-
3		Habsipur	Thimmapur	33KV	Siddipet	15.50	16.35	00.45		Heavey wind and gale	Thimmapur	-
1	RR N	132KV Medchal	33KV Devarayamjal	33KV	Medchal	11.25	14.25	03.00	BD	No Visible Fault	33KV Devarayamjal	-

TSSPDCL - LMRC / Corporate office

Date: 08.08.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
1	MBNR	Kandur	Komreddypally	11KV	Jadcherla	07.35	08.38	01.03		11 KV pin insulater fail near Kommreddy pally.	-	
1	NLG	Marriguda	Y.G.Pally	11KV	Devarakonda	16.00	17.40	01.40	E/L	Momentfault	-	
2		Pendlipakala	Pendlipakala	11KV	Devarakonda	15.20	17.40	02.20	E/L	Jumper cut	-	
3		Nampally	Madanapuram	11KV	Devarakonda	13.00	14.00	01.00	E/L	Jumper cut	-	
4		Veliminedu	Gundrampally	11KV	Nalgonda	14.00	17.00	03.00	E/L	11KV Insulator Fail	-	
5		Palem	Palem	11KV	Nalgonda	03.00	08.10	05.10	E/L	11KV Insulator Fail	-	
6		Pamanagundla	Ismailpally	11KV	Nalgonda	05.00	09.30	04.30	E/L	11KV Insulator Fail	-	
7		Nagaram	Wardhamanu Kota	11KV	Suryapeta	14.30	17.00	02.30	E/L	Conductor snapped	-	
8		Ananthagiri	Shantinagar	11KV	Huzurnagar	05.00	07.30	02.30	EL	11 KV LINE SNAPPED	-	
9		Dondapahad	Dondapahad	11KV	Huzurnagar	06.00	09.30	03.30	EL	pole Damaged	-	
10		Sirikonda	Lalthanda	11KV	Huzurnagar	05.00	08.15	03.15	EL	11 KV JUMPER CUT	-	
11		Siripuram	Srirangapuram	11KV	Huzurnagar	04.00	06.50	02.50	EL	11 KV LINE SNAPPED	-	
12		Dirncherla	Yallapuram	11KV	Huzurnagar	11.00	14.00	03.00	EL	11 KV LINE SNAPPED	-	
13		MT.Pally	Dharmaram	11KV	Bhongiri	06.00	10.00	04.00	EL/OL	11kv Insulator Failed	-	
14		Bibinagar	Gudur	11KV	Bhongiri	05.00	09.00	04.00	EL	11kv Pin Insulator Failed near Gudur Village	-	
15			Kondamadugu	Makariya	11KV	Bhongiri	09.25	10.50	01.25	EL	11kv Line snapped near Kondamadugu Village	-
16			Venkiryala	Venkiryala Indl	11KV	Bhongiri	05.30	10.05	04.35	EL	11kv Insulator Failed near Vinkireyala Village	-
1	MDK	Hathnoora	Town Ind	11KV	Jogipet	15.40	16.20	00.40		BD due to Tree fallen on line	-	
1	SDP	Thimmareddypally SS	11KV Thimmareddypally AGL feeder	11KV	Gajwel	14.50	19.05	04.15		11KV Line cut	-	
2		THUNKIKALSA	11KV Chakaram Feeder	11KV	Gajwel	14.05	15.45	01.40		11KV Jumper cut	-	
3		Wargal	11KV Wargal Agl Feeder	11KV	Gajwel	20.00	07.00	13.00		11KV Pin Insulator fail	-	
4		Jagadevapur	Ettikyala	11KV	Gajwel	17.05	19.00	01.55		Tree branches fallen on the 11KV line	-	
5		Akunoor	Rampoor	11KV	Husnabad	17.00	19.00	02.00		3 Ph BD, Due to rain, 1Ph ok	-	
6		Nagapuri	Gandikunta	11KV	Husnabad	16.35	19.35	03.00		3 Ph BD, 1Ph ok, Due to rain	-	
7		Nagapuri	Nagapuri	11KV	Husnabad	00.00	03.00	03.00		3 Ph BD, 1Ph ok, Due to rain	-	
8		Nagapuri	Pothireddypalli	11KV	Husnabad	00.00	09.10	09.10		3 Ph BD, 1Ph ok, Due to rain	-	
9		Rebarthy	Gagillapur Agl	11KV	Husnabad	06.50	19.25	12.35		BD Due to rain	-	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Jeedimetla-II	N R S A	11KV	Jeedimetla	12.23	13.43	01.20	BD	11kv Jumper Snapped At Phase-I	-
2		Athiwelly	Athiwelly	11KV	Medchal	14.40	16.30	01.50	BD	Tree Fallen on the 11KV Line at Kindi Basti, Bondalagadda	-
3		Medchal	IDA Kandlakoya	11KV	Medchal	10.35	12.23	01.48	BD	LT Pole Touched on the 11KV Line at Beer Company Opposite	-
4		ICICI	Unique-I	11KV	Medchal	16.40	19.40	03.00	BD	11KV Line cut near SS	-
1	RR E	Uppal Bhagath	Saraswathi Nagar	11KV	Habsiguda	13.33	15.20	01.47		11KV line cut near HMDA Layout at Uppal Main Road	-
1	HYD N	Jana Priya	Bharath Nagar	11KV	IV	00.07	02.32	02.25	EL	5 Way RMU fault at Bharath Nagar Fly Over	-
1	HYD S	C.R.P.F	Barkas	11KV	III	12.50	14.25	01.35	EL,OL-Rph	No Visible Fault	-
1	HYD C	Amberpet	Play Ground	11KV	II	22.17	00.10	01.53	EL,OL-R&Yph	Tree fallen on lines at Amberpet (11KV Bapu Nagar partial fdr also interrupted, due to B/F on 11KV Paly Ground fdr)	-
2		Z.P.Office	Seven Temple	11KV	I	22.36	00.04	01.28	OL	3Way RMU fault at Water Falls	-