

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1		1		1				
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988	1	8	1	8	1	8			
3	MDK	107	933		1		1		1			
4	SDPT				7		7		7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>16</b>	<b>3</b>	<b>16</b>	<b>3</b>	<b>16</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>17</b>	<b>4</b>	<b>17</b>	<b>4</b>	<b>17</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 08.08.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Ghanapur	Lattupally	33KV	Nagarkurnool	20.45	00.00	03.15	EL	Break down due to Heavy Gail & Rain	Lattupally	Alternate supply Arranged from 132KV Nagarkurnool
2		Mahabubnagar	Jadcherla	33KV	Mahabubnagar	11.56	12.06	00.10	EL	Break down due to Heavy Gail	Jadcherla	Alternate supply Arranged from Polepally
1	NLG	Kodada	Siripuram	33KV	Huzurnagar	09.35	10.20	00.45	O/L	33Kv line snapped	Siripuram	132KV Mungal to 33Kv Nadigudem on 10:20AM
1	HYD N	132KV Gunrock	Macha Bollarum	33KV	Nehru Ngr	09.45	10.00	00.15	EL	Cable fault at Select Talkies, Bollarum	Macha Bollarum	Loads tranferred onto 132KV Gunrock SS via 33KV Hakimpet SS

TSSPDCL - LMRC / Corporate office

Date: 08.08.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kesharajupally	Kesharajupally	11KV	Nalgonda	12.10	15.00	02.50	E/L	11KV Insulator Fail	-
2		Narketpally IE	Vanipakala	11KV	Nalgonda	08.20	11.20	03.00	E/L	11Kv Jumper cut	-
3		Pullemla	Kondapuram	11KV	Nalgonda	08.15	11.10	02.55	E/L	Tree fallen on the line	-
4		Aitipamula	Ch.Annaram	11KV	Nalgonda	10.30	13.10	02.40	E/L	Tree fallen on the line	-
5		Aipoor	Kotapahad	11KV	Suryapet	12.25	14.00	01.35	E/L	11Kv Insulator failed	-
6		Garidepally	L B Nagar	11KV	Huzurnagar	11.00	14.00	03.00	E/L	11Kv line cut	-
7		Bethavolu	Bethavolu	11KV	Huzurnagar	23.30	02.15	02.45	E/L	11Kv line snapped	-
8		Alair	Ch.Kandukur	11KV	Bhongir	10.00	13.00	03.00	E/L	11kv Pin Insulator Failed near Chinnakondur (V)	-
1	MDK	Pati	Shalimar	11KV	Patancheru	13.50	14.55	01.05		BD due to Tree fallen on line	-
1	SDP	Potharam	Mirzapoor	11KV	Husnabad	11.25	13.00	01.35		Conductor snapped	-
2		Bejjanki	Regulapally	11KV	Husnabad	13.10	17.30	04.20		Tree Branches fallen	-
3		Nagapuri	Gandikunta	11KV	Husnabad	08.45	09.15	00.30		Jumper cut	-
4		Chityal	Chityal Agl	11KV	Husnabad	13.10	14.30	01.20		O/L Jumper cut	-
5		Gowraram	Mylaram	11KV	Gajwel	21.45	06.00	08.15		phase to phase fault due to snake	-
6		Doulthabad	sheripally bandaram	11KV	Gajwel	14.15	16.16	02.01		100 KVA DTR Fault	-
7		Dom mata	Surampally	11KV	Gajwel	11.27	13.01	01.34		tree branch fallen on feeder	-
1	RR N	Kompally	NCL	11KV	Medchal	11.55	13.20	01.25		11KV Line AB Switch Opened at Prajay Apartment(Cloth fallen on the 11KV Line)	-