

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044	1		1		1				
	Total	606	3055	1	0	1	0	1	0	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		4		4		4			
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	12	1	12	1	12	0	0	
	Grand Total	1082	6468	2	12	2	12	2	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 10.08.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Ramannapet	Chityala	33KV	Nalgonda	14:22	18:24	4:02		Tree branches fallen on the line and 33KV Insulator failed	Chityala	No
1	HYD S	132KV Moosarambagh	Malakpet B-Quarters	33KV	Malakpet	16.07	16.20	00.13	OL-R&Bph	Cable damaged	Malakpet B-Quarters	Loads transferred onto 33KV Ch' Gutta - Laxmi Nagar

TSSPDCL - LMRC / Corporate office

Date: 10.08.19

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karkonda	Fathepur	11KV	Jadcherla	07.00	11.30	04.30		DTR Failure at Vadde Gudiselu Fathepur (V)	No
2		Kothamolgara	Elkicherla	11KV	Jadcherla	20.10	09.00	12.50		11KV Insulator failed & 11kv Conductor cut near Maddigatla Gate	No
3		Janampet	Annasagar	11KV	Jadcherla	20.01	06.29	10.28		Tree fallen on the 11KV line near Annasagar (V)	No
4		Udithyal	Udithyal	11KV	Jadcherla	7:49	9:28	1:39		Bird Died on the 11KV Line near Panthulu Bavi Udithyal (V)	No
1	NLG	B.Vellemla	Avravani	11KV	Nalgonda	8:00	13:00	5:00	E/L	Momentary fault	No
2		Kurampally	Kurumarthy	11KV	Nalgonda	10.00	12.30	02.30	E/L	11KV Disc failed	No
3		Dirsincherla	Somaram	11KV	Huzurnagar	04.30	07.30	03.00	EL	11KV Line snapped	No
4		Huzurnagar	Y.Singaram	11KV	Huzurnagar	01.30	04.30	03.00	EL	11KV Line snapped	No
5		Munagala	Nelamarry	11KV	Huzurnagar	03.00	06.00	03.00	EL	Jumper cut	No
6		Raghunadapalem	Nakkagudem	11KV	Huzurnagar	11:55	15:02	3:07	OL	Jumper cut	No
1	SDPT	Komuravelly	Posanpally	11KV	Husnabad	8:15	12:05	3:50		Insulator failure	No
2		Pandilla	Kunchanpally	11KV	Husnabad	19.10	21.30	02.20		Jumper cut	No