

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1		1		1				
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	8	1	8	1	8			
3	MDK	107	933									
4	SDPT			1	6	1	6	1	6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>14</b>	<b>2</b>	<b>14</b>	<b>2</b>	<b>14</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>15</b>	<b>3</b>	<b>15</b>	<b>3</b>	<b>15</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 11.08.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Madgulapally	Buggabaigudem	33KV	Miryalaguda	14.30	17.30	03.00	EL	Keep out nut and insulater fall on 33KV kasaram near Kasturba girls hostel in Kukkadam village	Madgulapally	NO
1	SDPT	Siddipet	Naryanraopet	33KV	Siddipet	09.25	11.55	02.30		B/D Rectified Lizard Fall Down Lc no 13811	Siddipet	NO
1	HYD N	132KV I.D.P.L.	Bowenpally (PTR-2)	NT	Nehru Ngr	04.15	04.22	00.07	EL,OL-Rph	Cable damaged by unknown person at Narsapur X Road	132KV I.D.P.L.	Loads transferred onto 132KV Gunrock SS via 33KV HMT fdr

TSSPDCL - LMRC / Corporate office

Date: 11.08.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ogodu	Ogodu	11KV	Nalgonda	06.00	10.00	04.00	E/L	11KV Line Cut	-
2		Madgulapally	Indugula	11KV	Nalgonda	11.20	13.40	02.20	E/L	11KV Line Disc Failur	-
3		Appajipeta	Bantugudem	11KV	Nalgonda	14.10	16.00	01.50	E/L	11KV Line Jumper Cut	-
4		G.T Giri	Gunjalooru	11KV	Suryapet	08.30	10.00	01.30	E/L	Tree Branch fallen on the line	-
5		Dirsincherla	Somaram	11KV	Huzurnagar	13.00	14.45	01.45	EL	Due to 11Kv jumper cutted	-
6		Garidepally	Appannapet	11KV	Huzurnagar	10.30	12.40	02.10	EL	Due to 11Kv jumper cutted	-
7		Akupamula	Akupamula Agl	11KV	Huzurnagar	00.00	02.45	02.45	EL	Due to 11Kv line snapped	-
8		Gaddipaly	Gaddipally	11KV	Huzurnagar	03.45	06.45	03.00	EL	Due to Tree branch fall on 11Kv line	-
1	SDPT	MULUGU SS	BAILAMPOOR	11KV	Gajwel	00.00	17.30	17.30		DISC FAILURE	-
2		GURRALASOPA SS	WADDEPALLY	11KV	Gajwel	13.00	17.05	04.05		DISC FAILURE	-
3		RAYAPOLE SS	THIMAKKAPALLY	11KV	Gajwel	20.40	22.00	01.20		INSULATER PROBLEM	-
4		Mustyal	Chuchanakota	11KV	Husnabad	00.00	06.25	06.25		No Visable fault	-
5		Potharam	Potharam Rural	11KV	Husnabad	05.40	06.30	00.50		BD,HT/LT Conductor snapped	-
6		Rebarthy	Gagillapur Agl	11KV	Husnabad	03.55	09.30	05.35		BD,Insulator failure	-
1	RR N	Kompally	Jaibheri	11KV	Medchal	17.11	18.09	00.58	BD	11KV UG Cable failed at Gurusai Apartment	-