

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		2		2				1 No. 33KV Still
2	NLG	144	988		6		6		6			
3	MDK	107	933	2		2		2				
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	8	4	8	4	8	0	0	
	Grand Total	1082	6468	5	9	4	9	4	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 15.08.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Solipur	33KV	Wanaparthy	07.54	08.30	00.36	E/L	Alternate Supply Taken to 132KV SS Ghanpur at 8:30Hrs	Solipur	Alternate Supply Taken to 132KV SS Ghanpur at 8:30Hrs
2		Amrachinta	Chandragattu Lift	33KV	Wanaparthy	00.00	08.07	08.07	E/L	Panel Board Brunt Out at SS	Chandragattu Lift	No
3		Gadwal	Nandinne	33KV	Gadwal	19.25	Still		E/L	Due to Heavy Rain Not Rectifeid	Nandinne	No
1	MDK	RC Puram	Ashok nagar	33KV	Patancheru	16.15	19.15	03.00		BD due to 2 No.s Jumpers snapped at Bheeramguda	Ashok nagar	-
2		Gummadidala	AFA	33KV	Patancheru	10.13	11.45	01.32		BD due to Monkey fallen on 33KV line	AFA	-

TSSPDCL - LMRC / Corporate office

Date: 15.08.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Akaram	Akaram	11KV	Nalgonda	13.30	16.00	02.30	E/L	11KV Line Disc Failur	-
2		Aregudem	Ch.Kaparthi	11KV	Nalgonda	11.20	13.40	02.20	E/L	11KV Line Jumper Cut	-
3		Reddygudem	Reddygudem	11KV	Suryapet	05.00	07.30	02.30	E/L	Insulator Failed	-
4		Gaddipally	Medaram	11KV	Huzurnagar	04.30	06.10	01.40	EL	11 KV LINE SNAPPED	-
5		Kistapuram	Tammaram	11KV	Huzurnagar	01.50	03.20	01.30	EL	11 KV JUMPER CUT	-
6		Raghunadapalem	Nakkagudem	11KV	Huzurnagar	06.15	08.30	02.15	EL	11 KV DISK FAILED	-
1	SDP	Erravally SS	KCR Feeder	11KV	Gajwel	07.50	11.45	03.55		Jumper Cut	-
2		Kokkonda SS	Singannaguda	11KV	Gajwel	06.00	10.00	04.00		Insulator Fail	-
1	RR N	Devarayamjal	Kottapet	11KV	Medchal	09.35	10.50	01.15		No Visible Fault	-