

Status Report on Breakdowns (Urban / Rural)

Urban

| S.No | Circle | No. of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------|-------------------------------|-------------|------------------------------------|-----------|-------------------------|-----------|-------------------------------------|-----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | | | | | | | | | |
| 6 | RR(N) | 54 | 550 | | 3 | | 3 | | 3 | | | |
| 7 | RR(E) | 168 | 403 | | 3 | | 3 | | 3 | | | |
| 8 | Hyd | 194 | 1044 | | 5 | | 5 | | 5 | | | |
| | Total | 606 | 3055 | 0 | 11 | 0 | 11 | 0 | 11 | 0 | 0 | |

Rural

| S.No | Circle | No. of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------------|--------------------------------|-------------|------------------------------------|-----------|-------------------------|-----------|-------------------------------------|-----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | | | | | | | | | |
| 2 | NLG | 144 | 988 | | 10 | | 10 | | 10 | | | |
| 3 | MDK | 107 | 933 | | | | | | | | | |
| 4 | SDPT | | | | 2 | | 2 | | 2 | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 0 | 12 | 0 | 12 | 0 | 12 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 0 | 23 | 0 | 23 | 0 | 23 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Date: 25.08.2019

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|--|---------------------------|
| 1 | NLG | Nakrekal | Kadaparthi | 11KV | Nalgonda | 08.00 | 10.30 | 02.30 | E/L | Tree branch fallen on 11KV line | - |
| 2 | | Nakrekal | Chandampally | 11KV | Nalgonda | 09.00 | 12.00 | 03.00 | E/L | Bird died on line | - |
| 3 | | Narketpally | M.Yedavelly | 11KV | Nalgonda | 10.45 | 13.20 | 02.35 | E/L | Jumper cut | - |
| 4 | | Kethepally | Korlapadu | 11KV | Nalgonda | 10.30 | 13.30 | 03.00 | E/L | Inasulator failed | - |
| 5 | | KN Konda | Balampally | 11KV | Miryalaguda | 13.00 | 15.40 | 02.40 | E/L | Jumper cut | - |
| 6 | | Dirsenapally | Machinapally | 11KV | Suryapet | 03.30 | 07.00 | 03.30 | E/L | Conductor snapped | - |
| 7 | | Munagala | Barakathgudem | 11KV | Huzurnagar | 06.30 | 09.30 | 03.00 | E/L | 11 KV LINE SNAPPED | - |
| 8 | | Gaddipally | Ponugodu | 11KV | Huzurnagar | 07.30 | 10.00 | 02.30 | E/L | 11 KV LINE SNAPPED | - |
| 9 | | Raghunadapalem | Nakkagudem | 11KV | Huzurnagar | 11.20 | 13.20 | 02.00 | E/L | 11 KV LINE SNAPPED | - |
| 10 | | Mothkur | Kondagadapa | 11KV | Bhongir | 05.00 | 08.30 | 03.30 | E/L | 11kv Disc Failed | - |
| 1 | SDPT | Guruvannapet | Guruvannapet | 11KV | Husnabad | 05.45 | 08.00 | 02.15 | | Line snapped same rectified | - |
| 2 | | Gurrallasofa | Ramaram | 11KV | Gajwel | 12.32 | 13.02 | 01.00 | | HT/LT | - |
| 1 | RR N | Jeedimetla-II | Ramreddy Nagar | 11KV | Jeedimetla | 09.20 | 10.40 | 01.20 | BD | 11kv line Jumper cut at kantta Rubbar Company,Ramreddy colony | - |
| 2 | | Kandlakoya | KV Reddy Nagar | 11KV | Medchal | 01.20 | 03.00 | 01.40 | BD | 11KV Pole damaged by Lorry at Nallala Bavi,KV Reddy Nagar | - |
| 3 | | Bowrampet | Bowrampet Village | 11KV | Jeedimetla | 16.50 | 17.50 | 01.00 | BD | Lorry dashed the 11kv line at Bowrampet Temple | - |
| 1 | RR E | P&T Colony | Chengicherla | 11KV | Keesara | 00.45 | 01.55 | 01.10 | | Tree branches fallen on 11kv line near Bal Reddy Function Hall | - |
| 2 | | P&T Colony | Budda Nagar | 11KV | Keesara | 02.45 | 04.45 | 02.00 | | 11KV Cable failed near Mallikarjuna Nagar Water Tank | - |
| 3 | | Nagaram | Bandlaguda | 11KV | Keesara | 23.50 | 00.48 | 00.58 | | 11KV Insulator failed near Singh Ground at Bandlaguda | - |
| 1 | HYD S | Devibagh | Bondalguda | 11KV | Charminar | 06.05 | 07.24 | 01.19 | EL | Bird fault on lines at Bahadurpura | - |
| 1 | HYD C | Erramanzil | Jaffer Ali Bagh | 11KV | Saifabad | 00.12 | 01.30 | 01.18 | EL | Cable fault at Barla Doddi Apts (2No. DTR's Kept Off) | - |
| 2 | | Langer House | Military Hospital | 11KV | Mehdipatanam | 01.40 | 02.50 | 01.10 | EL,OL-Bph | Tree branches fallen on lines at Military Hospital | - |
| 3 | | A.S.R Raju Nagar | GHMC Park | 11KV | Mehdipatanam | 05.10 | 06.10 | 01.00 | EL,OL | Cable fault at GHMC Park | - |
| 4 | | Ibrahimbagh | New Military | 11KV | Mehdipatanam | 15.43 | 17.00 | 01.17 | EL,OL | Tree branches fallen on lines at Golconda Cross Road | - |