

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	1	7	1	7	1	7			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>10</b>	<b>1</b>	<b>10</b>	<b>1</b>	<b>10</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 28.08.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Ramapuram	Mellacheruvu	33kv	Huzurnagar	14.30	17.30	03.00	EL/OL	Due to 33kv jumper cutted	Mellacheruvu	-

TSSPDCL - LMRC / Corporate office

Date: 28.08.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kodgal	Town	11kv	Jadcherla	05.30	08.38	03.08		HT/LT Near Lingampally village	-
1	NLG	Ravulapally	Gottimukkula gudem	11kv	Suryapeta	13.00	15.20	02.20	EL	Insulator failed	-
2		Dirsincherla	Dirsincherla	11kv	Huzurnagar	09.00	10.30	01.30	EL	Due to 11Kv jumper cutted	-
3		Timmareddy gudem	Ganapavaram	11kv	Huzurnagar	03.35	06.30	02.55	EL	Due to 11Kv line cutted	-
4		Siripuram	Vallapuram	11kv	Huzurnagar	09.40	10.50	01.10	EL	Due to 11Kv line cutted	-
5		Laxmidevigudem	Pamulapahad	11kv	Miryalaguda	10.45	14.50	04.05	EL	11KV Disc failed	-
6		Venkatapuram	Velupally	11kv	Bhongiri	08.30	11.00	02.30	EL	11 kv Insulator Failed Near Velupally Village	-
7		Narayanapur	Gudimalkapuram	11kv	Bhongiri	09.00	11.40	02.40	EL	Single Phase DTR Failed Near Mahamadabad Village	-
1	RR N	Subhash Nagar	Pragha Tools	11kv	Medchal	09.05	09.32	00.27	BD	11KV Brass Patti Cut & Replaced at BHEL R&D	-
1	RR E	Janapriya	Sadhan Vihar	11kv	Sainkपुरi	07.50	08.45	00.55		Tree branches fallen on 11Kv line at Netaji Nagar (LM Srinivas)	-