

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1	3	1	3	1	3			
	Total	606	3055	1	4	1	4	1	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	1	3	1	3	1			
2	NLG	144	988		1		1		1			
3	MDK	107	933									
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	3	3	3	3	3	0	0	
	Grand Total	1082	6468	4	7	4	7	4	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 01.12.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kalwakurthy	SLC Mills-1	33kv	Nagarkurnool	08.20	16.40	08.20	EL&OL	33KV Cable Damaged at 132KV SS Yard	SLC Mills-1	-
2		Balanagar	G.R Cable	33kv	Jadcherla	12.10	13.30	01.20	EL&OL	No visible fault	G.R Cable	-
3		Makthal	Narwa	33kv	Narayanapet	22.05	07.15 (02.12.19)	09.10	EL	Tree fallen on 33KV line	Narwa	Arranged from 33/11kv Narwa feeder at 00.00 hrs.
1	HYD N	132KV Gunrock	Chinna Thokatta	33kv	Bowenpally	00.00	00.06	00.06	OL-Rph	Old straight through Joint Kit failed near 132KV Gunrock SS	Chinna Thokatta	Loads transferred onto 132KV Gunrock SS via 33KV Bowenpally fdr

TSSPDCL - LMRC / Corporate office

Date: 01.12.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddarevelly	Chinnarevelly	11kv	Jadcherla	13.20	16.40	03.20		11Kv jumper Cut Near Chinnarevelly(Vi)	-
1	NLG	Mattampally	Errajelu	11kv	Huzurnagar	04.30	06.30	02.00	E/L	11Kv Line Snapped	-
1	SDPT	Dharmaram	Potharam	11kv	Husnabad	14.00	23.55	09.55		1-Ph ok,3 Ph BD	-
1	RR E	Ramanthapur	Chruch colony	11kv	Habsiguda	20.15	21.10	00.55		Alternet cable end kite fail at shardha nagar prinstan collage	-
1	HYD N	Zamistanpur	Sanjeevapuram	11KV	V	13.28	14.56	01.28	EL,OL-Rph	Jumper cut & Bird fault at Opp. S.R.Hospital	
2		Kalyan Nagar	Rahamath Nagar	11KV	X	13.35	14.56	01.21	EL,OL-Rph	Cable End Kit failed at Gurudwara (At 13:58Hrs partial fdr charged)	
1	HYD S	Kandikal Gate	Naseeb Nagar	11KV	III	14.10	15.20	01.10	EL,OL-R&Bph	AB Switch fault at Shoyab Hotel (At 14:45Hrs partial fdr charged)	