

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		8		8		8			
	Total	606	3055	0	11	0	11	0	11	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988	1	17	1	17	1	17			
3	MDK	107	933									
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	24	3	24	3	24	0	0	
	Grand Total	1082	6468	3	35	3	35	3	35	0	0	

TSSPDCL - LMRC / Corporate office

Date: 03.12.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Alampur	Shanthiagar-I	33KV	Gadwal	09.20	13.02	03.42	E/L	Tree follen on Shanthinagar Rampur X Road, Ramchandranagar	Shanthiagar-I	-
2		Mahabubnagar	Mahabubnagar	33KV	Town -III(Bhoothpur)	20.55	21.02	00.07	O/L & E/L	Heavy Sound Observed 132KV SS MBNR Yard back side	Mahabubnagar	Alternate supply arranged form 33KV SS Nawabpet
1	NLG	Wadapally	Janpahad	33KV	Huzurnagar	03.30	06.00	02.30		33 kv Disk Failed	Janpahad	-

TSSPDCL - LMRC / Corporate office

Date: 03.12.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Midjil	Kothur	11KV	Jadcherla	06.00	08.00	02.00		11KV Insulators Failed near Kothur	-
1	NLG	Kethepally	Inupamula	11KV	Nalgonda	07.00	09.20	02.20	EL	Insulator failed	-
2		Veliminedu	Pittampally	11KV	Nalgonda	09.30	11.20	01.50	EL	Jumper cut	-
3		V K Palem	Thungapadu	11KV	Miryalguda	09.15	11.40	02.25	EL	11KV Pin insulator damaged	-
4		Halia	Ibrahimpeta	11KV	Miryalguda	08.10	09.50	01.40	EL	11KV Jumper cut	-
5		Ravulapally	Ravulapally	11KV	Suryapet	08.30	11.00	02.30	EL	Insulator flashover	-
6		Garidepally	Town	11KV	Huzurnagar	05.00	07.45	02.45	EL	11 KV LINE SNAPPED	-
7		Nadigudem	Brundavanapuram	11KV	Huzurnagar	06.00	07.30	01.30	EL	11 KV LINE SNAPPED	-
8		Urlugonda	Tummagudem	11KV	Huzurnagar	07.00	08.45	01.45	EL	11 KV LINE SNAPPED	-
9		Paladugu	Duppally	11KV	Bhongir	07.30	08.30	01.00	EL	11 kv Disc Failed	-
10		Azeempet	Azeempet	11KV	Bhongir	05.00	09.10	04.10	EL	11 kv Insulator failed	-
11		Azeempet	Kanchanapally	11KV	Bhongir	06.00	09.10	03.10	EL	11 kv Insulator Failed	-
12		Athmakur	Koratikal	11KV	Bhongir	05.30	09.30	04.00	EL	11 kv Insulator Failed	-
13		Yennaram	Suraram	11KV	Choutuppal	09.55	10.35	00.40	EL	11 kv Insulator Failed	-
14		Thummalagudem	Bogaram	11KV	Choutuppal	08.00	11.03	03.03	EL	11 kv Disc Failed	-
15		Choutuppal	Thangedipally	11KV	Choutuppal	05.30	10.00	04.30	EL	11 kv Insulator Failed	-
16		Jublakpally	Kanumukula	11KV	Choutuppal	06.00	09.15	03.15	EL	11 kv Disc Failed	-
17		Voligonda	Nagaram	11KV	Choutuppal	12.02	15.22	03.20	EL	11 kv Insulator failed	-
1	SDP	Koheda	Theegalakuntapally	11KV	Husnabad	08.00	09.00	01.00		BD, Disc failure	-
2		Marmamula	Salakpoor	11KV	Husnabad	17.00	19.00	02.00		BD,conductor snapped	-
3		Nagapuri	Nagapuri	11KV	Husnabad	00.00	07.30	07.30		BD,Disc failure	-
4		Guruvannapet	Guruvannapet	11KV	Husnabad	00.00	06.30	06.30		BD,Due to rain	-
5		Guruvannapet	Tapaspally	11KV	Husnabad	00.00	06.30	06.30		BD,Due to rain	-
6		Rebarthy	Gagillapur Agl	11KV	Husnabad	00.00	13.30	13.30		BD,Tree fallen	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Jeedimetla SS I	Maheshwari	11KV	Jeedimetla	04.10	05.10	01.00	EI/OL	11 KV jumper cut at Sub station	-
1	RR E	Narapally	AP meet	11KV	Keesara	02.10	03.10	01.00		Insulaotr fail at Deviya nagar	-
2		Nagaram	Gandhi nagar	11KV	Keesara	01.50	03.30	01.40		No falt found & Jumper open at BMR enclave	-
1	HYD N	Srinagar Colony	Kamma Sangam	11KV	X	13.57	16.31	02.34	OL-R,Y&Bph	RMU flash over at Filsh Land Hotel	Arranged B/F on 11KV Nagarjuna Nagar feeder
1	HYD S	C.R.P.F	Salala	11KV	III	00.00	02.15	02.15	EL	Post type Insulator flash over at Salala	-
2		Hyderguda	W.S.Colony	11KV	III	00.05	01.35	01.30	EL	Pin Insulator flash over at Ram Bagh	-
3		Kulsumpura	Ambedkar Nagar	11KV	IX	00.08	05.38	05.30	EL	Cable fault	Added partial loads on 11KV Gandi Hanuman fdr at 02:18Hrs & remaining loads added on 11KV Tallagadda OH feeder
4		Seetharambagh	Dattatreya Nagar UG Cable	11KV	IX	01.30	02.45	01.15	EL	Pin Insulator flash over at Dattatreya Colony	-
5		Asmangadh	P&T Colony	11KV	VIII	03.43	04.46	01.03	EL,OL-Yph	DTR fault at Gayatri Apts	-
6		Asmangadh	Shiva Ganga	11KV	VIII	05.44	07.05	01.21	EL,OL-Bph	No Visible Fault	-
1	HYD C	Chilkaiguda	Golconda X Road	11KV	II	00.30	01.56	01.26	EL	Kite Sticks on lines at Krishna Colony Masjid	-