

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403									
8	Hyd	194	1044	1								
	Total	606	3055	1	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	4	0	4	0	4	0	0	
	Grand Total	1082	6468	1	7	0	7	0	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 05.12.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD N	132KV Gunrock	Airport	33KV	Nehru Ngr	12.55	12.57	00.02	OL-Rph	Yph Disc Insulator flash over near Jupiter Colony	132KV Gunrock	Loads normalised onto 132KV Patigadda SS via 33KV Airport fdr

TSSPDCL - LMRC / Corporate office

Date: 05.12.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Midjil	Boinpally	11KV	Jadcherla	07.00	09.40	02.40		11 KV jumper cut near boinpally thanda.	-
1	NLG	Annaram	Sangem	11KV	Suryapet	05.30	08.00	02.30	E/L	11Kv Insulator failed	-
2		Mattampally	Allipuram	11KV	Huzurnagar	06.00	07.45	01.45	E/L	11Kv Insulator failed	-
3		Bibinagar	Jampally	11KV	Bhongir	06.30	09.05	02.35	EL	11kv Insulator Failed at Srinivas well Near Jampally (V)	-
1	RR N	Aliabad	Majeedpur	11KV	Medchal	00.10	01.25	01.15	BD	11KV Line AB Switch Opened at Sangeeth Function Hall	-
2		Aliabad	LGM Pet	11KV	Medchal	06.40	08.05	01.25	BD	Tree Branches Fallen on 11KV Line at Kashawada	-
3		Athiwelly	IDA	11KV	Medchal	12.25	16.25	04.00	BD	11KV Pole damaged by Car at Yellampet Chowrasta	-