

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT			2		2		2				
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	3	2	3	2	3	0	0	
	Grand Total	1082	6468	2	5	2	5	2	5	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.12.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Palamakula	Baddipadiga	33KV	Siddipet	21:45	23:45	2:00		Insulator failed	Baddipadiga	No
2		Doultabad	Raipole	33KV	Gajwel	10.17	11.32	01.15		Pin insulator damaged	Raipole	No

TSSPDCL - LMRC / Corporate office

Date: 07.12.19

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kothamolgera	Kothamolgera	11KV	Jadcherla	07.15	14.35	07.20		DTR failure at Kappeta (V)	No
1	NLG	Pendlipakala	Penlipakala	11KV	Devarakonda	12:40	13:10	0:30	EL	11KV Line cut	No
2		Kasarabadha	T K Pahad	11KV	Suryapet	14.10	15.20	01.10	EL	Insulator failed	No
1	RR N	Medchal	IDA-I	11KV	Medchal	0:17	1:15	0:58		11KV Conductor snapped and replaced at Bus Body company	No
1	HYD N	Bowenpally	Jaya Nagar	11KV	VI	22.20	00.30	02.10	EL,OL-Yph	Conductor snapped due to Milk van hitting Pole at Nakshatra Bar	No