

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		11		11		11			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	11	0	11	0	11	0	0	
	Grand Total	1082	6468	0	16	0	16	0	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 12.12.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Koppole(K)	Bheemaram	11KV	Nalgonda	02.30	07.00	04.30	E/L	HT/LT line melting	-
2		Guntipally	Yerrabelly	11KV	Miryalaguda	04.00	06.30	02.30	E/L	11KV PIN INSULATOR FAILED NEAR VILLAGE	-
3		A D Pally	Veerlapalem	11KV	Miryalaguda	06.05	08.20	02.15	E/L	11KV PIN INSULATOR FAILED NEAR VILLAGE	-
4		Neelaigudam	Anjanpally	11KV	Miryalaguda	14.00	16.00	02.00	E/L	11 KV CONDUCTOR SNAPPED	-
5		Chandampeta	Chitryala	11KV	Devarakonda	09.10	11.20	02.10	E/L	11 KV line Cut	-
6		Angadipeta	P.A.Pally rural	11KV	Devarakonda	06.55	11.48	04.53	E/L	11 KV Conductor Snpped	-
7		Chidella	Mukundapuram	11KV	Suryapet	12.50	15.30	02.40	E/L	Insuletor Failed	-
8		Urlugonda	Tummagudem	11KV	Huzurnagar	04.00	06.30	02.30	E/L	11 KV LINE SNAPPED	-
9		Munagala	Turkagudem-1	11KV	Huzurnagar	14.35	16.05	01.30	E/L	11 KV LINE SNAPPED	-
10		Mothkur	Aregudem	11KV	Bhongiri	12.30	15.05	02.35	E/L	11kv Pin Insulator Failed & Line snapped near Sub _ Station	-
11		Ishkilla	Kakkireni	11KV	Choutuppal	11.30	15.30	04.00	E/L	11KV Pin Insulator Failed near Kakkireni Village	-
1	RR N	Aliabad	Bommarajpet	11KV	Medchal	07.15	08.50	01.35	BD	11KV AB Switch Opened at Venkateshwara Temple, Aliabad (No Fault)	-
1	RR E	NGRI	HBG	11KV	Habsiguda	10.05	11.10	01.05		Line AB swicth fail at Genpact opp	-
2		Uppal Bhagath	Saraswathi nagar	11KV	Habsiguda	09.55	11.00	01.05		Pin insulaotr fail at Shilpa ramam	-
3		Keesara	Ankireddypally	11KV	Keesara	06.10	07.00	00.50		End kite fail at Peddama chervu	-
1	HYD C	A.S.R.Raju Nagar	Golla Basthi	11KV	Medhipatanam	14.05	15.22	01.17	EL,OL	Cable fault at Hanuman Temple (1No. DTR kept off)	-