

Status Report on Breakdowns (Urban / Rural)**Urban**

| S.No | Circle | No.of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------|------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | | 1 | | 1 | | 1 | | | |
| 6 | RR(N) | 54 | 550 | | | | | | | | | |
| 7 | RR(E) | 168 | 403 | | | | | | | | | |
| 8 | Hyd | 194 | 1044 | | 1 | | 1 | | 1 | | | |
| | Total | 606 | 3055 | 0 | 2 | 0 | 2 | 0 | 2 | 0 | 0 | |

Rural

| S.No | Circle | No.of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------------|-------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | 1 | | 1 | | 1 | | | | |
| 2 | NLG | 144 | 988 | | 4 | | 4 | | 4 | | | |
| 3 | MDK | 107 | 933 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 1 | 4 | 1 | 4 | 1 | 4 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 1 | 6 | 1 | 6 | 1 | 6 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Date: 18.12.2019

| S.No | Circle | Name of 132/33KV SS | Name of 33 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Sub Stations Effected | Alternate Supply Arranged |
|------|--------|---------------------|----------------------|------|----------------------|-------|-------|----------|------------------|-----------------------------------|-----------------------|---|
| 1 | MBNR | Wanaparthi | Kodair | 33KV | Wanaparthi | 00.50 | 09.33 | 08.43 | E/L & O/L | Line Patrolling ,No Visible fault | Kodair | Alternate Supply Arranged from 220KV Singotam |

TSSPDCL - LMRC / Corporate office

Date: 18.12.2019

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|--|---------------------------|
| 1 | NLG | Repala | Repala agl | 11KV | Huzurnagar | 04.00 | 07.00 | 03.00 | EL | Due to 11Kv line snapped | - |
| 2 | | Eudloor | Parada | 11KV | Nalgonda | 08.00 | 10.30 | 02.30 | EL | 11KV Line Jumpet Cut | - |
| 3 | | Dugunivelly | Parada | 11KV | Nalgonda | 04.00 | 07.00 | 03.00 | EL | 11KV Line Jumpet Cut | - |
| 4 | | Vemulakonda | Chitthapuram | 11KV | Choutuppal | 05.00 | 08.00 | 03.00 | EL | 11 kv Line Snapped Near Chittapuram Village | - |
| 1 | RR S | Hafeezpet | New Hafeezpet | 11KV | Gachbowili | 06.40 | 08.00 | 01.20 | OL | No visible fault | - |
| 1 | HYD N | Road No.13 | Road No.1 | 11KV | X | 21.41 | 23.09 | 01.28 | EL,OL | Cat fallen in RMU at Road No.1 & Jumper cut at Bajaj Show Room | - |