

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988	2	5	2	5	2	5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>4</b>	<b>5</b>	<b>4</b>	<b>5</b>	<b>4</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>5</b>	<b>6</b>	<b>5</b>	<b>6</b>	<b>5</b>	<b>6</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 20.12.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kodangal	Pedda Nandigama	33KV	Vikarabad	08.05	13.15	05.10		LV's Pull Out & Break Down Due to Flash Over Disc Damaged at Pyalamaddi(V)		-
2		220/33KV Singotam	Kollapur	33KV	Nagarkurnool	13.05	15.08	02.03	E/L&O/L	Jumper Cut at Singotam back side		-
1	NLG	Shaligouraram	Nakrekal	33KV	Nalgonda	14.05	17.00	02.55	E/L	33KV Arvapally line cut at 132KV SS		-
2		Shaligouraram	Akaram	33KV	Nalgonda	14.05	17.00	02.55	E/L	33KV Arvapally line cut at 132KV SS		-
1	RR N	132KV Chintal	33KV Subhash Nagar	33KV	Medchal	Medchal	14.08	15.35	0.0604166667	33KV Pin Insulator damaged near Subhash Nagar SS		-

TSSPDCL - LMRC / Corporate office

Date: 20.12.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	GT Giri	GT Giri	11KV	Suryapet	11.40	13.10	01.30	E/L	Insulato failed	-
2		Palakeedu	Palakeedu	11KV	Huzurnagar	10.25	12.10	01.45	E/L	11 KV LINE SNAPPED	-
3		Huzurnagar	Singaram	11KV	Huzurnagar	10.05	11.30	01.25	E/L	11 KV LINE SNAPPED	-
4		Athmakur	Koratikal	11KV	Bhongir	11.00	14.00	03.00	E/L	11kv Insulator Failed	-
5		Choutuppal	Jublakpally	11KV	Choutuppal	10.00	12.00	02.00	E/L	11kv Insulator Failed	-
1	HYD S	Gunj	Hari Hara Kshetra	11KV	Asmangadh	01.07	02.35	01.28	EL,OL-Rph	AB Switch fault & Jumper cut at Reliance Digital	-