

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	3		3		3				
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	3	3	3	3	3	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		1		1		1			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	1	1	1	1	1	0	0	
	Grand Total	1082	6468	4	4	4	4	4	4	0	0	

TSSPDCL - LMRC / Corporate office

Date: 27.12.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Chinchode	33KV	Shadnagar	15.45	17.05	01.20	E/L	No Visbule Fault	Balanagar	No
1	RR N	132KV Malkaram	33KV Ratnalayam	33KV	Medchal	13.55	15.50	01.55	BD	Tripped on EL Indication(No Fault)		-
2		132KV Malkaram	33KV Shameerpet	33KV	Medchal	13.55	17.15	03.20	BD	Tripped on EL & OL Indication(No Fault)		-
3		132KV Medchal	33KV Devarayamjal	33KV	Medchal	02.07	08.57	06.50	BD	Bus Isolator to C. B Jumper Flash out in SS		-

TSSPDCL - LMRC / Corporate office

Date: 27.12.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Tekumatla	Yendipalally	11KV	Suryapet	13.15	14.40	01.25	E/L	Conductor Snapped	-
1	RR S	IIIT	IVRCL	11KV	Gachibowli	10.20	11.40	01.20		Bird Fallen on the 11kv line at Aleem college backside.	-
1	HYD S	Falaknuma	Aliyabad	11KV	Charminar	12.10	13.35	01.25	EL,OL	No Visible Fault	
1	HYD C	Nizam College	Brand Factory	11KV	Saifabad	10.45	12.00	01.15	EL	Tree branches fallen on lines at Street No.7, Himayath Nagar	