

Status Report on Breakdowns (Urban / Rural)**Urban**

| S.No | Circle | No.of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------|------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | | | | | | | | | |
| 6 | RR(N) | 54 | 550 | | 1 | | 1 | | 1 | | | |
| 7 | RR(E) | 168 | 403 | | | | | | | | | |
| 8 | Hyd | 194 | 1044 | | 1 | | 1 | | 1 | | | |
| | Total | 606 | 3055 | 0 | 2 | 0 | 2 | 0 | 2 | 0 | 0 | |

Rural

| S.No | Circle | No.of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------------|-------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | 1 | 1 | 1 | 1 | 1 | 1 | | | |
| 2 | NLG | 144 | 988 | | 2 | | 2 | | 2 | | | |
| 3 | MDK | 107 | 933 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 1 | 3 | 1 | 3 | 1 | 3 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 1 | 5 | 1 | 5 | 1 | 5 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Date: 28.12.2019

| S.No | Circle | Name of 132/33KV SS | Name of 33 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Sub Stations Effected | Alternate Supply Arranged |
|------|--------|---------------------|----------------------|------|----------------------|-------|-------|----------|------------------|------------------------------------|-----------------------|---------------------------|
| 1 | MBNR | Kothur | Natco Pharma | 33kv | Shadnagar | 01.40 | 14.45 | 13.05 | O/L | Replacement of Cable Kit at Kothur | Natco Pharma | - |

TSSPDCL - LMRC / Corporate office

Date: 28.12.2019

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|------------------------------------|
| 1 | MBNR | Marikal | Malkapur | 11kv | Jadcherla | 11.50 | 15.00 | 03.10 | | Tree Follen On The 11KV Line Near Malkapur (Vi) | - |
| 1 | NLG | Mattampally | Errajelu | 11kv | Huzurnagar | 00.40 | 06.35 | 05.55 | EL | 11 KV LINE SNAPPED | - |
| 2 | | Alair | Ikkurthy | 11kv | Bhongiri | 07.20 | 09.40 | 02.20 | OL | 11 kv Pin insulator failed & 11 KV Line snapped Near Dilwarpur village. | - |
| 1 | RR N | Kompally | Dholari Dhani | 11kv | Medchal | 19.15 | 20.45 | 01.30 | | 11KV Cable Kit Failed at Harshita Hospital,Kompally | - |
| 1 | HYD S | Salarjung | Salarjung Museum | 11kv | Charminar | 07.05 | 09.03 | 01.58 | EL,OL | Cable fault, 6No. Jumpers cut & 4No. HG fuses burntout at SS | Arranged B/F on 11KV Darushifa fdr |