

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1	4	1	4	1	4			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		7		7		7			
3	MDK	107	933		3		3		3			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>17</b>	<b>3</b>	<b>17</b>	<b>3</b>	<b>17</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 03.07.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Peddmandadi	33KV	Wanaparthy	15.40	18.28	02.48	E/L	R Phase jumper Cut and re binding Work at SS	Peddmandadi	-
2		Kothur	Natco Chemical	33KV	Shadnagar	02.20	10.40	08.20	E/L	Due to Cable kit failed Near Vinayaka Company	Natco Chemical	-
1	RR N	132KV LGM Pet	33KV MN Park	33KV	Medchal	04.50	08.00	03.10	BD	No visible fault	33KV MN Park	-

## TSSPDCL - LMRC / Corporate office

Date: 03.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thirumalagiri	Thatipamula	11KV	Suryapet	11.45	13.30	01.45	E/L	Insulato failed	-
2		Alingapuram	Raghavapuram	11KV	Huzurnagar	12.30	15.20	02.50	EL	Due to 11Kv line snapped	-
3		Kandibanda	Yerraram	11KV	Huzurnagar	09.14	10.55	01.41	OL	Due to 11Kv line snapped	-
4		Kandibanda	Gandi nagar thanda	11KV	Huzurnagar	12.03	14.32	02.29	EL/OL	Due to 11Kv jumper cutted	-
5		Gudapur	Munugode Town	11KV	Nalgonda	12.30	14.45	02.15	EL	11 KV Line Jumper Cut	-
6		Rayanaguda	J.R.Gude	11KV	Nalgonda	11.05	16.00	04.55	EL	11 KV Insulator Failure	-
7		Kethepally	Korlapahad	11KV	Nalgonda	14.30	17.30	03.00	EL	11 KV Line Jumper Cut	-
1	MDK	Inole	Sathyasai WW	11KV	Patancheru	14.00	14.40	00.40		BD due to Jumper cut	-
2		Gummadidala	Bell Remedies	11KV	Patancheru	13.25	18.35	05.10		BD due to Conductor snapped	-
3		Dundigal	Annaram	11KV	Patancheru	00.00	13.15	13.15		BD due to Jumper cut	-
1	RR S	Kattedan-II	Ravi foods	11KV	RJNR	14.55	16.20	01.25	B/D	11kv Pin insulator Failed at Ruby Foods	-
1	RR N	Suraram	Sai Baba Nagar	11KV	Jeedimetla	11.50	13.50	02.00	BD	11kv line PinInsulater Failure at Suresh Reddy House,Mythala Basthi	-
2		UMCC	Mahadevpuram	11KV	Medchal	06.05	07.00	00.55	BD	11KV Disc failed at Mahadevpuram	-
3		Kandlakoya	Kandlakoya	11KV	Medchal	14.00	15.25	01.25	BD	11KV Jumper Cut & Replaced at Saigeetha Ashramam Road	-
4		Kandlakoya	KV Reddy Nagar	11KV	Medchal	17.32	18.10	00.38	BD	11KV Cable failed at Redimix Company	-
1	RR E	Vinayak Nagar	Old Safilguda	11KV	Sainikpuri	16.24	16.54	00.30		Lezard fallen on 11Kv line at Sairam Enclave Deendayal Nagar (AE/OP)	-
2		AS Rao Nagar	Gokul Nagar	11KV	Sainikpuri	20.05	21.05	01.00		Tree fallen on 11Kv line at AS Rao Nagar Pathanjali Shop (LM Srinivas)	-