

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	6	1	6	1	6			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	3	2	2	2	2	2			
	Total	606	3055	4	9	3	9	3	9	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		3		3				
2	NLG	144	988		19		19		19			
3	MDK	107	933		4		4		4			
4	SDPT			3	2	3	2	3	2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	25	6	25	6	25	0	0	
	Grand Total	1082	6468	10	34	9	34	9	34	0	0	

TSSPDCL - LMRC / Corporate office

Date: 05.07.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kalwakurthy	Rachoor	33KV	Nagarkurnool	12.43	15.30	02.47	E/L	Pin Baining replaced at CBM Collage back side	Rachoor	-
2		Chinnamarror	Jetprole	33KV	Wanaparthi	20.50	08.55	12.05	O/L	Tripped on O/L Due to Breker Coil Burnt	Jetprole	-
3		Sri Rangapur	Utharaspally	33KV	Shadnagar	16.32	17.40	01.08	O/L	No Visbile Fault Due to Rain	Utharaspally	-
1	SDP	Habsipur	Khajipur	33KV	Siddipet	16.25	17.15	00.50		Tree branches fall on the line	Khajipur	-
2		Chandlapur	Kammarlapally	33KV	Siddipet	17.10	18.15	01.05		Insulator failed	Kammarlapally	-
3		Shanigaram	Bejjanki	33KV	Husnabad	17.15	19.35	02.20		Insulator failed	Bejjanki	-
1	RR N	132KV Medchal	33KV Medchal-I	33KV	Medchal	16.18	18.23	02.05		33KV Jumper Cut and replaced at 132KV Medchal SS	33KV Medchal-I	-
1	HYD N	132KV J' Hills	Sundew (HT Service)	33KV	Kalyan Ngr	13.00	17.45	04.45	All Indication	Cable Punctured by Water Works near Express TV Office	Sundew (HT Service)	-
1	HYD S	132KV Imlibun	Durga Nagar (Idle)	33KV	Chilalguda	06.30	12.05	00.00	EL	33KV Cable Jumper cut at 4 Pole Structure, Moosi River	Durga Nagar (Idle)	-
2		220KV Shivrapally	Ch' Baradari (Idle)	33KV	Malakpet	13.45			EL,OL-Yph		Ch' Baradari (Idle)	-

TSSPDCL - LMRC / Corporate office

Date: 05.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Paladugu	Duppally	11KV	Bhongir	04.00	09.55	04.55	EL	11kv Pin Insulator Failed near Paladugu (V)	-
2		Choutuppal	Chinna konduru	11KV	Choutuppal	02.00	07.00	05.00	EL/OL	11kv Pole Dammged near Jublakpally (V)	-
3		Vemulakonda	Vemulakonda	11KV	Choutuppal	03.00	05.40	02.40	EL/OL	11kv Line snpped near Vemulakonda (V)	-
4		Aroor	Gurunathpally	11KV	Choutuppal	04.00	06.00	02.00	EL	11kv Insulator Gurnathpally (V)3phase B/d	-
5		Aroor	Appa Reddy Pally	11KV	Choutuppal	22.00	15.00	17.00	EL/OL	Appa Reddy Pally Feeder breaker Fault Tag on Gurunath pally Feeder at 15:00 to Single phase ok 3phase Fault	-
6		Janpahad	Janpahad	11KV	Huzurnagar	09.25	10.35	01.10	EL	11Kv jumper cut	-
7		Mattapally	Sulthanpuram	11KV	Huzurnagar	12.55	14.25	01.30	EL	11kv line cut	-
8		Thogarrai	GudiBanda	11KV	Huzurnagar	15.00	16.30	01.30	EL	11Kv jumper cut	-
9		Munagala	Kokkireni-II	11KV	Huzurnagar	04.45	08.00	03.15	EL	11Kv jumper cut & Ab Switch Open	-
10		Mamidala	Aregudem	11KV	Nalgonda	17.00	18.55	01.55	EL	HT/LT Line Melt	-
11		Rajupeta	B.V.Gudem	11KV	Nalgonda	18.20	19.10	00.50	EL	Tree Fallen on the 11 KV Line	-
12		Narsingbatla	Kuthurugudem	11KV	Nalgonda	18.00	19.15	01.15	EL	Copper Patti Damaged	-
13		Eduloor	Parada	11KV	Nalgonda	17.10	18.50	01.40	EL	Tree Fallen on the 11 KV Line	-
14		Eduloor	Munukuntla	11KV	Nalgonda	17.10	19.00	01.50	EL	11 KV Jumper Cut	-
15		Rayanguda	Industrial	11KV	Nalgonda	17.15	18.00	00.45	EL	Tree Fallen on the 11 KV Line	-
16		Madgulapally	Kukkadam	11KV	Nalgonda	10.15	12.20	02.05	EL	11 KV Jumper Cut	-
17		Aragaddagudem	Thatikal	11KV	Nalgonda	07.10	10.43	03.33	EL	11 KV Jumper Cut	-
18		Rayanguda	KK Pally	11KV	Nalgonda	17.15	19.20	02.05	EL	11 KV Jumper Cut	-
19		Velugupally	Pasnoor	11KV	Suryapet	12.40	15.00	02.20	EL	Insulator failed	-
1	MDK	Sangareddy - II	Filterbed	11KV	Sangareddy	15.40	16.20	00.40		B/D Due to phase to phase	-
2		Patancheru Town	High power	11KV	Patancheru	18.00	19.00	01.00		B/D Due to Insulator Failure	-
3		Bollaram - I	Town-I	11KV	Patancheru	16.20	17.14	00.54		B/D Due to Jumpercut	-
4		Bollaram - I	Soubhagya	11KV	Patancheru	18.25	19.00	00.45		B/D Due to Jumpercut	-
1	SDP	DHOOLMITTA	ARJUNPATLA	11KV	HUSNABAD	17.35	09.10	15.35		Conductor snapped	-
2		THOTAPALLY	THOTAPALLY R	11KV	HUSNABAD	09.50	12.10	02.20		B/D Due to Line snapped	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Jeedimetla-I	Virchow	11KV	Jeedimetla	18.30	20.30	02.00	EL/OL	11kv AB cable failure At Virchow	-
2		Bowrampet	CoCo-Cola	11KV	Jeedimetla	15.03	16.50	01.47	OL	11kv Jumnper Cut Near Royal Acture bowrampet	-
3		Dp Pally	Bowrampet	11KV	Jeedimetla	16.05	17.10	01.05	OL	Due To rain	-
4		Devarayamjal	DMC	11KV	Medchal	18.25	19.20	00.55		11KV Pin Insulator failed at Devaramjal Cheruvu	-
5		Subhash Nagar	Gayatri Nagar	11KV	Medchal	13.18	13.52	00.34		Street Lights Line Touched on the 11KV Line at Gayatri Nagar	-
6		Subhash Nagar	Pragha Tools	11KV	Medchal	13.19	14.09	00.50		Tree fallen on the 11KV Line at Dandamudi Layout	-
1	RR E	Aushapur	Edulabad AGL	11KV	Keesara	10.40	13.40	03.00		11KV line cut at Chandupatlaguda	-
1	HYD N	Hakimpet	Risala Bazar	11KV	C-VI	18.25	19.55	01.30	All Indication	2No. Pin Insulators flash over at Sapthagiri Towers	-----
1	HYD S	C.R.P.F.	Anwar Mirchi	11KV	III	23.00	00.08	01.08	EL	Cable fault	Arranged B/F on 11KV Omer Colony feeder