

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403									
8	Hyd	194	1044	1	1	1	1	1	1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>3</b>	<b>2</b>	<b>3</b>	<b>2</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		21		21		21			
3	MDK	107	933	2	1	2	1	2	1			
4	SDPT			1	8	1	8	1	8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>31</b>	<b>3</b>	<b>31</b>	<b>3</b>	<b>31</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>5</b>	<b>34</b>	<b>5</b>	<b>34</b>	<b>5</b>	<b>34</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 06.07.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Kandi	SKOL	33KV	Sangareddy	08.25	11.25	03.00		BD due to Tree fallen on line	Kandi	No
2		Sadasivpet	Kondapur	33KV	Sangareddy	17.20	19.27	02.07		BD due to Jumper cut	Sadasivpet	No
1	SDPT	Palamakula	Narmetta	33KV	Siddipet	11.27	14.12	02.45		BD due to Tree fallen on line	Palamakula	No
1	RR N	132KV Medchal	33KV Petbasheerbagh	33KV	Medchal	14.08	16.20	02.12	BD	No Fault	132KV Medchal	No
1	HYD N	132KV Balkampet	H.P.S	33KV	Allwyn	00.34	00.38	00.04	OL-Yph,	I/C side End Kit failed in 33KV H.P.S	132KV Balkampet	Loads transferred onto 132KV Erragadda - H.P.S

## TSSPDCL - LMRC / Corporate office

Date: 06.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gangapur	Alwanpally	11KV	Jadcherla	12.55	14.30	01.35		11KV Wire Cut near Alwanpally	-
1	NLG	Pagidimarry	Dorepally	11KV	Nalgonda	06.00	09.00	03.00	E/L	11KV line cut at Sub-station back side	-
2		Appajipeta	Anneparthi	11KV	Nalgonda	04.20	14.50	10.30	E/L	11KV Insulator failed	-
3		Appajipeta	Appajipeta	11KV	Nalgonda	11.05	13.00	01.55	E/L	11KV Jumper cut	-
4		Nakrekal	Nomula	11KV	Nalgonda	06.20	09.30	03.10	E/L	11KV Jumper cut	-
5		Urumadla	Elikatte	11KV	Nalgonda	04.20	09.45	05.25	E/L	11KV line cut at Vembai(V)	-
6		Arlagaddagudem	N.R.Gudem	11KV	Nalgonda	09.30	11.00	01.30	E/L	11KV Insulator failed	-
7		Gattuppal	Lachammagudem	11KV	Nalgonda	05.35	10.30	04.55	E/L	11KV line cut at Lachammagudem village	-
8		Madgulapally	Kukkadam	11KV	Nalgonda	01.15	11.30	10.15	E/L	11KV Jumper cut	-
9		Rayanguda	Kankanapally	11KV	Nalgonda	08.10	13.20	05.10	E/L	Phase to phase	-
10		Agamothkur	Agamothkur	11KV	Miryalguda	09.14	18.50	09.36	E/L	Jumper Cut	-
11		Damarcherla	T.V.gudem	11KV	Miryalguda	10.40	16.20	05.40	E/L	Tree branches fallen on the 11Kv line near SS	-
12		Damarcherla	Damarcherla Town	11KV	Miryalguda	11.00	12.00	01.00	E/L	11KV Conductor melted at Saidurga Nagar	-
13		Damarcherla	Bothalapalem	11KV	Miryalguda	07.00	08.40	01.40	E/L	11KV Jumper cut near village	-
14		B.B.Gudem	Abangapuram	11KV	Miryalguda	10.15	14.15	04.00	E/L	Tree branches fallen on the 11Kv line near Village	-
15		Yerkaram	Dasthanda	11KV	Suryapet	14.00	16.30	02.30	E/L	Insulator failed	-
16		Amararam	Lingagiri	11KV	Huzurnagar	03.00	07.00	04.00	EL	11 KV LINE SNAPPED	-
17		Kodad Town	Komarabanda	11KV	Huzurnagar	15.05	16.10	01.05	EL	Control AB Open	-
18		Kodad Town	Tammara	11KV	Huzurnagar	15.05	16.10	01.05	EL	Control AB Open	-
19		Munagala	Barakathgudem	11KV	Huzurnagar	10.35	13.25	02.50	EL	11 KV LINE SNAPPED	-
20		Nelamarry	Nelamarry	11KV	Huzurnagar	09.30	12.00	02.30	EL	11 KV Jumper cut	-
21		Mothkur	Mothkur Rural	11KV	Bhongiri	10.50	13.50	03.00	EL	11 kv Line Snapped at Peddamma temple Backside Near Mothkur Village	-
1	MDK	Pati	Shalimar	11KV	Patancheru	16.00	17.30	01.30		BD due to Insulator failed	-
1	SDPT	Nagapuri	Nagapuri	11KV	Husnabad	09.20	11.15	01.55		Disc failure	-
2		Mustyal	Gadithota	11KV	Husnabad	11.40	14.30	02.50		Due to gale & wind	-
3		Akkannapet	Gollakunta	11KV	Husnabad	09.15	14.15	05.00		DTR failure	-
4		Thotapally	Thotapally	11KV	Husnabad	11.00	14.00	03.00		Conductor snapped	-
5		Dhoolmitta	Arjunpatla	11KV	Husnabad	00.00	10.30	10.30		Insulator failure	-
6		Dhoolmitta	Arjunpatla	11KV	Husnabad	11.20	16.30	05.10		Insulator failure	-
7		Rebarthy	Gagillapur Agl	11KV	Husnabad	13.10	17.10	04.00		Jumper cut	-
8		Thotapally	Veerapur	11KV	Husnabad	00.00	05.10	05.10		3 Ph BD,1 Ph ok	-
1	RR S	Chanda Nagar	Market	11KV	Gachibowli	07.25	09.00	01.35		11kv Conductor snapped at Market	-
1	RR N	Jeedimetla-I	Subashanagar	11KV	Jeedimetla	10.00	12.20	02.20	BD	11kiv Out Going AB cable Failur In Sub station	-
1	HYD N	Bansilalpet	Hyder Basti	11KV	Sec-Bad	09.44	11.02	01.18	EL	Cable fault at Botany School	-