

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		6		6		6			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1	2	1	2	1	2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>9</b>	<b>1</b>	<b>9</b>	<b>1</b>	<b>9</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	1	9	1	9	1	9			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT			1	18	1	11	1	11		7	<b>7 Nos. 11KV Still</b>
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>29</b>	<b>3</b>	<b>22</b>	<b>3</b>	<b>22</b>	<b>0</b>	<b>7</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>38</b>	<b>4</b>	<b>31</b>	<b>4</b>	<b>31</b>	<b>0</b>	<b>7</b>	

TSSPDCL - LMRC / Corporate office

Date: 07.07.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Madgulapally	Laxmidevigudem	33KV	Miryalaguda	11:55	12:50	00.55	E/L	Tree branches fallen at Molkapatnam	Laxmidevigudem	No
1	MDK	Kandi	HFC-I	33KV	Sangareddy	1:10	7:00	05.50		Insulator failed	HFC-I	No
1	SDPT	Shanigaram	Bejjanki	33KV	Husnabad	20:52	21:25	00.33		Poles broken	Bejjanki	Alternate supply arranged from Begumpet feeder
1	HYD N	132KV Balkampet	Kundan Bagh	33KV	Allwyn	02.26	02.31	00.05	OL	Cable fault	Kundan Bagh	Loads transferred onto 132KV Erragadda SS

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddarevelly	Chinnarevelly	11KV	Jadcherla	10.58	13.30	02.32		Bird Died on The 11KV line near Yerrakunta Cheruvu side	No
1	NLG	Pedaveedu	Pedaveedu	11KV	Huzurnagar	13:00	16:00	3:00	EL	11KV Line snapped	No
2		Munagala	Tadvai	11KV	Huzurnagar	08.15	11.20	03.05	EL	11KV Insulator failed	No
3		Kodad Town	Thammara	11KV	Huzurnagar	06.30	09.30	03.00	OL	11KV Jumper cut	No
4		Gondriyala	Gondriyala 02	11KV	Huzurnagar	08.20	11.20	03.00	EL	11KV Jumper cut	No
5		Indugula	Kothagudem	11KV	Nalgonda	12.00	16.30	04.30	EL	11KV Jumper cut	No
6		Aitipamula	Rasoolgudem	11KV	Nalgonda	10.35	16.00	05.25	EL	11KV Jumper cut	No
7		Eduloor	Naragudem	11KV	Nalgonda	07.20	09.00	01.40	EL	11KV Jumper cut	No
8		Laxmidavigudem	Ravulapenta	11KV	Miryalaguda	07.55	08.50	00.55	EL	11KV Jumper cut at ravulapenta	No
9		Maryala	Chowderpally	11KV	Bhongiri	7:30	9:45	2:15	OL	11KV Line Snapped & 11 kv Insulator failed near Chowderpally Village	No
1	MDK	Pati	Shalimar	11KV	Patancheru	9:30	11:10	1:40		Tree branches fallen on the line	No
1	SDPT	Potharam	Keshavapur	11KV	Husnabad	11:20	19:00	7:40		Insulator failure	
2		Pandilla	Potlapally	11KV	Husnabad	18:20	20:20	2:00		Heavy gale and wind	
3		Gouravelli	Gudatipally	11KV	Husnabad	11:20	14:10	2:50		Line cut	
4		Thotapally	Thotapally town	11KV	Husnabad	19:10				Break down	
5		Thotapally	Dacharam & veerapur	11KV	Husnabad	19:50				Heavy gale and wind (3PH)	
6		Samudrala	Laxmipur	11KV	Husnabad	5:30	12:30	7:00		Pole damaged	
7		Koheda	Kurella	11KV	Husnabad	19:15				Break down	
8		Koheda	Sriramulapally	11KV	Husnabad	19:15				Break down	
9		Guruvannapet	Guruvannapet	11KV	Husnabad	20:35				Break down (3PH)	
10		Guruvannapet	Pochanpally	11KV	Husnabad	21:15				Break down (3PH)	
11		Nagpuri	Gandkunta	11KV	Husnabad	15:40	16:45	1:05		Disk failure	
12		Komuravelli	Komuravelli 24 hrs	11KV	Husnabad	21:00				Break down	
13		Gajwel	Town1	11KV	Gajwel	13.05	13.17	0.12		conductor snapped	
14		Markook	Markook Town	11KV	Gajwel	15.20	20.30	5.10		E/L	
15		Damarakunta	Damarakunta	11KV	Gajwel	20.01	20.30	0.29		E/L	
16		Raipole	Thimmakpally	11KV	Gajwel	10.01	14.10	4.09		conductor snapped	
17		Dommat	Surampally	11KV	Gajwel	14.55	18.30	3.75		E/L	
18		Marpadaga	AGL Marpadaga	11KV	Gajwel	4.35	6.40	2.05		Conductor snapped	
1	RR S	Gandham Guda	Hydharshakote	11KV	RJNR	9:40	10:36	0:56		Tree branches fallen on 11KV line at Bairagiguda old Village	No
2		Gandham Guda	Suncity	11KV	RJNR	11.10	12.40	01.30		11KV Insulator failed at Santhi Nagar	No
3		Rajendranagar	Chinthamet	11KV	RJNR	11.45	12.40	00.55		DTR Brass Patti cut touching to channel	No
4		Kattedan-II	Murali Hotel	11KV	RJNR	12.05	12.55	00.50		11KV Cable failure at Gowri Plastic Company	No
5		Lanco Hills	Sai Aishwarya	11KV	Gachibowli	14.09	15.16	01.07		Iron Pole touched to 11KV line at Chitrapuri Showroom	No
6		Lodha	Indu Apartment	11KV	Kondapur	16:02	17:05	1:03		11KV Insulator failed at 4 <sup>th</sup> Phase	No
1	RR N	Kompally	Jayabheri	11KV	Medchal	16:45	17:25	0:40		100KVA DTR Brass patti cut & replacement at Bank Colony	No
1	HYD N	James Street	Chikoti Complex	11KV	Sec'bad	08.10	10.25	02.15	EL	No Visible Fault	Arranged B/F on 11KV Minerva fdr
1	HYD C	Fever Hospital	Barkathpura Bus Depot	11KV	Azamabad	10.28	12.05	01.37	EL	Tree branches fallen on lines (3No. DTR's Kept Off at Jalal Apts)	No