

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		5		5		5			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		5		5		5			
	Total	606	3055	0	12	0	12	0	12	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		17		17		17			
3	MDK	107	933									
4	SDPT				14		14		14			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	32	0	32	0	32	0	0	
	Grand Total	1082	6468	0	44	0	44	0	44	0	0	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddarevelly	Chinnarevelly	11KV	Jadcherla	10.58	13.30	02.32		Bird died on The 11KV line near Yerrakunta Cheruvu Side	No
1	NLG	Annaparthi	Annaparthi	11KV	Nalgonda	13:10	14:55	1:45	E/L	Tree fallen on the line	No
2		Thimmannagudem	Telakantigudem	11KV	Nalgonda	04.05	04.40	00.35	E/L	Insulator failed	No
3		Eduloor	Parada	11KV	Nalgonda	11.00	14.30	03.30	E/L	Tree fallen on the line	No
4		Aitipamula	Annaram	11KV	Nalgonda	09.25	11.25	02.00	E/L	Insulator failed	No
5		Kethepally	Korlapahad	11KV	Nalgonda	08.00	10.30	02.30	E/L	Jumper cut	No
6		Pullemla	Pullemla	11KV	Nalgonda	01.30	04.15	02.45	E/L	Tree fallen on the line	No
7		Chandur	Gundrrapally	11KV	Nalgonda	09.00	12.30	03.30	E/L	11KV Line cut	No
8		Chandur	Kastala	11KV	Nalgonda	02.00	04.20	02.20	E/L	Jumper cut	No
9		Madgulapally	Kukadam	11KV	Nalgonda	12.00	13.45	01.45	E/L	Jumper cut	No
10		Mupparam	Vootkur	11KV	Miryalaguda	06.30	07.49	01.19	E/L	11KV Jumper cut	No
11		Mukundapuram	Kalluru	11KV	Huzurnagar	03.00	06.30	03.30	E/L	Insulator failed	No
12		Alingapuram	Gundlapahad	11KV	Huzurnagar	07.30	09.20	01.50	E/L	11 KV Line snapped	No
13		Garidepally	Kalmalcheruvu	11KV	Huzurnagar	12.50	14.00	01.10	E/L	Jumper cut	No
14		Pedaveedu	Lothuvagu	11KV	Huzurnagar	07.00	10.00	03.00	E/L	Jumper cut	No
15		Solipet	Ramulthanda	11KV	Bhongir	06.00	08.00	02.00	EL	11kv Insulator failed	No
16		Solipet	Peraram	11KV	Bhongir	05.30	08.00	02.30	EL	25KV DTR failed	No
17		Peddakandukur	Masaipet	11KV	Bhongir	23:25	8:30	9:05	EL	11KV Disc failed	No
1	SDPT	Husnabad	Husnabad Town-1	11KV	Husnabad	7:50	8:45	0:55		Tree branch touched line	No
2		Potharam	Potharam Rural	11KV	Husnabad	01.20	06.30	05.10		Due to gale and wind	No
3		Potharam	Mirzapoor	11KV	Husnabad	00.00	10.00	10.00		Insulator failure	No
4		Thotapally	Mallampally	11KV	Husnabad	16.00	00.00	08.00		S-Ph supply OK 3-Ph BD	No
5		Gandipally	Ramavaram	11KV	Husnabad	00.00	08.50	08.50		Tree branch touched line	No
6		Gandipally	Ramavaram	11KV	Husnabad	22.30	00.00	01.30		Break Down	No
7		Ramchandrapur	Vinjapally	11KV	Husnabad	00.00	13.10	13.10		HT/LT same rectified	No
8		Thotapally	Thotapally (T)	11KV	Husnabad	00.00	05.40	05.40		Insulator failure	No
9		Koheda	Kurella	11KV	Husnabad	02.50	05.40	02.50		Insulator failure	No
10		Guruvannapet	Guruvannapet	11KV	Husnabad	00.00	06.30	06.30		Insulator failure	No
11		Guruvannapet	Posanpally	11KV	Husnabad	00.00	06.30	06.30		Insulator failure	No
12		Guruvannapet	Tapaspally	11KV	Husnabad	21.05	00.00	02.55		Break Down	No
13		Nagapuri	Gandikunta	11KV	Husnabad	05.30	07.00	01.30		Insulator failure	No
14		Nagapuri	Pothreddypalli	11KV	Husnabad	20:20	0:00	3:40		S-Ph supply OK 3-Ph BD	No
1	RR N	Mayurinagar	Ramnareshnagar	11KV	Kukatpally	20:16	21:21	1:05		Due To Havy Rain & Wind	No
2		UMCC	RM Nagar	11KV	Medchal	19.45	20.15	00.30		11KV Line touched to 11KV Pole at PP Nagar	No
3		GP Pally	GP Pally	11KV	Medchal	15.50	16.50	01.00		Tree fallen on 11KV Line at Pipes Company	No
4		Kolthur	Kolthur	11KV	Medchal	16.20	18.15	01.55		LT Line touched to HT Line at Kolthur Village	No
5		Kistapur	IDA Hanuman	11KV	Medchal	15:45	16:55	1:10		11KV Line cut & replacement at Rolastar Company	No
1	RR E	Mallapur-2	LV-1	11KV	Habsiguda	17:00	19:10	2:10		11KV Bus bar Polymer Disc failed at SS Yard	No
2		Pocharam	Jodimetla	11KV	Habsiguda	20.28	21.25	00.57		11KV Pin insulator failed at Viva Colony	No
1	HYD S	Asmangadh	Goutham Nagar	11KV	Asmangadh	01.10	02.45	01.35	All Indication	3No. Jumpers cut at Patel Nagar	No
2		Miralam	Shaik-E-Masjid	11KV	Charminar	20:25	21:30	1:05	EL	Pin Insulator flash over at Owaisy Hills	No
1	HYD C	Asif Nagar	Military	11KV	Mehdipatnam	20.00	21.30	01.30	EL	Tree branches fallen on lines at Military Area	No
2		A.C Guards	N.M.D.C	11KV	Mehdipatnam	20.03	21.25	01.22	EL	No Visible Fault	No
3		A.C Guards	Niloufer Hospital	11KV	Mehdipatnam	20.03	21.15	01.12	EL	AB Switch End Kit failed at Town Planning Office	No