

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		9		9		9			
3	MDK	107	933		1		1		1			
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	13	1	13	1	13	0	0	
	Grand Total	1082	6468	1	16	1	16	1	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 09.07.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Amangal	Polepally	33kv	Shadnagar	00.05	05.00	04.55		No Visible Fault Due to Rain	Polepally	-

TSSPDCL - LMRC / Corporate office

Date: 09.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Pedda Revelly	Chinna Revally	11kv	Jadcherla	11.10	12.30	01.20		Bird Died on The 11Kv line Near Ambru Naik Dtr at Chinnarevelly(V)	-
1	NLG	Mattampally	Erjelu	11kv	Huzurnagar	09.00	12.00	03.00	EL	Due to 11Kv agl jumper cutted	-
2		Raghunadapalem	Nakkalagudem	11kv	Huzurnagar	07.50	10.50	03.00	EL	Due to 11Kv agl jumper cutted	-
3		Ananthagiri	Mogalaikota	11kv	Huzurnagar	11.20	12.20	01.00	EL	Due to 11Kv line snapped	
4		Thurkapally	Thurkapally	11kv	Nalgonda	08.00	13.10	05.10	EL	Tree Branches On 11KV Line Phase To Phase Melting.	
5		Appajipeta	Anneprthy AGL	11kv	Nalgonda	12.15	14.20	02.05	EL	HT/LT Line Melting	
6		Madgulapally	Kukkadam	11kv	Nalgonda	15.00	17.00	02.00	EL	Moment Fullt	
7		Koppol(K)	Koppole	11kv	Nalgonda	06.00	08.30	02.30	EL	11KV Line Cutting.	-
8		Kolanpaka	Somaram	11kv	Bhongir	05.40	09.00	03.20	EL/OL	11kv Line snapped near Doodi venkatapur School	-
9		Alair	Ikkurthi	11kv	Bhongir	07.00	12.40	05.40	EL	11kv Pin Insulator Faied near Ikkurthi Village	-
1	MDK	Gaddapotharam - I	Matrix	11kv	Patancheru	15.10	16.50	01.40		BD due to Tree fallen on line	-
1	SDPT	Koheda	Theegalakuntapally	11kv	Husnabad	17.00	18.00	01.00		3 Ph BD,1 Ph ok	-
2		Nagapuri	Gandikunta	11kv		12.40	13.30	00.50		Conductor snapped	-
1	RR N	Jeedimetla-III	Back lighty Hylam	11kv	Jeedimetla	01.20	02.20	01.00	OL	11kv line AB Cable Failure at SS Back side	-
1	HYD S	Gosha Mahal	M.J.Market	11kv	Begumbazar	02.40	04.05	01.25	EL,OL-Bph	Cable fault at Vazeer Complex	----
2		Osm. Hospital	Gowliguda	11kv	Begumbazar	02.52	04.23	01.31	All Indication	Cable fault at Gowliguda	Arranged B/F on 11KV Puthlibowli fdr