

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		5		5		5			
7	RR(E)	168	403									
8	Hyd	194	1044		6		6		6			
	Total	606	3055	0	12	0	12	0	12	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		9		9		9			
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	12	1	12	1	12	0	0	
	Grand Total	1082	6468	1	24	1	24	1	24	0	0	

TSSPDCL - LMRC / Corporate office

Date: 12.07.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Oil Seeds	33KV	Gadwal	08.56	12.50	03.54	E/L	Conductor Snapped near 132KV SS	Oil Seeds	-

TSSPDCL - LMRC / Corporate office

Date: 12.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Koppole(K)	Kopolu	11KV	Nalgonda	08.30	11.00	02.30	E/L	11 KV Line Jumper Cut	-
2		Wnagamathy	Madharam	11KV	Nalgonda	12.00	15.00	03.00	E/L	11 KV Line Jumper Cut	-
3		Penpahad	SR Palem	11KV	Suryapet	06.30	08.50	02.20	E/L	Insulator flashover	-
4		Karvirala	Ramachandrapuram	11KV	Huzurnagar	21.45	23.50	02.35	E/L	11 KV LINE SNAPPED	-
5		Keethavarigudem	Laxmipuram	11KV	Huzurnagar	05.00	08.30	03.30	E/L	11 KV LINE MILT	
6		Palakeedu	Sajjapuram	11KV	Huzurnagar	14.00	17.00	03.00	E/L	11 KV JUMPER CUT	
7		Nemaragommula	Jammelapeta	11KV	Bhongir	17.50	20.30	02.40	E/L	11 kv Insulator Failed	
8		Maryala	Chowderpally	11KV	Bhongir	18.00	21.00	03.00	E/L	11 kv Insulator Failed	
9		Sharajipet	Tangutoor	11KV	Bhongir	04.00	07.00	03.00	E/L	11 kv Insulator Failed	-
1	SDPT	Dharmaram	Dharmaram(R.)	11KV	Husnabad	15.20	15.45	00.25		DTR Cable problem	-
2		Guruvannapet	Tapaspally	11KV	Husnabad	06.30	09.35	03.05		Insulator failure	-
3		Koheda	Theegalakuntapally	11KV	Husnabad	06.00	10.40	04.40		Insulator failure	-
1	RR S	Kattedan-I	Feeder-IV	11KV	RJNR	10.30	13.25	02.55	B/D	11KV Pole damaged at Disha foods due to Lorry dashed	-
1	RR N	Kompally	NCL	11KV	Medchal	01.40	02.40	01.00	BD	No Fault	-
2		Subhash Nagar	Padma Nagar	11KV	Medchal	17.25	19.05	01.40	BD	11KV Cable end kit failed at	-
3		Kompally	Kompally	11KV	Medchal	18.25	19.09	00.44	BD	11KV Cable end kit failed at Bhagi Reddy Fanction	-
4		GP Pally	Aparna	11KV	Medchal	04.00	05.30	01.30	BD	11KV Disc failed at Aparna Opp	-
5		Shameerpet	Alankrita	11KV	Medchal	12.10	13.00	00.50	BD	11KV Jumper Cut & Replaced at Janaki Seeds, Shameerpet	-
1	HYD C	ITI Mallepally	Anjuman	11KV	Mehdipatnam	20.52	21.57	01.05	EL,OL	No Visible Fault	Partial bit charged at 21:34Hrs (60/140Amps) & remaining loads added on 11KV J.K.Nagar fdr
2		Lake View	Eenadu	11KV	Mehdipatnam	12.10	13.45	01.35	EL	Cable fault at Lumbini Rock Apts	-----
1	HYD S	Kandikalgate	Naseeb Nagar	11KV	Charminar	18.13	19.57	01.44	EL	Pin Insulator flash over Bajaj Show Room	-----
2		Falaknuma	Guntal Shah Darga	11KV	Charminar	18.35	19.40	01.05	EL,OL-Rph	Kite Sticks fallen on lines at Ayaan Hotel	-----
3		Khilwath	Khajipura	11KV	Charminar	21.20	23.25	02.05	EL,OL	2No. Cable Jumpers, 1No. top Jumper cut & Brass Patti B/O at Khajipura	Partial bit charged at 22:05Hrs (10/75Amps) Line AB Switch opened at Khajipura
4		Ch' Baradari	S.R.T Colony	11KV	Charminar	06.50	08.00	01.10	EL,OL	I/C Jumper cut at Ice Factory	-