

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1	6	1	6	1	6			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	2	15	2	15	2	15			
3	MDK	107	933									
4	SDPT			1	1	1	1	1	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>17</b>	<b>3</b>	<b>17</b>	<b>3</b>	<b>17</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>24</b>	<b>4</b>	<b>24</b>	<b>4</b>	<b>24</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 16.07.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Dirsincherla	Garidepally	33KV	Huzurnagar	13.15	17.00	03.45	EL/OL	33 kv pole damaged	Garidepally	-
2		Dirsincherla	Mukundhapuram	33KV	Huzurnagar	13.10	18.00	05.50	EL/OL	33 kv pole damaged	Mukundhapuram	-
1	SDPT	Palamakula	Baddipadaga	33KV	Husnabad	00.00	09.00	09.00		BD due to line problem	Baddipadaga	-
1	HYD S	220KV Shivrampally	Hyderguda	33KV	Asmangadh	00.20	00.35	00.15	EL	Cable puntured by DRHCL at PVNR Piller No.17	Hyderguda	Loads transferred onto 33KV Sh' Pally - Karwan OH line

## TSSPDCL - LMRC / Corporate office

Date: 16.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Mallaboinpally	Mallaboinpally	11kv	Jadcherla	06.58	10.38	03.40		11KV Disc fail near Mallaboinpally	-
1	NLG	SLBC	M.D.Pally	11kv	Nalgonda	10.40	13.40	03.00	E/L	11 KV Line Jumper Cut	-
2		Kattangur	Bollepally	11kv	Nalgonda	02.00	06.40	04.40	E/L	Tree fallen on line	
3		Kattangur	Kalimera	11kv	Nalgonda	02.30	06.00	03.30	E/L	Tree fallen on line	
4		Narketpally	Mandra	11kv	Nalgonda	08.40	11.30	02.50	E/L	11KV Insulator Failure	
5		Thoragal	Thangellavarigudem	11kv	Nalgonda	07.00	09.00	02.00	E/L	Disk failed	
6		Thoragal	Gajendravarigudem	11kv	Nalgonda	04.30	06.00	01.30	E/L	11 KV Line Jumper Cut	
7		Narketpally IE	Narketpally indl	11kv	Nalgonda	08.00	09.05	01.05	E/L	HT LT line milting	
8		Mukundapuram	G kothapally	11kv	Suryapet	05.45	06.50	01.05	E/L	Insulator failed	
9		Kudakuda	Ilapuram	11kv	Suryapet	07.30	09.15	01.45	E/L	Jumper cut	
10		Amaravaram	Lingagiri	11kv	Huzurnagar	05.00	07.30	02.30	EL	11 KV LINE SNAPPAED	
11		Dirincherla	Somaram	11kv	Huzurnagar	06.00	09.30	03.30	EL	11 KV POLE DAMAGED	
12		Dirincherla	Narsaigudem	11kv	Huzurnagar	04.00	08.30	04.30	EL	11 KV POLE DAMAGED	
13		Palakeedu	Bothalapalem	11kv	Huzurnagar	04.00	07.30	03.30	EL	11 KV INSULATOR FAILED	
14		Munagala	Nelamarry	11kv	Huzurnagar	18.15	21.45	03.30	EL	11 KV LINE SNAPPAED	
15		Paladugu	Dattappagudem	11kv	Bhongir	01.25	07.25	06.00	EL	100KVA DTR Failed	
1	SDPT	Cherial	Cherial Town	11kv	Husnabad	18.40	19.50	01.10	BD	BD due to line fault	-
1	RR N	Uddamarry	Usharpally	11kv	Medchal	10.30	12.05	01.35		Tree Branch fallen on the 11KV Line at Mallanna Temple	-
1	HYD N	Mothi Nagar	B.S.Puri	11kv	IV	10.00	11.20	01.20	EL	11KV Jumper cut at Spencers Super Market (10:10Hrs 20/40Amps loads charged)	
1	HYD C	Golconda	Aditya Nagar Cable	11kv	VII	14.32	15.45	01.13	EL	Pin Insulator flash over at Samatha Colony	
2		Chilkaiguda	Golconda X-Roads	11kv	II	15.04	16.32	01.28	EL	Post type Insulator flash over at Care Hospital, Piller No.21	
3		Amberpet	C.P.L	11kv	II	15.18	17.20	02.02	EL,OL-R&Bph	Insulator flash over at Patel Nagar	
4		S.D.Hospital	Crescent Hospital	11kv	VII	15.46	17.01	01.15	EL,OL-Yph	Cable fault of Universal Breaker at N.M.D.C	
5		S.D.Hospital	Crescent Hospital	11kv	VII	17.17	18.17	01.00	EL,OL-Yph	HT Jumper cut at Andhra Bank	