

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550	1	14	1	14	1	14			
7	RR(E)	168	403		6		6		6			
8	Hyd	194	1044		6		6		6			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>28</b>	<b>1</b>	<b>28</b>	<b>1</b>	<b>28</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	4	2	4	2	4			
2	NLG	144	988	2	40	2	40	2	40			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>5</b>	<b>44</b>	<b>5</b>	<b>44</b>	<b>5</b>	<b>44</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>6</b>	<b>72</b>	<b>6</b>	<b>72</b>	<b>6</b>	<b>72</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 20.07.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kalwakurthy	Marcharla	33KV	Nagarkurnool	03.40	09.05	05.25	E/L	LV Panel Spark at SS	Kalwakurthy	No
2		Makthal	Narva	33KV	Narayanapet	02.10	04.20	02.10	E/L	Pin insulator replaced near Raikot	Makthal	No
1	NLG	Mattampally	Raghunadapalem	33KV	Huzurnagar	06.00	10.00	04.00	EL/OL	33 KV JUMPER CUT	Mattampally	No
2		Dirincherla	Mukundapuram	33KV	Huzurnagar	02.10	05.30	03.20	EL/OL	33 kv Disk Failed	Dirincherla	No
1	MDK	Bollaram	Bollaram-II	33KV	Patancheru	17.33	20.15	02.42		BD due to Condcutor snapped	Bollaram	No
1	RR N	132KV LGM Pet	33KV BE Vaccine	33KV	Medchal	Medchal	00.00	07.30	0.3125	33KV Disc failed at Alexandria Company	132KV LGM Pet	No

## TSSPDCL - LMRC / Corporate office

Date: 20.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Pedda Revally	Hemajipur	11KV	Jadcherla	05.25	09.30	04.05		BD 11KV Insulator fail near Pedda Revally	-
2		Rajapur	Mudireddypally	11KV	Jadcherla	03.00	08.30	05.30		BD 11KV Wire cut near Mudireddypally	-
3		Donur	Vaspula	11KV	Jadcherla	03.10	09.00	05.50		BD 11KV Wire cut near Vallabraopally	-
4		Mallaboinpally	Bureddypally	11KV	Jadcherla	04.00	09.30	05.30		BD 11KV Wire cut near Bureddypally	-
1	NLG	Narketpally	Express feeder	11KV	Nalgonda	00.00	02.50	02.50	E/L	11 KV Line Jumper Cut	-
2		Kanagal	Kanagal	11KV	Nalgonda	04.00	07.00	03.00	E/L	11 KV Line Jumper Cut	-
3		Thoragal	Gajendraigudem	11KV	Nalgonda	07.00	08.00	01.00	E/L	11KV Insulator Failure	-
4		B.Vellemla	B.Vellemla	11KV	Nalgonda	04.00	07.00	03.00	E/L	11KV Insulator Failure	-
5		Nemmani	Melakunta	11KV	Nalgonda	13.00	16.44	03.44	E/L	11 KVn line cut	-
6		Nemmani	Pothnenipally	11KV	Nalgonda	09.00	12.30	03.30	E/L	Tree fallen on line	-
7		Narketpally IE	Express feeder	11KV	Nalgonda	06.20	08.49	02.29	E/L	11KV Insulator Failure	-
8		Indugula	Malaparajugudem	11KV	Nalgonda	12.00	16.10	04.10	E/L	11 KV Line Jumper Cut	-
9		Mamidala	Aregudem	11KV	Nalgonda	09.00	11.20	02.20	E/L	11KV Insulator Failure	-
10		Arlagaddagudem	NR gudem	11KV	Nalgonda	07.00	08.50	01.50	E/L	11 KV Line Jumper Cut	-
11		Eduloor	Munukuntla	11KV	Nalgonda	07.00	08.50	01.50	E/L	11KV Insulator Failure	-
12		Rajavaram	Rajavaram	11KV	Miryalaguda	06.50	17.45	10.55	E/L	11KV Disc failed	-
13		Pulicherla	Pulicherla	11KV	Miryalaguda	14.30	16.17	01.47	E/L	Conductor snapped	-
14		Yacharam	Annaram	11KV	Miryalaguda	02.40	06.10	03.30	E/L	11KV Disc failed	-
15		Velmagudem	Velmagudem	11KV	Miryalaguda	06.00	07.50	01.50	E/L	11KV Disc failed	-
16		Damarcherla	M.K.Charla	11KV	Miryalaguda	07.00	08.00	01.00	E/L	Tree fallen	-
17		Damarcherla	K.N.Konda	11KV	Miryalaguda	05.00	06.30	01.30	E/L	11KV Disc failed	-
18		Ramadugu	Palem	11KV	Miryalaguda	02.00	08.00	06.00	E/L	11KV Disc failed	-
19		Thummadam	Thummadam	11KV	Miryalaguda	06.00	08.00	02.00	E/L	11KV Disc failed	-
20		Penpahad	Ananjipuram	11KV	Suryapet	11.30	12.40	01.10	E/L	Insulator failed	-
21		Amararam	Yathavakilla	11KV	Huzurnagar	03.30	06.00	02.30	EL	11 KV LINE SNAPPED	-
22		Mattapally	Sultahnपुरa thanda	11KV	Huzurnagar	04.30	06.30	02.00	EL	11 KV JUMPER CUT	-
23		Palakeedu	Bothalapalem	11KV	Huzurnagar	05.30	07.00	01.30	EL	11 KV LINE SNAPPED	-
24		Karvirala	Keshavapuram	11KV	Huzurnagar	03.40	06.20	02.40	EL	11 KV LINE SNAPPED	-
25		Mellacheruvu	Revoor	11KV	Huzurnagar	05.00	08.30	03.30	EL	11 KV JUMPER CUT	-
26		Munagala	Industrial	11KV	Huzurnagar	02.00	05.30	03.30	EL	11 KV LINE SNAPPED	-
27		IDA	Bommaipally	11KV	Bhongir	02.00	06.00	04.00	EL	11kv Line snapped near Bommaipally Village 3 Phase B/d Single Phase Ok	-
28		Raigir	Jammapur	11KV	Bhongir	09.10	10.30	01.20	EL	11kv Insulator Failed near Jammapur Village	-
29		MR.Gudem	Baswapuram	11KV	Bhongir	09.00	11.30	02.30	EL	11kv Pin Insulator Failed near Baswapur Cherru 3 Phase B/d Single Phase Ok	-
30		CH.Laxmapur	Madapur Town	11KV	Bhongir	04.00	08.30	04.30	EL	11 kv DISC Failed at Petrolbunk Near Madapur Town	-
31		Bibinagar	Arun teja	11KV	Bhongir	00.10	10.05	09.55	EL	3no's 11kv Poles Dammegeged near Bibinagar Village	-
32		Rajapeta	Renikunta Agl	11KV	Bhongir	02.00	07.30	05.30	EL	11 kv Insulator Failed at SS-4 Near Renikunta Village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
33		Alair	Alair Town	11KV	Bhongir	05.00	07.00	02.00	EL	11 kv Pin Insulator Failed at SS-20 Near Alair town	-	
34		Mothkur	Kondagadapa	11KV	Bhongir	06.00	10.00	04.00	EL	11kv Insulator Failed near Sub_ station 3 Phase B/d Single Phase Ok	-	
35		Paladugu	Dattappagudem	11KV	Bhongir	04.00	08.00	04.00	EL	11 kv Insulator Failed at SS-1 Near Dattappagudem Village	-	
36		Paladugu	Duppelly	11KV	Bhongir	04.00	08.30	04.30	EL	11 KV Insulator Failed at Okkonigudem Near Duppelly Village	-	
37		Athmakur	Koratikal	11KV	Bhongir	05.00	10.00	05.00	EL	11kv Disc Failed & 11kv Insulator Failed near Athmakur Village	-	
38		Ramannapeta	Siripuram	11KV	Choutuppal	06.00	08.50	02.50	EL	11kv Pin Insulator Failed near IGM School	-	
39		Yannaram	Palliwada	11KV	Choutuppal	10.20	11.05	00.45	EL	11kv Insulator Failed near Palliwada Village	-	
40		Aroor	Gurnathpally	11KV	Choutuppal	04.00	06.00	02.00	EL	11 kv Insulator Failed Near Gurnathpally Village	-	
1		RR S	IIIT	Jayabheri	11KV	Gachibowli	04.15	05.18	01.03	BD	Internet cable fallen on the 11kv line at Street No.3, Old Gachibowli	-
2			Cyber city	Muskipet	11KV	Kondapur	05.55	07.20	01.25	BD	11kv Cable end-kit failed at Road No.1, Pragathi Nagar,Muskipet	-
1	RR N	Vemana Colony	Bhavani puram	11KV	Medchal	00.10	03.00	02.50	BD	11kv Pin insulator failure At R V udayan	-	
2		G Vikas	Reddy Colony	11KV	Medchal	07.30	08.30	01.00	BD	11kv Pole Damage At bus Depo	-	
3		Nizampet	Srinivasa colony	11KV	Medchal	00.28	01.36	01.08	BD	11kv Pin insulator failure At K T R colony Road -3	-	
4		Chandanagar	Shankernagar	11KV	Medchal	01.30	03.10	01.40	BD	11kv Pin insulator failure At Shilapa Enclave	-	
5		Jeedimetla-IV	Tagorea	11KV	Medchal	07.00	08.30	01.30	BD	Tree fallen On the 11kv Line opp Tagorea Company	-	
6		Jeedimetla-IV	AUTO Stand	11KV	Medchal	02.35	03.25	00.50	BD	Due To Rain	-	
7		UMCC	Mahadevpuram	11KV	Medchal	01.05	01.30	00.25	BD	Line AB Switch opened at Mahadevpuram( 11KV Pin Insulator failed )	-	
8		HMT	Ganesh Nagar	11KV	Medchal	01.20	04.20	03.00	BD	11KV Pin Insulator failed at Kalpna Society	-	
9		Chintal	Bhagathsingh Nagar	11KV	Medchal	23.10	00.25	01.10	BD	11KV Pin Insulator failed at Vasantha Enclave, Bhagathsingh Nagar	-	
10		Subhash Nagar	Ramraj Nagar	11KV	Medchal	03.12	03.50	00.38	BD	11KV Jumper Cut at Sensor Shopping Mall	-	
11		Athiwelly	Somaram	11KV	Medchal	04.25	06.10	01.45	BD	11KV Disc failed at Somaram Alugu	-	
12		Athiwelly	SPIC	11KV	Medchal	05.20	07.40	02.20	BD	11KV Pin Insulator failed at Mailaram	-	
13		ICICI	ICICI	11KV	Medchal	03.30	06.20	02.50	BD	2 Nos. Pin Insulators failed at IKP	-	
14		Devarayamjal	Kottapet	11KV	Medchal	00.00	02.25	02.25	BD	11KV Pin Insulator failed at 6th Pole Devaramjal	-	
1	RR E	Moula ali	HCL	11KV	Sainikpuri	01.30	02.45	01.15		Tree fallen on 11KV line at Rod No 7 (FOC Bal Narshma)	-	
2		Anand Bagh	NMDC	11KV	Sainikpuri	02.52	04.45	01.53		11KV Pin Insulator failed at Shalini Apt nearEast Anand Bagh (FOC Shankar)	-	
3		AS Rao Nagar	Gokul Nagar	11KV	Sainikpuri	18.03	18.40	00.37		UG Cable failed at Shardha Bus Stop (due to AB Switch Open 1/2 bitt charged OK) (LM Srinivas)	-	
4		Ramanthapur	Gokhale Nagar	11KV	Habsiguda	23.39	01.26	01.47		Line Patrolling but no visible fault	-	
5		IDA Uppal	Jersey	11KV	Habsiguda	23.30	03.15	03.45		11KV Outgoing B-Phase Post of Insulator failed at SS Yard	-	
6		Nacharam Indore	Mallikarjuna Nagar	11KV	Habsiguda	07.02	08.05	01.03		Line Patrolling but no visible fault & B/F from 11KV Hema Nagar	-	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	H.A.L.	Indian Rubber	11KV	Bowenpally	02.15	03.35	01.20	EL	No Visible Fault	-
2		Chinna Thokatta	Central Excise	11KV	Bowenpally	02.40	03.55	01.15	EL,OL-Y&Bph	No Visible Fault	-
1	HYD S	Yakuthpura	Saleema Khatoon	11KV	Asmangadh	01.44	06.33	04.49	EL	Road Crossing UG Cable fault at Yakuthpura Bridge	Arranged B/F on 11KV Khan Nagar feeder
2		Aliyabad	Boys Town	11KV	Charminar	02.44	04.06	01.22	EL	Cable fault	Arranged B/F on 11KV Masrath Function Hall fdr
3		Salarjung	Alija Kotla	11KV	Charminar	04.46	06.00	01.14	EL,OL	Cable fault	Arranged B/F on 11KV Gulzar House feeder
4		Salarjung	Q.Q Stadium	11KV	Charminar	11.46	13.20	01.34	EL,OL-Bph	Cable fault	Arranged B/F on 11KV Petlaburz fdr