

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		8		8		8			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		8		8		8			
	Total	606	3055	0	17	0	17	0	17	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		7		7		7			
3	MDK	107	933		2		2		2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	10	1	10	1	10	0	0	
	Grand Total	1082	6468	1	27	1	27	1	27	0	0	

TSSPDCL - LMRC / Corporate office

Date: 25.07.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Kodair	33KV	Wanaparthi	09.15	12.16	03.01	O/L	Due to LA Blast at 220KV SS Wanaparthi	Kodair	-

TSSPDCL - LMRC / Corporate office

Date: 25.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Mothiganapur	Medigadda Thanda	11KV	Jadcherla	07.35	11.30	03.55		11KV Insulator Failed near Mothiganapur	-
1	NLG	Arvpally	Ramannagudem	11KV	Suryapet	10.45	13.15	02.30	E/L	Conductor snapped	-
2		Madgulapally	Kukkadam	11KV	Nalgonda	09.15	10.40	01.25	E/L	11KV jumper cut	-
3		Eduloor	Gadibaigudem	11KV	Nalgonda	16.25	17.00	00.35	E/L	11KV jumper cut	-
4		Mellavai	Devathpally	11KV	Devarakonda	14.15	15.00	00.45	E/L	11 kv Insulator Failed	-
5		Dirsincherla	Yellapuram	11KV	Huzurnagar	14.10	16.57	02.47	OL	Due to 11Kv line jumer cutted	-
6		Munagala	Kokkireni-II	11KV	Huzurnagar	13.40	16.30	02.50	EL	Due to 11Kv line snapped	-
7		Kolanpaka	Raghavapuram	11KV	Bhongir	02.45	06.30	03.45	EL/OL	11kv Raghvapuram Feeder lighting arrester Failed	-
1	MDK	ARoor	EXPRESS	11KV	Sangareddy	10.40	11.50	01.10		BD due to Insulator Burst	-
2		Patancheru Town	MIA-II	11KV	Patancheru	18.45	19.55	01.00		BD due to Insulator Failed	-
1	RR N	Jeedimetla-I	JETEL	11KV	Jeedimetla	18.34	19.34	01.00		T/F Pin insulator failure at Tech Mahindra	-
2		Dp pally-II	Tech mhindra	11KV	Jeedimetla	12.05	13.05	01.00		11kv Bird fallen on the 11kv line Near tech mahindra	-
3		Dp pally-II	Tech mhindra	11KV	Jeedimetla	13.35	14.50	01.15		Cloth Fallen on 11KV Line at AP Agro	-
4		HMT	Manikya Nagar	11KV	Medchal	18.37	19.17	00.40		11KV Pin Insulator Failed at Tirupathi Electronics	-
5		Petbasheerabad	Balaji Hospital	11KV	Medchal	18.38	19.58	01.20		11KV Jumper cut and replaced at Mandaipally Road	-
6		Thumkunta	Thumkunta	11KV	Medchal	06.36	08.00	01.24		No Visible Fault	-
7		Shameerpet	Nalsar	11KV	Medchal	18.40	20.50	02.10		11KV Post of Insulator Failed at Laxma Reddy Garden,MC Pally	-
8		Laxmapur	MC Pally	11KV	Medchal	19.25	20.40	01.15		No Visible Fault	-
1	RR E	Narapally	Prathap Singaram	11KV	Keesara	09.15	09.40	00.25		11KV Brass patti cut at Korremula Village	-
1	HYD N	Sanjeevaiah Park	Police Line	11KV	C-VI	17.35	18.45	01.10	EL,OL-Rph	No Visible Fault	Arranged B/F on 11KV My Fair Complex feeder
2		H.M.T	Sri Sai Colony	11KV	VI	18.30	19.35	01.05	EL,OL-Rph	No Visible Fault	-
3		Gymkhana	Pared Ground	11KV	C-VI	19.05	20.50	01.45	EL	Post type Insulator flash over Nala DTR	-
4		Hakimpet	Allenby Lines	11KV	C-VI	19.15	20.50	01.35	EL	Tree branches fallen on lines at Allenby Lines	Arranged B/F on 11KV Bollarum P.S feeder
5		Pragatools	L&T	11KV	VI	18.38	00.40	06.02	EL,OL-Bph	Pin Insulator flash over at IDA, Gandhi Nagar (Partial fdr charged at 19:42Hrs)	-
1		Amberpet	Play Ground	11KV	II	17.30	19.00	01.30	EL	Pin Insulator flash over at Akram Hotel	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
2	HYD C	Mothi Mahal	Saleh Nagar	11KV	VII	18.22	20.16	01.54	EL,OL-Yph	Tree branches fallen on lines at Saleh Nagar	-
3		Asif Nagar	Jyothi Nagar	11KV	VII	19.25	20.50	01.25	All Indication	Cable fault at Oliva Hospital	-