

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	5	1	5	1	5			
7	RR(E)	168	403		8		8		8			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	1	17	1	17	1	17	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	1	4	1	4	1			
2	NLG	144	988	4	32	4	32	4	32			
3	MDK	107	933		1		1		1			
4	SDPT				32		28		28			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	8	66	8	62	8	62	0	0	
	Grand Total	1082	6468	9	83	9	79	9	79	0	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Nagarkurnool	33KV	Nagarkurnool	16.32	18.15	01.43	O/L	Due to Rain	Nagarkurnool	Alternate supply arranged form 33KV Ithole SS at 18:15Hrs
2		Makthal	Narwa	33KV	Narayanapet	10.45	12.25	01.40	E/L	Tree Fallen on the line near Minority colony	Narwa	-
3		Makthal	Maganoor	33KV	Narayanapet	19.30	20.20	00.50	E/L	Tree Fallen on the line	Maganoor	-
4		Alampur	Undavelly	33KV	Gadwal	16.06	17.00	00.54	E/L	Due to Rain	Undavelly	Alternate supply Arranged from 33KV Alampur SS at 17:00Hrs
1	NLG	Ramannapet	Velminedu	33KV	Nalgonda	00.00	02.00	02.00	E/L	Tree Branched fallen on the line Tree Cutting Done		-
2		Ramannapet	Chityal	33KV	Nalgonda	00.00	01.15	01.15	E/L	Tree Branched fallen on the line Tree Cutting Done		-
3		Suryapet	HPCL	33KV	Suryapet	04.30	09.00	04.30	E/L	5No.s 33Kv Insulator Flashover		-
4		Thungathurthy	Thungathurthy	33KV	Suryapet	03.30	08.15	04.45	EL/OL	33Kv Insulator Flashover		-
1	RR N	LGM Pet	BE Pharma	33KV	Medchal	15.58	17.30	01.32		33KV Pin Insulator Failed and replaced at near by Nektar Company	BE Pharma	-

TSSPDCL - LMRC / Corporate office

Date: 26.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kothamolgara	Maddigatla	11KV	Jadcherla	07.00	11.00	04.00		11KV Pin Binding Fail near Nallagutta Side	-
1	NLG	Aregudem	Chityala AGL	11KV	Nalgonda	09.35	11.00	01.25	E/L	Bird Died on the 11 KV Line	-
2		Palem	Palem	11KV	Nalgonda	20.30	11.10	14.40	E/L	Tree Branches Fallen on the Line	-
3		Nakrekal	Nomula	11KV	Nalgonda	20.30	10.00	13.30	E/L	Due to Hevay Rain	-
4		Nakrekal	Chandanapally	11KV	Nalgonda	20.30	10.50	14.20	E/L	Due to Hevay Rain	-
5		Nakrekal	Marrur	11KV	Nalgonda	20.30	11.00	14.30	E/L	Due to Hevay Rain	-
6		Kattangur	Bollepally	11KV	Nalgonda	03.00	10.00	07.00	E/L	Big Tree Fallen on the 11 KV Line	-
7		Nakkalapally	Shapally	11KV	Nalgonda	00.00	14.00	14.00	E/L	Pin Insulator Failed	-
8		Urumadla	Yelikatte	11KV	Nalgonda	16.35	17.40	01.05	E/L	11KV Jumper Cut	-
9		Edulagudem	Edulagudem	11KV	Miryalguda	08.30	09.30	01.00	E/L	11KV disc insulator failed	-
10		Miryalguda Town	Housing Board	11KV	Miryalguda	16.00	17.30	01.30	E/L	Tree branches fallen on the line	-
11		B.Annaram	Kothapeta	11KV	Miryalguda	10.30	12.30	02.00	E/L	11Kv pin insulator failed near SS	-
12		B.Annaram	Balajinagar	11KV	Miryalguda	11.25	12.45	01.20	E/L	Tree branches fallen on the line near village	-
13		Athmakur (S)	T.Penpahad	11KV	Suryapet	06.30	09.40	03.10	E/L	11Kv Insulator flashover	-
14		Nagaram	Wardhamanu kota	11KV	Suryapet	11.30	15.00	03.30	E/L	11Kv Conductor snapped	-
15		Yerkaram	Ramannagudem	11KV	Suryapet	04.30	08.00	03.30	E/L	11Kv Insulator flashover	-
16		Thatipamula	Sri ram thanda	11KV	Suryapet	05.45	09.20	03.35	E/L	11Kv Insulator flashover	-
17		Amararam	Yathavakilla	11KV	Huzurnagar	07.00	09.45	02.45	E/L	11Kv Jumper Cut	-
18		Ananthagiri	Shantinagar	11KV	Huzurnagar	05.00	07.20	02.20	E/L	11Kv Jumper Cut	-
19		Dirincherla	Chellepally	11KV	Huzurnagar	05.30	09.00	03.30	E/L	11Kv Line Snapped	-
20		Gondiryala	Gondiryala-1	11KV	Huzurnagar	03.00	06.30	03.30	E/L	11Kv Line Snapped	-
21		Palakeedu	Palakeedu	11KV	Huzurnagar	05.00	08.40	03.40	E/L	11Kv Disk Failed	-
22		Dirincherla	Narsaigudem	11KV	Huzurnagar	10.30	11.50	01.20	E/L	11Kv Disk Failed	-
23		Garidepally	Appannpet	11KV	Huzurnagar	13.30	14.40	01.00	E/L	11Kv Line Snapped	-
24		Nandanam	Thukkapuram	11KV	Bhongir	09.30	11.40	02.10	E/L	11kv Disc Failed at Jittola well Near Thukkapur Village	-
25		Motakondur	Motakondur Town	11KV	Bhongir	23.50	03.10	03.20	E/L	11kv Insulator Failed Near Motakondur Town	-
26		Raghunathpur	Raghunathpur Agl	11KV	Bhongir	04.00	07.55	03.55	E/L	11kv Pin Insulator Failed at Basanthapuram Village	-
27		Datherpally	Jangampally	11KV	Bhongir	13.30	14.45	01.15	E/L	11kv Insulator Failed at Bal reddy well Near Jangampally Village	-
28		Ambala	Parupally	11KV	Bhongir	08.30	09.30	01.00	E/L	11kv Insulator Failed Near Parupally Village	-
29		Ramannapeta	Bogaram	11KV	Choutuppal	06.20	10.10	03.50	O/L	11kv Line Snapped Near Bogaram Village	-
30		Jai Kesaram	Jai Kesaram Agl	11KV	Choutuppal	08.30	10.50	02.20	E/L	11kv Insulator Failed Near Jai kesaram Village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
31		Peddaravulapally	Peddaravulapally	11KV	Choutuppal	14.40	16.50	02.10	E/L	11kv Insulator Failed Near Peddaravulapally Village	-
32		Sangem	Dubbala	11KV	Choutuppal	07.45	11.44	03.59	E/L	11KV Disc Failed Near Dubbala Village	-
1	MDK	Gaddapotharam -I	Matrix	11KV	Patancheru	17.40	19.40	02.00		BD due to Conductor Snapped	-
1		Potharam	Potharam Town	11KV	Husnabad	13.40	16.10	02.30		Disc failure same rectified	
2		Potharam	Keshawapoor	11KV	Husnabad	00.00	10.50	10.50		Tree branched fallen on line same rectified	
3		Akkannapet	Gollakunta	11KV	Husnabad	11.45				S-ph supply OK, 3-Ph supply BD	
4		Gouravelly	Gouravelly Rural	11KV	Husnabad	00.00	12.00	12.00		Disc failure same rectified	
5		Bejjanki	Muthannapet	11KV	Husnabad	12.00				S-ph supply OK, 3-Ph supply BD	
6		Koheda	Venkateshwarapally	11KV	Husnabad	10.40	12.10	01.30		Insulator failure same rectified	
7		Koheda	Kurella	11KV	Husnabad	11.50	13.55	02.05		Insulator failure same rectified	
8		Akunoor	Rudrapally	11KV	Husnabad	11.10	15.40	04.30		Lines touched same rectified	
9		Gurjakunta	Gurjakunta Agl	11KV	Husnabad	11.20				S-ph supply OK, 3-Ph supply BD	
10		Mustyal	Cherial Agl	11KV	Husnabad	00.00				S-ph supply OK, 3-Ph supply BD	
11		Guruvannapet	Tapaspally	11KV	Husnabad	09.20	16.05	06.45		Insulator failure same rectified	
12		Dhoolmitta	Dhoolimitta Agl	11KV	Husnabad	05.00	17.00	12.00		Line fallen same rectified	
13		Rebarthy	Rebarthy	11KV	Husnabad	01.00	12.30	11.30		Insulator failure same rectified	
14		Rebarthy	Ladnoor	11KV	Husnabad	00.00	06.00	06.00		Due to gale and wind	
15		Marmamula	Dharmaram	11KV	Husnabad	09.09	13.42	04.33		Due to gale and wind	
16	SDP	Kondakandla	Town	11KV	Gajwel	04.00	08.00	04.00		Jumper cut	
17		Jagadevpur	Dhavalapur agl	11KV	Gajwel	01.00	07.40	06.40		Insulator failure	
18		Wargal	Town	11KV	Gajwel	07.30	08.00	00.30		Tree branches fallen on line	
19		Chirasagar	chirasagar	11KV	Gajwel	14.00	15.30	01.30		Insulator failure	
20		Mulugu	Bilampur	11KV	Gajwel	03.00	09.00	06.00		Jumper cut	
21		Mulugu	Mulugu Agl	11KV	Gajwel	07.00	12.00	05.00		Conductor snapped	
22		Mulugu	Indl	11KV	Gajwel	16.42	19.10	02.28		Insulator failure	
23		Markook	Sneha	11KV	Gajwel	01.00	05.00	04.00		Insulator failure	
24		Ramsagar	Ankireddyapally	11KV	Gajwel	13.55	17.20	03.25		Insulator failure	
25		Raipole	Indl	11KV	Gajwel	21.40	06.52	09.12		Tree branches fallen on line	
26		Raipole	Indl	11KV	Gajwel	13.17	14.25	01.00		Tree branches fallen on line	
27		Anajipur	Anajipur	11KV	Gajwel	07.00	10.24	03.24		Tree branches fallen on line	
28		Domata	Surampally	11KV	Gajwel	14.00	15.30	01.30		Insulator failure	
29		Doulthabad	Lingarajpally	11KV	Gajwel	11.25	16.08	04.42		Insulator failure	
30		Doulthabad	Githampally	11KV	Gajwel	14.35	17.30	02.55		Insulator failure	
31		Medhinipur	Mangole	11KV	Gajwel	07.10	11.35	04.25		Insulator failure	
32		Kondapak	Viswanathpally	11KV	Gajwel	08.30	15.00	06.30		Tree branches fallen on line	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Devarayamjal	Kottapet	11KV	Medchal	08.50	10.00	01.10		Tree fallen on the 11KV Line at Radhika Garden	-
2		Medicity	IDA-I	11KV	Medchal	12.40	14.05	01.25		Tree Branch fallen on the 11KV Line at Khandelwal Company	-
3		Devarayamjal	Mandaipally	11KV	Medchal	15.00	17.30	02.30		Tree Fallen on 11KV Line at Sanjava Reddy Bavi,Mandaipally	-
4		Laxmapur	MC Pally	11KV	Medchal	12.45	14.10	01.25		11KV Disc Failed at Cheruvukatta	-
5		Devarayamjal	Kottapet	11KV	Medchal	11.00	17.30	06.30		11KV Line AB Switch Opened at VRL Company	-
1	RR E	Janapriya	Vampuguda	11KV	Sainikpuri	04.20	06.45	02.25		11KV Disk Failed at Maruthi Nagar (LM Janardhan)	-
2		Nacharam Indore	Vyjanthi	11KV	Habsiguda	14.29	15.36	01.07		Insulator fail at Kalyani motor back side	-
3		Aushapur	Madharam	11KV	Keesara	17.00	19.00	02.00		Line cut at Madharam village	-
4		Chekripuram	Ayyappa	11KV	Keesara	16.20	16.59	00.39		Insulaotr fail at MVR nagar	-
5		Saket	Dammaiguda	11KV	Keesara	01.05	02.30	01.25		11KV jumper cut at Laxmi nagar Dammaiguda	-
6		Narapally	Industrial	11KV	Keesara	17.50	18.30	00.40		Insulator fail at venkatadri town ship phase 3	-
7		Peerzathiguda	China reddy thota	11KV	Keesara	17.00	21.20	04.20		Line AB swithc open half feeder Ok due to disk fail at Spark hospital	-
8		Peerzathiguda	China reddy thota	11KV	Keesara	01.35	03.00	01.25		Line petroling done no visiable falt found	-
1	HYD N	H.M.T	Sri Sai Colony	11KV	VI	14.20	16.00	01.40	EL	No Visible Fault	-
2		H.A.L	Sri Rama	11KV	VI	14.30	16.00	01.30	EL	No Visible Fault	-
3		I.D.P.L	Vijaya Electrical	11KV	VI	14.45	16.58	02.13	EL,OL-Rph	Cable fault	Arranged B/F on 11KV Lokesh Machine feeder
4		MLA Colony	Cine Ghar	11KV	X	23.10	00.20	01.10	EL,OL-Rph	Faulty DTR at Road No.12	-