

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		22		22		22			
3	MDK	107	933		1		1		1			
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>27</b>	<b>1</b>	<b>27</b>	<b>1</b>	<b>27</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>31</b>	<b>1</b>	<b>31</b>	<b>1</b>	<b>31</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 28.07.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kothur	Binju Metals	33KV	Shadnagar	00.45	07.50	07.05		B Phase Jumper at 132KV SS Kothur	Binju Metals	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Thirmalapur	Dondlapally	11KV	Jadcherla	09.32	12.16	02.44		Due to 11 KV jumper cut and disc failed Near Dondlapally.	No
1	NLG	Anneparthi	Betalian	11KV	Nalgonda	12:05	14:25	2:20	E/L	Tree fallen on the line	No
2		Appajipeta	Appajipeta	11KV	Nalgonda	01.30	04.30	03.00	E/L	11 KV Line Jumper Cut	No
3		Thoragal	Madaram	11KV	Nalgonda	13.50	15.20	01.30	E/L	11 KV Line Jumper Cut	No
4		Akkenapally	Akkenapally	11KV	Nalgonda	12.30	15.30	03.00	E/L	Insulator Failure	No
5		Nemmani	Pothinenipally	11KV	Nalgonda	12.00	16.00	04.00	E/L	Disk failure	No
6		Nakkalapally	Shapally	11KV	Nalgonda	12.20	14.05	01.45	E/L	11 KV Line Jumper Cut	No
7		Nakrekal	Kadaparthi	11KV	Nalgonda	11.50	14.05	02.15	E/L	11 KV Line Jumper Cut	No
8		Nakrekal	DaNDAMPALLY	11KV	Nalgonda	12.18	14.10	01.52	E/L	Insulator Failure	No
9		Nakrekal	Nomula	11KV	Nalgonda	12.35	15.35	03.00	E/L	HT, LT line milting	No
10		Kethepally	Inupamula	11KV	Nalgonda	13.00	15.00	02.00	E/L	11 KV Line Jumper Cut	No
11		Nakrekal	Chandampally	11KV	Nalgonda	12.18	14.10	01.52	E/L	Insulator Failure	No
12		Tekumatla	Yendlapally	11KV	Suryapet	12.15	14.30	02.15	E/L	Insulator flashover	No
13		Kudakuda	M.G Nagar thanda	11KV	Suryapet	15.10	16.30	01.20	E/L	Conductor snapped	No
14		Ananthagiri	Shantinagar	11KV	Huzurnagar	03.30	06.30	03.00	EL	11KV Line snapped	No
15		Bethavolu	Seetharamnagar Thanda	11KV	Huzurnagar	04.30	08.00	03.30	EL	11KV Disc failed	No
16	Munagala	Kokkereni-2	11KV	Huzurnagar	03.30	07.00	03.30	EL	11KV Line snapped	No	
17	Dirincherla	Narsigudem	11KV	Huzurnagar	01.30	06.40	05.10	EL	11KV Line snapped	No	
18	Burugadda	Burugadda	11KV	Huzurnagar	11.05	13.00	01.55	EL	Insulator Failure	No	
19	Ananthagiri	Mogalaikota	11KV	Huzurnagar	15.10	16.15	01.05	EL	11KV Line snapped	No	
20	Addagudur	CH.Ramaram	11KV	Bhongir	08.15	11.00	02.45	EL	Insulator Failure	No	
21	Addagudur	Addagudur Agl	11KV	Bhongir	10.10	12.20	02.20	EL	Insulator Failure	No	
22	Voligonda	Mandapuram	11KV	Choputuppall	13:21	17:00	3:39	EL	Insulator Failure	No	
1	MDK	Bollaram - II	Vasavidatta	11KV	Patancheru	13:50	14:20	0:30		Due to CT PT Problem	No
1	SDPT	Husnabad (NEW)	Malapally	11KV	Husnabad	0:00	0:09	0:09		Disc failed	No
2		Husnabad (NEW)	Malapally	11KV	Husnabad	09.50	12.30	02.40		Insulator Failed	No
3		Chityal	Chityal Agl	11KV	Husnabad	00.00	05.20	05.20		Due to rain	No
1	RR N	Kompally	Garden Society	11KV	Medchal	11:10	12:50	1:40		11KV Pin Insulator failed at Gym Center,Jaibheri	No
2		Kandlakoya	Goderj IDA	11KV	Medchal	09.10	10.50	01.40		Tree fallen on the 11KV line at Cold Storage company,GP Pally	No
3		Mayurinagar	Ram nareshaNagar	11KV	Kukatpally	10.55	12.38	01.43		Cloth fallen on the 11kv Line near mithra Hills	No
1	HYD C	Bathkammakunta	Saibaba Temple	11KV	II	10.58	13.04	02.06	EL,OL-Rph	Disc Insulator flash over at Sudarshan Apts., SBI Colony	No