

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550		9		9		9			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		13		13		13			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>27</b>	<b>0</b>	<b>27</b>	<b>0</b>	<b>27</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		6		6		6			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT				6		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>14</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>41</b>	<b>3</b>	<b>39</b>	<b>3</b>	<b>39</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 31.07.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Dilip Roling Mill	33KV	Jadcherla	19.50	20.50	01.00	EL	LA Failed and Replaced	Dilip Roling Mill	-
2		Sri Rangapur	Scan Energy	33KV	Shadnagar	17.58	19.00	01.02	EL	Line Side Jumper Cut at 132KV SS	Scan Energy	-
1	MDK	Zaheerabad	Machnoor	33KV	Zaheerabad	15.00	18.00	03.00		B/D due to Insulator failure	Machnoor	-

## TSSPDCL - LMRC / Corporate office

Date: 31.07.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	MT.Pally	Mulkapally	11KV	Bhongir	04.00	22.15	06.15	EL	25 kva DTR Failed	-
2		Ramannapet	Janampally	11KV	Choutuppal	11.10	13.15	02.05	EL	11kv Insulator Failed	-
3		Dondapadu	Kakatiya	11KV	Huzurnagar	10.25	13.30	03.05	EL	Due to 11Kv line snapped	-
4		Ananthagiri	V.R.Puram	11KV	Huzurnagar	10.50	13.30	02.40	EL	Due to HT/LT fault occurred	-
5		Gondriyala	Gondriyala 02	11KV	Huzurnagar	10.00	13.00	03.00	EL	Due to 11Kv line cuted	-
6		Eduloor	Naregudem	11KV	Nalgonda	16.15	18.00	01.45	EL	11KV Line Jumper Cut	-
1	MDK	Collectorate	Office	11KV	Sangareddy	18.20	20.15	01.55		B/D due to Pin Insulator failure	-
2		Sangareddy Town-II	No-III	11KV	Sangareddy	19.30	23.00	03.30		B/D due to Tree branches fallen on the line	-
1	SDP	Gandipally	Nandaram	11KV	Husnabad	18.15	Still			Heavy gale and wind(3 PH)	-
2		Gandipally	Gandipally	11KV	Husnabad	18.25	Still			Heavy gale and wind(3 PH)	-
3		Ramchandrapur	Vinjapally	11KV	Husnabad	18.30	19.40	01.10		Heavy gale and wind	-
4		Mustyala	Cherial town	11KV	Husnabad	06.55	12.50	05.55		Disk Failure	-
5		Koheda	Thegalakuntapally	11KV	Husnabad	15.00	17.40	02.40		Insulator failure	-
6		Chityala	Thadoor	11KV	Husnabad	19.40	21.15	01.35		Heavy gale and wind	-
1	RR S	Nanakramguda	Manjeera	11KV	Gachibowli	14.15	15.28	01.13	BD	11kv Disc failure near Manjeera Diamond.	-
2		Balajinagar	Moosapet	11KV	Kondapur	20.11	21.25	01.14	BD	Star cable fallen on the 11kv line near D-mart and Bird fallen on the 11kv line near Chaitanya food court.	-
1	RR N	Vikas	Kendriyavihar	11KV	Kukatpally	16.30	18.35	02.05		11kv line jumper & Conductore cut at Block No:03	-
2		Aleap	Doctores Colony Cable	11KV	Jeedimetla	11.20	12.40	01.20		Tree Branchesh Fallen the 11kv line Near Plot:1146 ,Pragathinagar	-
3		Dppally	Gagillapur	11KV	Jeedimetla	09.30	10.30	01.00		Tree Branchesh Fallen the 11kv line Near Nagaloor	-
4		Dppally	Ganddimaisamma	11KV	Jeedimetla	15.10	16.10	01.00		Bowrampet Line AB Open & Insulater Failure at HP Petrol Bunk	-
5		Dulapally	Dulapally Village	11KV	Medchal	03.32	05.50	02.18		11KV Pole damaged by Lorry at near Govt School	-
6		Chintal	Ganesh Nagar	11KV	Medchal	10.55	11.25	00.30		11KV Brass Patti Cut & Replaced at NTR Nagar	-
7		Kompally	Aparna	11KV	Medchal	14.20	15.01	00.41		Tree Branch fallen on the 11KV Line at HP Petrol Bunk	-
8		Devarayamjal	DMC	11KV	Medchal	16.40	19.30	02.50		11KV Pin Insulator faled Near Arakalaguda Village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
9		Medchal	IDA-I	11KV	Medchal	18.45	20.05	01.20		11KV Jumper cut and replaced Near Check Post	-
1	RR E	Uppal	Nava Bharath	11KV	Habsiguda	15.35	17.25	01.50		11KV Pin Insulator failed near Aparna Redimix Company at IDA Uppal	-
2		Balaji Nagar	Sai Baba	11KV	Keesara	14.28	15.30	01.02		Tree branches fallen on 11kv line at Firing Range Area	-
3		Singapur	RGK	11KV	Keesara	19.25	20.25	01.00		11KV line cut at ORR Ghanapuram	-
1	HYD S	Attapur	Allah Masjid	11KV	III	10.10	11.38	01.28	EL,OL	Cable fault	Arranged B/F on 11KV Kishan Bagh OH feeder
2		Aliyabad	Police Quarters	11KV	III	20.38	22.50	02.12	EL	Insulator flash over at Ammanwadi	-
3		Miralam	Kalapather	11KV	III	12.30	13.40	01.10	EL,OL	Cable damaged by MCH wing at Shanthi Stall (1No. DTR kept off)	-
4		Khilwath	Charminar	11KV	III	15.55	17.35	01.40	EL,OL	Tree fallen on lines at Mothi Gally	-
5		Falaknuma	Jangam Mett AB Cable	11KV	III	16.00	17.55	01.55	EL,OL-Rph	Tree fallen on lines at Kalva Gadda	-
6		Panjasha	Sulthan Shahi	11KV	III	19.00	20.10	01.10	EL	Pin Insulator flash over at Mehar Baba Nagar	-
7		Gunj	Palton	11KV	VIII	19.15	20.25	01.10	EL	Pin Insulator flash over at Palton X Road	-
1	HYD C	S.D.Hospital	Khadi Bandar	11KV	VII	19.10	20.25	01.15	EL	No Visible Fault	-
2		Vittalwadi	YMCA	11KV	II	19.10	20.30	01.20	EL,OL-R&Bph	Pin Insulator flash over at Nrupathunga College	-
3		Fever Hospital	C.C.S Hospital	11KV	II	19.37	20.55	01.18	All Indication	RMU fault at C.C.S Hospital	-
4		Erramanzil	Red Rose	11KV	I	08.18	09.50	01.32	EL,OL	No Visible Fault	-
5		Durga Nagar	Krishna Nagar	11KV	II	15.30	16.50	01.20	EL,OL-Rph	Pin Insulator flash over at Ashok Function Hall, Zindatilismath Road	-
6		Chilkalguda	44 Bus Stop	11KV	II	16.30	18.15	01.45	EL,OL	Cable fault	Arranged B/F on 11KV Parsigutta fdr