

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	2	1	2	1	2	1			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	2	7	2	7	2	7	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	13	1	13	1	13			
2	NLG	144	988	1	52	1	52	1	52			
3	MDK	107	933	2	1	2	1	2	1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	66	4	66	4	66	0	0	
	Grand Total	1082	6468	6	73	6	73	6	73	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.06.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kothur	PNG	33KV	Shadnagar	00.10	14.15	14.05		AB Switch open at Company No Visible fault at line		-
1	NLG	Marriguda	Gattupal	33KV	Devarakonda	19.00	17.00	22.00		2 Nos. 33 KV Poles Damaged		Alternate Supply Taken from 33/11 KV SS Janagam
1	MDK	Zaheerabad	Chota Hyderabad	33KV	Zaheerabad	00.00	12.05	12.05		BD due to Isulator failed		-
2		Zaheerabad	New Allana	33KV	Zaheerabad	12.30	14.45	02.15		BD due to Isulator failed		-
1	RR N	132KV LGM Pet	33KV Aliabad	33KV	Medchal	08.10	13.18	05.08		33KV Bus Bar Y Phase Replaced at Aliabad SS		-
2		132KV Medchal	33KV Medchal-II	33KV	Medchal	08.58	10.30	01.32		33KV Jumper cut at near by 132KV Medchal SS		-

TSSPDCL - LMRC / Corporate office

Date: 04.06.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	udithyal	udithyal	11KV	Jadcherla	07.00	11.00	04.00		Ht/Lt Near Veerannapally Tanda Side.	-
2		Donoor	Donoor	11KV	Jadcherla	11.50	13.09	01.19		11Kv Phase To Phase Near Donoor Tanda Side.	-
3		Donoor	Vaspula	11KV	Jadcherla	02.00	09.55	07.55		11Kv Wire Cut Near Vallab Raopally(Vi).	-
4		Badepally	Alwanpally	11KV	Jadcherla	21.45	10.50	13.05		Pin Insulator Failure Near Alwanpally(Vi).	-
5		Badepally	Burgupally	11KV	Jadcherla	21.45	11.00	13.15		11kv jumper Cut Near kistampally(Vi).	-
6		Badepally	Gangapur	11KV	Jadcherla	21.45	13.20	15.35		B.D. Pin Insulator Failure Near Gangapur(Vi).	-
7		Janampet	Polkampally	11KV	Jadcherla	20.45	07.05	10.20		B.D. 11kv jumper Cut Near Janampet(Vi).	-
8		Tirumalapur	Khanapur	11KV	Jadcherla	09.09	09.56	00.47		B.D.Tree Follen On The 11Kv line Near Hanuman Temple Khanapur (Vi)	-
9		Hemajipur	Hemajipur	11KV	Jadcherla	11.00	12.55	01.55		B.D.11Kv Line Cut Near Hemajipur(Vi).	-
10		kothapally	Velgomla	11KV	Jadcherla	08.00	09.10	01.10		B.D.11Kv Phase To Phase Chilver(Vi).	-
11		Kothamolgara	Kothamolgara	11KV	Jadcherla	20.05	09.15	13.10		11Kv Insulator failure Near Chinna Kappeta(Vi).	-
12		Kothamolgara	Elkiherla	11KV	Jadcherla	06.45	10.00	03.15		11Kv Phase To Phase Near Battupally(Vi).	-
13		Kothamolgara	Karvena	11KV	Jadcherla	20.05	15.00	18.55		11Kv Phase To Phase Near Dharambavi(Vi).	-
1		B.Banda	B.Banda	11KV	Nalgonda	06.10	10.00	03.50		11 KV Line Jumper Cut	-
2		B.Banda	N.G.Kothapally	11KV	Nalgonda	00.00	15.00	15.00		11 KV Line Jumper Cut and 2 Nos. Poles Damaged	
3		Pamanagundla	Pittampally	11KV	Nalgonda	04.00	07.55	03.55		HT/LT Line Melt	
4		Pamanagundla	Dasarigudem	11KV	Nalgonda	03.00	06.30	03.30		Tree Branches Fallen on the 11 KV Line	
5		P.D.Pally	Kanchanapally	11KV	Nalgonda	16.10	10.20	18.10		Tree Branches Fallen on the 11 KV Line and 11 KV Jumper Cut	
6		P.D.Pally	Domalapally	11KV	Nalgonda	16.20	15.35	23.15		Tree Branches Fallen on the 11 KV Line and 11 KV Jumper Cut	
7		Narketpally	Mandra	11KV	Nalgonda	07.30	09.40	02.10		HT/LT Line Melt	
8		Aregudem	Chinnakaparthi	11KV	Nalgonda	10.10	12.50	02.40		11 KV Line Disc Failure	
9		Arlagaddagudem	Tatikal	11KV	Nalgonda	06.00	08.00	02.00		HT/LT Line Melt	
10		S.Gouraram	Gurjala	11KV	Nalgonda	18.00	07.00	13.00		11 KV Line Cut	
11		Kethepally	Inupamula	11KV	Nalgonda	20.00	12.20	16.20		Big Tree Fallen on the Line	
12		Dirincherla	Chellepally	11KV	Huzurnagar	04.00	06.30	02.30	EL	11 KV LINE SNAPPED	
13		Sirikonda	Raipahad	11KV	Huzurnagar	05.00	08.00	03.00	EL	11 KV JUMPER CUT	
14		Keethavarigudem	Kothagudem	11KV	Huzurnagar	06.00	09.30	03.30	EL	11 KV LINE SNAPPED	
15		Keethavarigudem	Keethavarigudem	11KV	Huzurnagar	06.30	09.00	02.30	EL	11 KV LINE SNAPPED	
16		Nadigudem	Karivirala	11KV	Huzurnagar	09.00	12.05	03.05	EL	11 KV DISK FAILED	
17		Tallasingaram	Somlathanda	11KV	Suryapet	09.30	13.00	03.30	EL	11KV Conductor snapped at ss-23	
18		Padamtipally	Iddampally	11KV	Devarakonda	06.30	09.00	02.30	EL	11 Kv Disc Failed	
19		Padamtipally	Thurupupally	11KV	Devarakonda	06.30	16.00	09.30	EL	HT/HT & 11KV 1 No Insulator Failed	
20		Padamtipally	Kandukur	11KV	Devarakonda	06.30	18.00	11.30	EL	Only S-Ph OK	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
21	NLG	Tatikol	Kacharam	11KV	Devarakonda	06.10	19.00	12.50	EL	Only S-Ph OK	
22		Pendlipakala	Gajinagar	11KV	Devarakonda	03.00	11.49	08.49	EL	HT/HT	
23		Devarakonda	Devarakonda town-1	11KV	Devarakonda	19.25	22.00	02.35	EL	Jumper Cutt	
24		Devarakonda	Devarakonda town-2	11KV	Devarakonda	22.00	15.00	17.00	EL	Pole Damaged	
25		Devarakonda	K.B.Pally	11KV	Devarakonda	22.00	06.00	08.00	EL	Tree Fallen	
26		Devarakonda	Mynampally	11KV	Devarakonda	22.00	06.00	08.00	EL	DTR Failed	
27		Chandampeta	G.Polepally	11KV	Devarakonda	08.30	10.30	02.00	EL	HT/HT	
28		Chandampeta	Gajilapuram	11KV	Devarakonda	08.30	12.30	04.00	EL	11 KV 2 Nos Insulator failed	
29		Kothapally	Peruvala	11KV	Devarakonda	07.30	17.20	09.50	EL	1 No Pole Damaged	
30		Kothapally	Kista Thanda	11KV	Devarakonda	07.30	16.30	09.00	EL	11 KV Line Cutt	
31		Kothapally	Peddemunigal	11KV	Devarakonda	07.30	12.40	05.10	EL	HT/HT	
32		Cherukupally	Bolanpally	11KV	Devarakonda	06.30	12.50	06.20	EL	Tree Fallon	
33		Cherukupally	Dindi Rural	11KV	Devarakonda	06.30	11.30	05.00	EL	Jumper Cutt	
34		Koppole	LD Gudem	11KV	Devarakonda	08.00	10.30	02.30	EL	HT/HT	
35		Koppole	Aregudem	11KV	Devarakonda	07.00	15.30	08.30	EL	Jumper Cutt	
36		Shivannagudam	R.R.Pally	11KV	Devarakonda	01.00	17.00	16.00	EL	Pole Damaged	
37		Marrigudam	Konduru	11KV	Devarakonda	06.00	13.00	07.00	EL	11 KV Line Cutt	
38		Marrigudam	Water Gried	11KV	Devarakonda	06.00	11.00	05.00	EL	11 KV 1 no Insulator Failed	
39		Chinthapally	Raingudam	11KV	Devarakonda	05.00	15.00	10.00	EL	2 Nos Pole Damaged	
40		Chinthapally	Nasarlappally	11KV	Devarakonda	06.30	17.30	11.00	EL	HT/HT	
41		Nampally	Peddapuram	11KV	Devarakonda	06.00	08.50	02.50	EL	Tree Fallon	
42		Bollepally	Jampally	11KV	Bhongir	06.00	13.15	07.15	OL	11 kv Jumper Cut & Phase to phase Near Jampally Village	
43		MT.Pally	Dharmaram	11KV	Bhongir	01.00	08.30	07.30	EL	SS-2 Post-off Insulator Failed Near Malkapur Church	
44		B.Ramaram	Malyala	11KV	Bhongir	06.00	9;00	03.00	OL	11 kv Line Snapped Near Devunithanda	
45		Golankonda	Matoor	11KV	Bhongir	03.00	07.20	04.20	OL	11 KV Disc Failed at Anjaiah Well Near Matoor Village	-
46		Raghunathpur	Challuru Agl	11KV	Bhongir	01.00	15.00	14.00	OL	10 no's Pole Dammaged Near Challuru Village	-
47		Datherpally	Jangampally	11KV	Bhongir	16.30	19.00	02.30	OL	40 NO;s 11 kv DTR's & 10 NO's LT Poles Dammaged.3 no's 100 kva DTR's & 1 no 25 kva DTR Dammaged	-
48		Datherpally	Mallapuram	11KV	Bhongir	16.30	19.30	03.00	OL	10 NO'S 11 KV Pole Dammaged & 1 no.100 Kva DTR' & 2 no's 25 Kva DTR's Dammaged.	-
49		Paladugu	Duppelly	11KV	Bhongir	10.00	18.00	08.00	OL	Feeder Limb Failed, Direct Connection . 2 DTR's OFF	-
50		Athmakur	Thukkapur	11KV	Bhongir	01.00	05.00	05.00	OL	HT/LT Near Thukkapur Village	-
51		Pallerla	Kurella	11KV	Bhongir	04.00	09.20	05.20	EL	2 no's Pole Dammaged & Tree Branchess Fallen at Line Near Kurella village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
52		Jangam	Jangam	11KV	Choutuppal	05.00	16.45	11.45	EL	2 no;s LT Pole Dammged.11 KV Insulator Failed & 11 kv Line Snapped Near Bollakunta Village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MDK	Pati	My Home	11KV	Patancheru	01.00	01.30	00.30		BD Due to Jumper cut	-
1	RR S	Lanco Hills	Khaja Guda	11KV	Gachibowli	13.10	16.58	03.48	BD	JCB Dashed The 11kv line Pole Near Llera Aharam Hotel at Khajaguda	-
1	RR N	Kistapur	IDA Hanuman	11KV	Medchal	09.05	10.45	01.40		Tree & Bird fallen on the 11KV Line at Ravalkole Common & Rice mill Kistapur	-
1	RR E	Mallapur	Mallapur Village	11KV	Habsiguda	06.30	07.30	01.00		11KV Insulator failed at K.L Reddy Community Hall	-
2		Boduppal	Hema Nagar	11KV	Habsiguda	11.20	13.20	02.00		11KV Pole damaged due to Lorry dashed at New Hema Nagar	-
3		Cherlapally-III	IOC	11KV	Sainikpuri	13.13	14.25	01.12		11Kv Pole damage at IOC Petrol Bunk (AE/OP)	-
4		Chengicherla	My Villas	11KV	Keesara	12.10	14.40	02.30		11KV Line cut at My Villas	-
1	HYD C	Fever Hospital	Fever Hospital	11KV	Azamabad	02.14	03.35	01.21	OL-Y&Bph	Tree branches fallen on lines at B.R.K.R.School	-