

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044	1	1	1	1	1	1			
	Total	606	3055	1	8	1	8	1	8	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		11		11		11			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	14	0	14	0	14	0	0	
	Grand Total	1082	6468	1	22	1	22	1	22	0	0	

TSSPDCL - LMRC / Corporate office

Date: 17.06.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD S	132KV Bandlaguda	Amberpet (Idle)	33KV	Chilalguda	07.06	14.40	07.34	EL,OL	Disc Insulator flash over near Location No.72, Moosi River Bridge	Amberpet (Idle)	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bothpur	Boothpur	11KV	Jadcherla	06.00	08.00	02.00		11KV Insulator failed near pothulamadugu.	No
2		Midjil	Boinpally	11KV	Jadcherla	08.15	11.40	03.25		11KV Jumper cut near Solar plant back side.	No
1	NLG	Thungathurthy	Vempaty	11KV	Suryapet	07.00	10:00	03.00	E/L	Insulator failed	No
2		Penpahad	Annaram	11KV	Suryapet	06.10	07.30	01.20	E/L	Conductor snapped	No
3		Gundepuri	Pasthala	11KV	Suryapet	07.10	09.30	02.20	E/L	Insulator failed	No
4		Rajupeta	Rajupeta	11KV	Nalgonda	04.40	07.40	03.00	E/L	11KV Jumper Cut	No
5		Marror	Gorenkalapally	11KV	Nalgonda	11.00	14.00	03.00	E/L	11KV Jumper Cut	No
6		Kodad Town	Kodad T-3	11KV	Huzurnagar	04.15	06.00	01.45	EL	Due to Cable failed near DTR	No
7		Akupamula	Singaram	11KV	Huzurnagar	06.00	09.00	03.00	EL	Due to 11KV Jumper cutted	No
8		Urulugonda	Sarvaram	11KV	Huzurnagar	15.10	17.20	02.10	EL	Due to 11KV Insulator failure	No
9		Akupamula	Akupamula Industrial	11KV	Huzurnagar	15.15	16.15	01.00	EL	Due to 11KV Jumper cut	No
10		Raghunathpur	Challur Agl	11KV	Bhongir	02.00	08.00	06.00	EL/OL	11KV Line snapped near Challur Village	No
11		Narayanapur	Kothagudem	11KV	Choutuppal	6:00	9:30	3:30	EL	11KV Insulator failed near Jangaon Road	No
1	MDK	Patancheru	High power	11KV	Patancheru	15:10	16:00	0:50		Jumper cut	No
1	RR S	Kismathpur	Vidyapeetam	11KV	Rajendranagar	2:50	3:50	1:00		11KV Insulator failed at Vidyapeetam	No
2		Rajendranagar	Pahadi	11KV	Rajendranagar	15.05	16.30	01.25		Tree branches fallen on 11KV line at Miratel Function Hall	No
1	RR N	Mayurinagar	Gokaraju Rangaraju	11KV	Kukatpally	1:05	3:00	1:55	OL	Aman fallen on the 11KV line at Vijaya School back side	No
2		Subhash Nagar	Jeedimetla	11KV	Medchal	02.16	02.55	00.39		Tree fallen on the 11KV line at HDFC Bank, Jeedimetla	No
3		Medchal	IDA Kandlakoya	11KV	Medchal	02.45	04.20	01.35		No visible fault	No
1	RR E	NGRI	HMT Nagar	11KV	Habsiguda	7:57	8:58	1:01		11KV Brass patti cut at St.No.04 HMT Nagar	No
2		Nagaram	S N Colony	11KV	Keesara	05.51	07.35	01.44		11KV Copper pati cut near GVR Garden	No
1	HYD S	Chanchalguda	Chowni	11KV	Asmangadh	20.25	21.45	01.20	OL-Rph	HT Line snapped at Azeem Cycle Taxi	Arranged B/F on 11KV Bada Bazar feeder