

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1	3	1	3	1	3			
	Total	606	3055	1	4	1	4	1	4	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	2	18	2	18	2	18			
3	MDK	107	933		1		1		1			
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	22	2	22	2	22	0	0	
	Grand Total	1082	6468	3	26	3	26	3	26	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.06.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	SURYAPET	Chandupatla	33KV	HUZURNAGAR	05.00	09.45	04.45	EL/OL	33 KV INSLATER FAILED		-
2		Dirincherla	Garidepally	33KV	HUZURNAGAR	17.00	20.00	03.00	EL/OL	PIN INSLATER FAILED		-
1	HYD C	132KV Asif Nagar	I.T.I Mallepally	33KV	Asif Nagar	01.47	01.57	00.10	EL,OL	-----		Loads transferred onto 132KV NIMS SS via 33KV Nampally SS

TSSPDCL - LMRC / Corporate office

Date: 18.06.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karvena	Karvena	11KV	Jadcherla	03.45	08.30	04.45		11KV Jumper cut near Karvena	-
1	NLG	Sharajipeta	Sharajipeta	11KV	Bhongir	07.30	11.00	03.30	EL	11kv Jumper Cut	-
2		Bondugula	Bondugula Agl	11KV	Bhongir	05.30	08.00	02.30	EL	11kv Jumper Cut	-
3		Paladugu	Dattappagudem	11KV	Bhongir	04.00	06.30	02.30	OL	11kv Line Snapped	-
4		Azeempet	Kanchanapally	11KV	Bhongir	06.00	08.05	02.05	EL	11 kv Jumper Cut	-
5		Gundala	Nunegudem	11KV	Bhongir	10.00	11.00	01.00	OL	HT/LT at SS-13	-
6		Ambala	Parupally	11KV	Bhongir	13.00	14.05	01.05	OL	HT/LT	-
7		Laxmapuram	Thummalagudem	11KV	Choutuppal	12.20	13.20	01.00	EL	11 kv Jumper Cut	-
8		Voligonda	Sunkishala	11KV	Choutuppal	07.30	09.40	02.40	EL	Bird Fallen at Line	-
9		Voligonda	Dasireddygudem	11KV	Choutuppal	11.30	15.30	04.00	OL	11 kv Line Snapped	-
10		Jalapuram	Gottipathy	11KV	Suryapet	06.30	09.40	03.10	E/L	Insulator failed	-
11		Janpahad	Janpahad	11KV	Huzurnagar	04.15	07.05	02.50	EL	11 KV INSLATER PIN BINDING CUT	-
12		Gaddipally	K B Puram	11KV	Huzurnagar	06.30	10.00	03.30	EL	11 KV LINE SNAPPED	-
13		Mukundapuram	Mukundapuram	11KV	Huzurnagar	08.30	11.00	02.30	EL	11 KV INSLATER FAILED	-
14		Sirikonda	Balluthanda	11KV	Huzurnagar	04.00	07.30	03.30	EL	11 KV LINE SNAPPED	-
15		Nemmani	Nemmani	11KV	Nalgonda	12.00	13.00	01.00	E/L	11 Kv line Insulator failed	-
16		Rayaniguda	J.R.gudem	11KV	Nalgonda	03.00	05.40	02.40	E/L	Jumper cut	-
17		Kethepally	Korlapahad	11KV	Nalgonda	01.00	03.00	02.00	E/L	Ab switch fault	-
18		Kethepally	Indl Feeder	11KV	Nalgonda	12.50	15.00	02.10	E/L	Bird Died on line	-
1	MDK	SOL	BMF	11KV	Patancheru	10.30	11.25	00.55		B/D Due to Conductor Snapped	-
8	SDPT	Bejjanki	Muthannapet	11KV	Husnabad	14.30	18.30	04.00		Insulator failure	-
9		Mustyala	Chunchunakota	11KV	Husnabad	00.00	11.20	11.20		Insulator failure	-
1	RR N	Kandalkoya	KV Reddy Nagar	11KV	Medchal	14.00	14.50	00.50	BD	11KV Pole damaged by Lorry at Bollaram Road	-
1	HYD N	Maitrivanam	Aditya UG	11KV	Erragadda	12.10	13.20	01.10	EL,OL-Rph	Foreign material fallen on lines at GHMC	-
1	HYD S	Kanchanbagh	Riyasath Nagar	11KV	Charminar	02.25	03.40	01.15	EL,OL-Rph	Disc insulator flash over at Omer Hotel	-
1	HYD C	Golconda	Mothi Mahal	11KV	Mehdipatnam	00.40	02.40	02.00		O/G Cable fault at F.F.Functional Hall	Arranged B/F on 11KV M.D Lines feeder