

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	2	3	2	3	2	3			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>9</b>	<b>2</b>	<b>9</b>	<b>2</b>	<b>9</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1				1		1No 33KV feeder still
2	NLG	144	988		13		13		13			
3	MDK	107	933									
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>14</b>	<b>1</b>	<b>14</b>	<b>0</b>	<b>14</b>	<b>1</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>23</b>	<b>3</b>	<b>23</b>	<b>2</b>	<b>23</b>	<b>1</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 19.06.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kalwakurthy	SCL Mills	33KV	Nagarkurnool	22.15		01.45	E/L&O/L	Not Rectified Due to Cable Damaged		No
1	HYD N	132KV Chinthal	H.A.L	NT	Allwyn	03.15	03.40	00.25	EL	Pole damaged by unknown person Opp.HMT Tractor Factory At 17.43 hrs Loads normalised after 2No R.S.Joint Poles erection at HMT Tractor Factory		Loads transferred onto 132KV IDPL SS via 33KV Bowenpally SS fdr
1	HYD S	132KV Chilkalguda	Chilkalguda	ST	Chilkalguda	00.02	00.12	00.10	EL,OL-Yph	Old Joint Kit failed at Mysamma Temple, Musheerabad X Road		Loads transferred onto 33KV Chilkalguda - Industrial Area line

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Yerkaram	Dasthanda	11KV	Suryapet	10.30	13.15	02.45	OL	HT/LT Line melt	-
2		Kistapuram	Thammaram	11KV	Huzurnagar	04.35	08.10	03.35	EL	Due to 1-Ph DTR Fault occured	-
3		Repala	Kalakova	11KV	Huzurnagar	12.05	13.10	01.05	EL	Due to bird fall on 11Kv line	-
4		Repala	Repala	11KV	Huzurnagar	20.10	23.00	02.50	EL	Due to 11Kv line cutted	-
5		Mattapally	Ramachandhrapuram	11KV	Huzurnagar	22.45	23.55	01.10	EL	Due to 11Kv line cutted	-
6		CH.Annaram	Garlabaigudem	11KV	Nalgonda	08.55	11.50	02.55	EL	Tree branches fallen on line at J.Shankar house	-
7		Pamukunta	Pamukunta	11KV	Bhongir	08.00	11.00	03.00	EL	11 KV Jumper Cut at Karronikaluva Near Pamukunta Village	-
8		Raghunathpur	Raghunathpur Agl	11KV	Bhongir	12.30	16.30	04.00	EL	11 kv Jumper cut at Ramanareddygudem Near Raghunathpur Village	-
9		Mothkur	Anajipur	11KV	Bhongir	07.55	08.50	00.55	OL	11 kv Line Snapped at Kalmakuntla road Near Anajipur Village	-
10		Yennaram	Palliwada	11KV	Choutuppal	02.20	10.40	08.20	OL	LT Line Snapped Near Yennaram Village	-
11		Malkapur	Malkapur Agl	11KV	Choutuppal	01.00	09.25	08.25	EL	11 kv Jumper Cut Near Malkapur Village	-
12		S.Lingotam	Lingijigudem Agl	11KV	Choutuppal	08.00	09.09	01.09	EL	11 KV Jumper Cut Near Lingoigudem Village	-
13		Voligonda	Mandapuram	11KV	Choutuppal	05.00	11.00	06.00	OL	11 KV Line Snapped Near Mandapuram Village	-
1	SDPT	Akunoor	Rampur	11KV	Husnabad	13.10	17.00	03.50		Heavy gale and wind (3 Ph)	
1	RR S	Gaganpahad	Sathamrai (V)	11KV	RJNR	05.31	06.45	01.14	BD	T/F post type insulator Failed at Sathamrai Village	-
2		Lanco Hills	Chitrapuri Colony	11KV	Gachibowli	12.32	13.32	01.00	BD	11KV Pole Bent by JCB Dashed and Rectified at Chitrapuri colony Crusher.	-
1	RR N	Kompally	NCL	11KV	Medchal	15.35	16.40	01.05	BD	11KV UG Cable Failed at Shivashivani School	-
2		Balajinagar	Kukatpally	11KV	Kukatpally	02.50	04.30	01.40	BD	11kv Pole Diamage At V V N nagar Colony kamman	-
3		Jeedimetla-III	Ram Reddy Nagar	11KV	Jeedimetla	07.45	08.50	01.05	EL/OL	Tree Branches fallen On The 11kv Line at ram reddy Nagar	-
1	RR E	Vasanthapuri	Raghavendra	11KV	Sainikpuri	02.00	03.22	01.22		UG Cable failed at Ushodaya Market and Raghavendra load added on Venkateshwar Nagar (Artisan Ramu)	-
1	HYD S	Miralam	Hasan Nagar	11KV	Charminar	04.20	15.45	11.25	EL,OL-Bph	Road Crossing Cable fault at Hasan Nagar	Arranged partial loads B/F on 11KV Ansari Road feeder
2		Miralam	Teegala Kunta	11KV	Charminar	17.20	19.05	01.45	EL,OL-Rph	Incoming Cable fault	Arranged B/F on 11KV MCH Colony feeder
1	HYD C	Vittalwadi	APCO	11KV	Azamabad	12.52	13.58	01.06	All Indication	No Visible Fault	Arranged B/F on 11KV Gandhi Kutter feeder