

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		3		3		3			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		12		12		12			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>14</b>	<b>0</b>	<b>14</b>	<b>0</b>	<b>14</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>0</b>	<b>20</b>	<b>0</b>	<b>20</b>	<b>0</b>	<b>20</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 22.06.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	RR S				NIL							-
5	RR N				NIL							-
6	RR E				NIL							-
7	HYD				NIL							-

TSSPDCL - LMRC / Corporate office

Date: 22.06.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Lokirev	Lingampally	11kv	Jadcherla	02.15	09.34	07.19		11Kv Phase To Phase Near Lingampally( Vi).	-
1	NLG	Jalalpuram	Gottiparthi	11kv	Suryapeta	04.30	06.50	02.20	EL	Insulator failed	-
2		Garidepally	L B Nagar	11kv	Huzurnagar	03.00	05.00	02.00	EL	11 KV LINE SNAPPED	-
3		Ponugodu	Ponugodu	11kv	Huzurnagar	07.15	09.40	02.25	EL	11 KV JUMPER CUT	
4		Kalmaicheruvu	Ganugabanda	11kv	Huzurnagar	06.35	09.05	02.30	EL	11 KV JUMPER CUT	
5		G.Malkapuram	Pulichinthala Project	11kv	Huzurnagar	05.40	07.30	02.10	EL	11 KV LINE SNAPPED	
6		Sirikonda	Balluthanda	11kv	Huzurnagar	09.30	12.00	02.30	EL	11 KV LINE SNAPPED	
7		Annaparthi	Annaparthi	11kv	Nalgonda	05.30	08.00	02.30	EL	Insulator failed	
8		Mushampally	Mushampally	11kv	Nalgonda	08.00	09.30	01.30	EL	Jumper cut	
9		Narketpally	Mandra	11kv	Nalgonda	09.40	12.00	02.20	EL	Tree fallen on line	-
10		Chada	Chada	11kv	Bhongir	08.00	11.30	03.30	EL	11 KV Insulator Failed Near Chada Village	-
11		Yennaram	Kakkireni	11kv	Choutuppal	08.15	12.20	04.05	EL	11 kv Pin Insulator Failed Near Kakkireni Village	-
12		Jangam	Puttapaka	11kv	Choutuppal	09.00	13.50	04.50	EL	11 kv Disc Failed Near Sub-station 10 no.Pole	-
1	MDK	Bollaram-II	Vasavidatta	11kv	Patancheru	11.20	12.07	00.47		B/D due to Jumper cut	-
1	RR N	Uddamarri	Shneha Form	11kv	Medchal	05.00	07.30	02.30	BD	11KV Pin Insulator failed at Uddamarri Road	-
2		Thumkunta	Thumkunta	11kv	Medchal	11.48	12.46	00.58	BD	11KV Pin Insulator failed at Thumkunta Asramam	-
1	RR E	AS Rao Nagar	Gokul Nagar	11kv	Sainikpuri	01.45	02.20	00.35		UG Cable fail at Good Luck Hotel Load Add on AS Rao Nagar feeder (Artisan/Balraju)	-
1	HYD N	Raheja	Gafoor Nagar	11kv	Jubilee Hills	05.05	06.20	01.15	EL,OL-Rph	Pin Insulator flash over at Gafoor Nagar	-----
2		Yousufguda	Celebrations	11kv	Jubilee Hills	05.26	07.02	01.36	EL	No Visible Fault	Arranged B/F on 11KV J' Hills P.S for
1	HYD S	Panjasha	Pancha Mohalla	11kv	Charminar	02.25	04.06	01.41	All Indication	No Visible Fault	Arranged B/F on 11KV Charminar for