

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		8		8		8			
3	MDK	107	933	2	1	2	1	2	1			
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	14	2	14	2	14	0	0	
	Grand Total	1082	6468	2	17	2	17	2	17	0	0	

TSSPDCL - LMRC / Corporate office

Date: 28.06.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Kandi	HFC I	33KV	Sangareddy	20.25	22.30	02.05		BD due to Insulator failed	HFC I	-
2		Kandi	SKOL	33KV	Sangareddy	20.05	04.30	08.25		BD due to Disk failure	SKOL	-

TSSPDCL - LMRC / Corporate office

Date: 28.06.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Annasagar	Tatikonda	11KV	Jadcherla	09.00	13.04	04.04		11KV Phase To Phase Near Tatikonda(Vi).	-
1	NLG	Chandampeta	Siddapuram	11KV	Devarakonda	10.00	12.27	02.27	E/L	HT/LT	-
2		Cheedella	Gajula Malkapuram	11KV	Suryapet	05.40	07.30	01.50	E/L	Tee branch fallen on the line	-
3		Dirincherla	Narsaigudem	11KV	Huzurnagar	08.00	10.10	02.10	E/L	11KV Line Snapped	-
4		Keethavarigudem	Kothagudem	11KV	Huzurnagar	08.40	09.40	01.00	E/L	11KV Line Snapped	-
5		Thogarrai	Gudibanda	11KV	Huzurnagar	15.40	16.40	01.00	E/L	11KV Jumper Cut	-
6		Bibinagar	Saket India	11KV	Bhongir	08.10	10.59	02.49	O/L	2 Different Places 11 kv Line Snapped Near Andhra center Gudur Village	-
7		Voligonda	Nagaram	11KV	Choutuppal	13.10	14.05	00.55	O/L	Phase to Phase Near Nagaram Village	-
8		Sangem	Sangem	11KV	Choutuppal	05.25	07.42	02.17	E/L	11KV Disc Failed Near Sangem Village	-
1	MDK	Sadashivapet	TSM	11KV	Sangareddy	11.30	12.50	01.20		B/D due to Jumper cut at Peddapur	-
1	SDP	Gandipally	Gandipally	11KV	Husnabad	00.00	07.00	07.00		3 Ph BD,1 Ph ok,Insulator failure	-
2		Katkur	Mallaram	11KV	Husnabad	05.00	10.00	05.00		BD,Conductor snapped	-
3		Koheda	Theegalakuntapally	11KV	Husnabad	00.00	08.15	08.15		BD,Insulator failure	-
4		Pandilla	Pandilla Rural	11KV	Husnabad	00.50	08.10	07.20		BD,Trees fallen	-
1	RR S	KPHB	KPHB	11KV	Kondapur	14.47	16.25	01.38		CT Secondary TB burnt in braker control pannel	-
1	RR E	Chengicherla	MY Villas	11KV	Keesara	12.40	13.50	01.10		11KV Brass patti at Anu Shakthi Nagar	-
1	HYD S	Asmangadh	Gowtham Nagar	11KV	VIII	11.15	12.20	01.05	EL,OL-Rhp	Jumper B/o of Auto Reclosure at Red Cross Society	-