

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988		12		12		12			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	16	2	16	2	16	0	0	
	Grand Total	1082	6468	2	20	2	20	2	20	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.06.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Peddmandaddi	33kv	Wanaparthi	18.34	18.50	00.16	E/L	Not Rectified Due to Disc Failure	Peddmandaddi	-
1	MDK	Zaheerabad	Jharasangam	33kv	Zaheerabad	01.00	06.40	05.40		BD due to Jumper cut	Jharasangam	-

TSSPDCL - LMRC / Corporate office

Date: 29.06.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Donur	Singamdoddy	11KV	Jadcherla	11.30	13.30	02.00		11KV Jumper Cut near Singamdoddy	-
2		Annasagar	Tatikonda	11KV	Jadcherla	06.28	10.00	03.32		11KV Phase to Phase near Tatikonda	-
1	NLG	Yerkaram	Yerkaram	11KV	Suyapeta	10.30	12.45	02.15	E/L	Conductor snapped	-
2		Mattapally	Sulthanpuram thanda	11KV	Huzurnagar	06.00	09.30	03.30	EL	11 KV LINE SNAPPED	-
3		Kalmalcheruvu	Ganganagar	11KV	Huzurnagar	02.30	5:30	03.00	EL	11 KV JUMPER CUT	-
4		Repala	Kalakova	11KV	Huzurnagar	07.00	09.30	02.30	EL	11 KV LINE SNAPPED	-
5		Alingapuram	Gundlapahad	11KV	Huzurnagar	10.00	13.00	03.00	EL	11 KV JUMPER CUT	-
6		Chandur	Gundrampally	11KV	Nalgonda	13.00	15.45	02.45	EL	11 KV Line Jumper Cut	-
7		Tatikol	Kacharam	11KV	Devarakonda	10.30	13.30	03.00	EL	11 KV Line Jumper Cut	-
8		Anantharam	Hanmapuram	11KV	Bhongir	05.00	07.00	02.00	EL	11 kv Jumper Cut Near Hanmapuram Village	-
9		NG.Bandal	Gandhamalla	11KV	Bhongir	05.00	07.45	02.45	EL	Tree Branches Fallen	-
10		Paladugu	Duppelly	11KV	Bhongir	08.00	11.40	03.40	OL	11 kv Line Snapped	-
11		Addagudur	Addagudur	11KV	Bhongir	09.00	11.55	02.55	EL	Bird Fallen at line	-
12		Malkapur	Malkapur Agl	11KV	Choutuppal	11.40	13.40	02.00	EL	11 KV Line Jumper Cut	-
1	MDK	Gaddapotharam -I	Kajipally Industrial	11KV	Patancheru	15.55	17.40	01.45		B/D due to Insulator failed	-
2		Sangareddy- T-I	Friday Market	11KV	Sangareddy	10.25	11.20	00.55		BD ue to Disk failed	-
1	RR N	Devarayamjal	Kottapet	11KV	Medchal	11.45	12.30	00.45	EL	11KV Pin Insulator failed at Radhika Garden	-
2		Medchal	IDA Kistapur	11KV	Medchal	16.45	17.51	01.06	EL	11KV Pin Insulator failed at Rockwell Company	-
1	RR E	Chengicherla	MY villas	11KV	Keesara	14.00	15.30	01.30		T/F LUG cut at Attala compamany	-
1	HYD S	Kulsumpura	Gandi Hanuman	11KV	Charminar	20.50	22.02	01.12	EL	Bunch Cable fault at Hanuman Temple	-