

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	1	1	1	1	1	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		5		5		5			
3	MDK	107	933		1		1		1			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	7	0	7	0	7	0	0	
	Grand Total	1082	6468	1	8	1	8	1	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 03.11.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	RR N	132KV Malkaram	33KV Shameerpet	33KV	Medchal	13.08	15.27	02.19	BD	No visible fault	33KV Shameerpet	-

TSSPDCL - LMRC / Corporate office

Date: 03.11.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nuthankal	Pilumalla	11KV	Suryapet	04.00	06.40	02.40	E/L	11Kv Insulator failed	-
2		Janpahad	Janpahad	11KV	Huzurnagar	06.00	07.30	01.30	E/L	11Kv Line Snapped	-
3		Dirincherla	Narsaigudem	11KV	Huzurnagar	08.30	10.10	01.40	E/L	11Kv Line Snapped	-
4		Bibinagar	Gudur	11KV	Bhongir	06.00	09.15	09.15	E/L	11kv Insulator Failed Near Gudur (V)	-
5		Chada	Kondapuram	11KV	Bhongir	14.30	17.00	02.30	O/L	11kv Line Snapped Near Kondapuram (V) out side	-
1	MDK	Sadasivpet	Jogipet	11KV	Sangareddy	06.05	08.35	02.30		BD due to Pin binding failed	-
1	SDPT	Husnabad RW	Pandilla	11KV	Husnabad	10.30	11.55	01.25		BD due to Conductor snapped	-
1	RR N	Medchal	Apparel Park	11KV	Medchal	13.49	14.29	00.40	BD	11KV Post of Insulator failed near Apparel Park	-