

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	1	4	1	4	1	4			
3	MDK	107	933									
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	6	1	6	1	6	0	0	
	Grand Total	1082	6468	1	8	1	8	1	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.11.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Wadapally	Haritha	33kv	Miryalaguda	04.30	08.30	04.00	E/L	B/D due to Conductor snapped	Haritha	-

TSSPDCL - LMRC / Corporate office

Date: 04.11.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karkonda	Khanapur	11kv	Jadcherla	11.25	13.37	02.12		11KV Jumper cut near Khanapur	-
1	NLG	Penpahad	S. R Palem	11kv	Suryapeta	16.00	17.20	01.20	E/L	Conductor snapped	-
2		Kamareddygudem	Brundavanpuram	11kv	Miryalguda	08.10	09.57	01.47	E/L	Insulator failure	-
3		Rajavaram	Thirumalagiri	11kv	Miryalguda	02.00	03.43	01.43	E/L	Insulator failure	-
4		Peddakandukur	Bahupet	11kv	Bhongiri	09.40	12.15	02.35	EL	11kv Disc Failed near Bahupet Village	-
1	SDPT	Bejjanki	Kallepally	11kv	Husnabad	20.10	20.50	00.40		B/D due to Jumper cut	-
1	RR N	UMCC	Mahadevpuram	11kv	Medchal	07.35	08.00	00.25		HT/LT Line Melted at Yandamudi Layout	-
1	HYD N	Pragatools	Raj Foods	11kv	VI	13.00	14.14	01.14	EL,OL-Bph	UG Cable damaged at Shivaji Statue, R.R.Nagar	13:27 Hrs partial fdr charged (20/40 Amps)