

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2								
2	NLG	144	988	1	3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	3	0	3	0	3	0	0	
	Grand Total	1082	6468	3	6	0	6	0	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 09.11.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kosgi	Surayapally	33KV	Nagarkurnool	01.40	07.26	05.46	E/L	Chemeleon Fallen on the Line Challapur	Kosgi	No
2		220KV Palkonda	Kothamolgera	33KV	Mahabubnagar	02.39	07.43	05.04	E/L	Insulator replaced at Amistapur	220KV Palkonda	No
1	NLG	Dirshincherla	Keethavarigudam	33KV	Huzurnagar	13.46	16.53	03.07	EL	Jumpet Cut		-

TSSPDCL - LMRC / Corporate office

Date: 09.11.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Koppole(K)	Beemavaram	11KV	Nalgonda	12.30	15.10	02.40	EL	Jumper cut	-
2		Dirincherla	Narsaigudem	11KV	Huzurnagar	16.00	17.10	01.10	EL	11 KV JUMPER CUT	-
3		Champur	Singaram	11KV	Bhongir	14.40	16.50	01.10	EL	11kv Insulator Failed near Singaram Village	-
1	RR N	Kistapur	IDA Hanuman	11KV	Medchal	17.20	17.55	00.35	BD	11KV Line cut and replaced at Hexa Chemical Company	-
1	RR E	Saketh	Jawahar Nagar	11KV	Keesara	11.40	12.26	00.46		Bird fallen on 11kv line at Ambedkar Nagar	-
1	HYD S	Kulsumpura	Ambedkar Nagar	11KV	IX	13.08	14.20	01.12	EL	Cable damaged at Ambedkar Nagar	Arranged B/F on 11KV Maha Laxmi Nagar feeder