

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		4		4		4			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	4	1	4	1	4	0	0	
	Grand Total	1082	6468	1	6	1	6	1	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 13.11.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Revally	33KV	Wanaparthi	17.00	23.00	06.00	EL	5 no Conductors snapped at line	Revally	-

TSSPDCL - LMRC / Corporate office

Date: 13.11.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ch.Annaram	Sangam	11KV	Nalgonda	13.00	15.20	02.20	EL	11 KV Line Junper Cut	-
2		Jalalpuram	MK Thanda	11KV	Suryapet	08.55	11.25	02.30	EL	Insulator failed	-
3		Mukundapuram	Somaram	11KV	Huzurnagar	05.30	06.45	01.15	EL	11 KV LINE SNAPPED	-
4		Mothkur	Mothkur Town	11KV	Bhongir	09.30	11.00	01.30	EL	11kv Line Snapped	-
1	RR N	Jeedimetla SS IV	Bhagyalaxmi	11KV	Jeedimetla	05.15	06.50	01.35	EL/OL	UG Cable kit failure opp Varsha Company,given back feeding from JDM SS I	-
1	RR E	Narapally	Narapally Industrial	11KV	Keesara	07.10	08.50	01.40		11KV Pin Insulator failed at Venkatadri Township	-