

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	5	1	5	1	5			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	7	2	7	2	7	0	0	
	Grand Total	1082	6468	2	9	2	9	2	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 17.11.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33KV	Narayanapet	09.55	11.50	01.55		B/D due to LA Blast	Vepoor	-
1	NLG	Miryalguda	Tripuraram	33KV	Miryalguda	00.00	05.55	05.55	EL	No visible fault	Tripuraram	-

TSSPDCL - LMRC / Corporate office

Date: 17.11.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Chandampeta	Mudidandla	11kv	Devarakonda	16.10	16.50	00.40	EL	HT/HT	-
2		Kudakuda	Ilapuram	11kv	Suryapet	16.00	17.30	01.30	EL	Insulator failed	-
3		Nadigudem	Karvirala	11kv	Huzurnagar	09.00	11.40	02.40	EL	Due to tree branch fall on 11Kv line	-
4		Motakondur	Cholleru Agl	11kv	Bhongir	12.55	13.55	01.00	EL	11 KV Line Snapped	-
5		Suddala	Theriyala	11kv	Bhongir	09.00	12.50	04.20	EL	11 kv Insulator Failed	-
1	SDPT	Thotapally	Thotapally (R)	11kv	Husnabad	08.20	12.17	03.57		B/D due to Insulator failure	-
2		Bekkal	Kutigal	11kv	Husnabad	08.00	12.25	04.25		B/D due to Jumper problem	-
1	RR S	Nanakramguda	Church	11kv	Gachibowli	00.40	01.57	01.17		11KV AB CableEnd kit Failed near Hanuman temple at Nanakramguda	
1	RR E	Mallapur	Noma	11kv	Habsiguda	19.40	21.50	02.10		Tree Fallen on 11KV Line at Dathathreya Nagar	-