

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044	1		1		1				
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		4		4		4			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>4</b>	<b>2</b>	<b>4</b>	<b>2</b>	<b>4</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>6</b>	<b>3</b>	<b>6</b>	<b>3</b>	<b>6</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 18.11.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Alampur	Undavelly	33KV	Gadwal	19.15	19.45	00.30	O/L	Due to Fire on CT-B Phase Studd at 132KV SS Alampur SS	Undavelly	Alternate Supply Arranged from 33KV Alampur at 19:45Hrs.
1	MDK	Pashamilaram	Matix	33KV	Sangareddy	07.50	09.20	01.30		B/D due to Lightning arrester failed in Matix Company	Matix	-
1	HYD N	132KV Jubilee Hills	Prashasan Nagar	33KV	Kalyan Ngr	16.53	16.58	00.05	EL,OL-Rph	Cable damaged by R&B wing at Opp: HMDA Park, Road No.51	Prashasan Nagar	Loads transferred onto 132KV J' Hills SS via 33KV Asif Nagar Ckt-2

TSSPDCL - LMRC / Corporate office

Date: 18.11.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kudakuda	Kudakuda Agl	11KV	Suryapet	11.40	12.40	01.00	E/L	Tree branch fallen	-
2		Nadigudem	Ratnavaram	11KV	Huzurnagar	12.30	14.30	02.00	EL	Due to HT/LT fault occurred	-
3		Datherpally	Jangamapally	11KV	Bhongir	04.00	07.45	03.45	EL	11 kv Insulator Failed Near Mailar gadda Thanda. 3 Phase B/d Single phase	-
4		Choutuppal	Thangedipally	11KV	Choutuppal	02.00	08.40	06.40	EL	11KV Insulator Failed near Rangamma Well Thangdapally Village 3 Phase B/d Single phase ok	-
1	RR N	Dp Pally SS II	Idian Oil	11KV	Jeedimetla	11.55	12.55	01.00	BD	Tree branch fall on the 11kv line MRO Office back side	-
2		Dp Pally SS II	Idian Oil	11KV	Jeedimetla	14.40	16.55	02.15	BD	11kv line cut MRO Office back side	-