

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933		1		1		1			
4	SDPT			1	1	1	1	1	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	8	3	8	3	8	0	0	
	Grand Total	1082	6468	4	11	4	11	4	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 22.11.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33KV	Mahabubnagar	14.58	19.05	04.07	E/L	Foreign material fallen on 33KV line	Vepoor	No
1	NLG	Dirshincherla	Keethavarigudem	33KV	Huzurnagar	6:00	10:00	4:00	EL	Due to 33KV Insulators failure	Keethavarigudem	No
1	SDPT	Palamakula	Baddipadaga	33KV	Siddipet	8:15	10:05	1:50		No visible fault	Baddipadaga	No
1	RR N	132KV Medchal	Kompally	33KV	Medchal	7:40	11:24	3:44		33KV Jumper cut and replaced at Kompally Flyover	Kompally	No

TSSPDCL - LMRC / Corporate office

Date: 22.11.19

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Pamanagundla	Pittampally	11KV	Nalgonda	12:17	17:06	4:49	E/L	Crow Died on 11KV Line	No
2		Kethepally	Gudiwada	11KV	Nalgonda	07.15	12.30	05.15	E/L	HT/LT Line melting	No
3		Ch.Annaram	Ch.Annaram	11KV	Nalgonda	04.28	11.00	06.32	E/L	11KV Line tap on 11KV 'X' Arm	No
4		Kattangur	Bollepally	11KV	Nalgonda	05.10	08.50	03.40	E/L	11KV Jumper cut	No
5		Phanigiri	Phanigiri Agl	11KV	Suryapet	07.40	09.15	01.35	E/L	Conductor Snapped	No
6		Nemaragomula	Jiyapally	11KV	Bhongiri	8:30	10:00	1:30	EL	11KV Line snapped near Jiyapally Village	No
1	MDK	Hadnoora	Town	11KV	Jogipet	18:40	19:40	1:00		Tree branches fallen on the line	No
1	SDPT	Thotapally	Devakkapally	11KV	Husnabad	10:48	13:02	2:14		Line cut	No
1	RR N	Athiwelly	Gubba	11KV	Medchal	4:40	7:20	2:40		11KV Jumper cut and replaced at near by SS	No
1	HYD N	Osm. University	Mettuguda	11KV	V	13.47	14.50	01.03	EL,OL	DTR Cable fault at Mettuguda Church	No
1	HYD S	Gosha Mahal	Hindi Nagar	11KV	IX	04.40	07.35	02.55	EL	DTR fault at Ravi Petrol Pump	No