

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	6	0	6	0	6	0	0	
	Grand Total	1082	6468	0	8	0	8	0	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 25.11.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	SDPT				NIL							-
5	RR S				NIL							-
6	RR N				NIL							-
7	RR E				NIL							-
8	HYD				NIL							-

TSSPDCL - LMRC / Corporate office

Date: 25.11.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Donur	Vaspula	11kv	Jadcherla	14.08	16.12	02.04		BD 11KV Jumper cut near Vallabraopally	-
1	NLG	Mattampally	Allipuram	11kv	Huzurnagar	05.00	06.45	01.45	EL	11 KV LINE SNAPPED	-
2		Arjalabavi	Arjalabavi AGL	11kv	Nalgonda	14.00	16.25	02.25	EL	Jumper Cut	-
3		Akaram	Vaddipamula	11kv	Nalgonda	12.30	15.00	02.30	EL	Insulator failed	-
4		Chada	Kondapur	11kv	Bhongiri	00.15	09.30	09.15	EL	11 kv Pin Insulator Failed Near Kondapur Village	-
5		Mothkur	Anajipur	11kv	Bhongiri	08.30	10.45	02.15	EL	11 kv Line snapped Near Anajipur Village	-
1	RR N	Petbasheerabad	Vaishnavi Enclave	11kv	Medchal	05.50	06.45	00.55		No visible Fault	-
2		Kistapur	IDA Hanuman	11kv	Medchal	13.45	14.30	00.45		Tree Branches fallen on the 11KV Line at Rudra Pratap Company & Ravalkole Vaagu	-