

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		7		7		7			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	7	1	7	1	7	0	0	
	Grand Total	1082	6468	1	13	1	13	1	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.11.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Shadnagar	Stem Core	33KV	Shadnagar	12.05	14.25	02.20	E/L	Pin binding failed at Nagulapally Road	Stem Core	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Aitipamula	CH.Annaram	11KV	Nalgonda	12:00	14:15	2:15	EL	Jumper cut	No
2		Pamangundla	Yerrasanigudem	11KV	Nalgonda	07.35	08.45	01.10	EL	Insulator failed	No
3		Thungathurthy	Ganugubanda	11KV	Suryapet	07.30	11.00	03.30	EL	Disc & Insulator flashover	No
4		Jammigadda	Kesaram	11KV	Suryapet	03.30	07.20	03.50	EL	Bird fallen on the line	No
5		Palakeedu	Bothalapalem	11KV	Hurzurnagar	13.10	14.30	01.20	EL	Single phase Transformer failed	No
6		Paladugu	Duppelly	11KV	Bhongir	11.05	12.50	01.45	EL	11KV Line snapped	No
7		Golanpally	Golanpally	11KV	Choutuppal	3:20	6:20	3:00	EL	11KV Line Snapped	No
1	RR N	UMCC	RM Nagar	11KV	Medchal	18:40	19:17	0:37		HT Cable melted at Umadevi Nagar	No
2		Dulapally	IDA-II	11KV	Medchal	11.40	12.48	01.08		11KV Jumper cut at MPT Industry	No
1	RR E	IDAuppall	L.N nagar	11KV	Habsiguda	7:58	9:10	1:12		Tree branches fallen on 11kv line at TV colony road no 4	No
2		Anandbagh	Balaram Nagar	11KV	Sainikpuri	03.00	04.10	01.10		No visible fault	No
1	HYD N	I.D.P.L.	S.V.C.I.E.	11KV	VI	23.05	00.15	01.10	EL,OL	HT Line snapped at S.V.C.I.E., Bala Nagar	No
1	HYD C	Golconda	Darga Cable	11KV	VII	12.19	13.40	01.21	EL,OL-Bph	Bird fault on lines at Pochamma Basti	At 13:08 Hrs parial feeder (40/70) charged