

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		8		8		8			
	Total	606	3055	0	14	0	14	0	14	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	3	4	3	4	3			
2	NLG	144	988		7		7		7			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	10	4	10	4	10	0	0	
	Grand Total	1082	6468	4	24	4	24	4	24	0	0	

TSSPDCL - LMRC / Corporate office

Date: 03.10.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Manthathi	33KV	Nagarkurnool	01.40	09.02	07.22	E/L	Isolator jumper reconnecting at 132KV SS	Manthathi	No
2		Ghanapur	Solipur	33KV	Wanaparthi	01.25	07.20	05.55	E/L&O/L	Due to tree fallen on the line & insulator damaged at Shahpur Gate	Solipur	Alternate Supply Arranged From 33KV Solipur from 132KV SS Wanaparthi
3		Chinnamaroor	Kalwarala	33KV	Wanaparthi	02.30	02.45	00.15	E/L	33KV Conductor snapped	Kalwarala	Alternate Supply Arranged From 33KV Weepangandla
4		Gadwal	Oil Seeds	33KV	Gadwal	1:45	8:40	6:55	E/L	Disc flash over at Pudur cut point	Oil Seeds	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kothamolgara	Maddiagatla	11KV	Jadcherla	01.20	06.00	04.40		Due to 11 KV wire cut near maddigatla.	No
2		Peddarevelly	Chinnarevelly	11KV	Jadcherla	23.10	08.00	08.50		Due to 11 KV insulator failed near Koilakunta Thanda	No
3		Boothpur	Amistapur	11KV	Jadcherla	01.00	12.45	11.45		Due to 11 KV disc failed near Amistapur	No
1	NLG	Edulur	Munukuntla	11KV	Nalgonda	16:15	18:30	2:15	EL	11 KV Line jumper cut	No
2		Akaram	Akaram	11KV	Nalgonda	12.50	14.50	02.00	EL	11 KV Line jumper cut	No
3		Pamanagundla	Pittampally	11KV	Nalgonda	06.00	10.28	04.28	EL	Insulator failure	No
4		Thungathurthy	Banda Ramaram	11KV	Suryapet	05.30	07.00	01.30	EL	Tree branch fallen on the line	No
5		Jammigadda	Town Feeder	11KV	Suryapet	16.40	18.15	01.35	EL	Tree branch fallen on the line	No
6		Keethavarigudem	Kothagudem	11KV	Huzurnagar	07.20	10.30	03.10	EL	Due to 11KV insulator failed	No
7		Gaddipaly	Kuthubushapur	11KV	Huzurnagar	6:15	9:15	3:00	EL	Due to 11KV line snapped	No
1	RR N	Subhash Nagar	Jairam Nagar	11KV	Medchal	6:00	6:45	0:45	EL	Bird fallen on the 11KV line at Beema Developers	No
2		Subhash Nagar	Ramaraj Nagar	11KV	Medchal	09.20	10.05	00.45	EL	No visible fault	No
3		UMCC	Mini Industry	11KV	Medchal	11.54	13.00	01.06	EL	Stick fallen on the 11KV line at Vivekananda Nagar	No
4		Ravalkole	Cheruvukatta	11KV	Medchal	13.19	14.14	00.55	EL/OL	11KV Conductor snapped and replaced at Lokesh Company Opp	No
1	RR E	NGRI	HMT Nagar	11KV	Habsiguda	17:20	18:22	1:02		11KV UG Cable failed at St.No.02 HMT Nagar	No
2		IDA Uppal	Metro	11KV	Habsiguda	03.09	05.41	02.32		11KV UG Cable failed near Srikrishna Chemical Company backside	No
1	HYD N	Kalyan Nagar	Krishna Nagar	11KV	X	08.38	09.55	01.17	EL,OL-Rph	Sparking AB Switch at Rahamath Nagar & Faulty loads of 11KV Rahamath Nagar fdr	No
2		Bhudevi Nagar	Adarsh Nagar	11KV	C-VI	16:14	17:50	1:36	EL	No Visible Fault	No
3		Bhudevi Nagar	Ram Raj Nagar	11KV	VI	16:30	17:40	1:10	EL,OL	Pin Insulator flash over at Shanker Encave	No
4		Bowenpally	Gowtham Nagar	11KV	VI	16:30	18:20	1:50	All Indication	Tree branches fallen on lines at IAF Quarters	No
5		Kalyan Nagar	Laxmi Nagar	11KV	X	16:35	17:48	1:13	EL,OL-Rph	Pin Insulator flash over at SAO Madam House	No
6		Hakimpet	Hakimpet Airforce	11KV	C-VI	17.05	18.28	01.23	EL	Cable fault at Military Area	Arranged B/F on 11KV Risala Bazar feeder
1	HYD C	Asif Nagar	Hakimpet	11KV	VII	04.30	06.01	01.31	EL,OL	No Visible Fault	Arranged B/F on 11KV Military fdr
2		Durga Nagar	Sunder Nagar	11KV	II	17.06	18.10	01.04	EL,OL	Cable fault at Sunder Nagar	Partial feeder charged & Remaining fdr arranged B/F on 11KV Kamala Nagar feeder