

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	5	25	5	25	5	25			
7	RR(E)	168	403		10		10		10			
8	Hyd	194	1044	1	24		24		24			1 - No. 33KV Still
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>6</b>	<b>59</b>	<b>5</b>	<b>59</b>	<b>5</b>	<b>59</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988		11		11		11			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				11		8		8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>24</b>	<b>3</b>	<b>21</b>	<b>3</b>	<b>21</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>9</b>	<b>83</b>	<b>8</b>	<b>80</b>	<b>8</b>	<b>80</b>	<b>0</b>	<b>0</b>	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Krishna	33KV	Narayanpet	09.15	11.25	02.10	E/L	Due to LA Failure Near at Tangdi SS	Krishna	-
2		Achampet	Inole	33KV	Nagarkurnool	21.05	21.55	00.50	E/L&O/L	Insulator Failed at Gurramguda Location & Mannewaripally Isolator Opened at Inole supply stood OK	Inole	-
1	MDK	Gummadidala	GPSS-II	33KV	Patanceru	12.15	13.50	01.35		BD due to Pin Insulator failed	GPSS-II	-
1	RR N	132KV Chintal	33KV Chintal	33KV	Medchal	04.22	09.35	05.13	BD	33KV End Kit Failed and replaced at 132KV Chintal SS	33KV Chintal	-
2		132KV Medchal	33KV Aliabad	33KV	Medchal	13.43	16.55	03.12	BD	Tree fallen on the 33KV Line near 132KV Medchal SS	33KV Aliabad	-
3		132KV Medchal	33KV Medchal -I	33KV	Medchal	13.45	16.02	02.17	BD	Tree fallen on the 33KV Line at Unicorn Company	33KV Medchal -I	-
4		132KV Medchal	33KV Keshavaram	33KV	Medchal	13.50	16.07	02.17	BD	Tree fallen on the 33KV Line near 132KV Medchal SS	33KV Keshavaram	-
5		132KV Malkaram	33KV Shameerpet	33KV	Medchal	14.07	18.43	04.36	BD	33KV Pin Insulator failed at Bits Campus	33KV Shameerpet	-
1	HYD N	132KV Gunrock	Airport - James Street (DC Line)	33KV	Nehru Ngr	13.23			OL-R&Yph	Big tree fallen on Line, 1No. Tower damaged, 1No. Spun Pole broken & 3No. Poles X-Arms broken at Airport Quarters near 33KV Gymkhana SS	Airport - James Street (DC Line)	-

## TSSPDCL - LMRC / Corporate office

Date: 06.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karvena	Kothur	11KV	Jadcherla	11.15	13.50	02.35		Due to 11 KV wire cut near Kothur	-
1	NLG	Kudakuda	Iylapuram	11KV	Suryapet	12.50	15.45	02.50	E/L	11kv Insulator flashover	-
2		Gaddipally	Kutubshapuram	11KV	Huzurnagar	10.15	12.00	01.45	E/L	11 KV LINESNAPPED	-
3		Anatharam	Hanmapur	11KV	Bhongir	06.00	10.30	04.30	EL/OL	11kv Disc & 11kv Insulator & 11kv Line snapped near Hanmapur (V)	-
4		MR.Gudem	MR.Gudem	11KV	Bhongir	06.50	11.00	05.10	E/L	11kv Line Snapped near Baswapur (V)	-
5		Peddathanda	Peddathanda	11KV	Bhongir	04.00	08.40	04.40	E/L	11kv Insulator Failed near Maisammakunta	-
6		Ramlingampally	Jalalpur	11KV	Bhongir	06.00	10.00	04.00	E/L	11kv Disc Failed near Jalalpur (V)	-
7		Golankonda	Matoor	11KV	Bhongir	00.10	08.25	08.15	E/L	25kva DTR Failed near Matoor (V) 3 Phase B/d Single phase OK	-
8		Golankonda	Golankonda	11KV	Bhongir	06.30	08.00	01.30	E/L	11KV Line Snapped near Golankonda (V)	-
9		Pamkunta	Pamkunta	11KV	Bhongir	03.30	08.00	04.30	EL/OL	11kv Disc Failed near Pamkunta (V)	-
10		Pamkunta	Singaram	11KV	Bhongir	04.00	07.00	03.00	EL/OL	11kv Line snapped near Sinagaram (V)	-
11		Mothkur	Anajipur	11KV	Bhongir	04.00	07.50	03.50	EL/OL	11kv Line snapped near Anajipur (V)3 Phase B/d Single phase OK	-
1	MDK	Patancheru	MIA-II	11KV	Patancheru	13.20	16.15	02.55		BD due to Tree branches fallen on the line	-
1	SDP	Gandipally	Nandaram	11KV	Siddipet	00.00	12.10	12.10		Insulator failure same rectified	-
2		Gouravelly	Gudatipally	11KV	Siddipet	13.20	15.00	01.40		Insulator failure same rectified	-
3		Bejjanki	Kallepally	11KV	Siddipet	17.00	19.00	02.00		Gale and wind	-
4		Ramchandrapur	Vinjalpally	11KV	Siddipet	15.00				S-ph supply OK, 3-Ph BD	-
5		Begumpet	Ennampally	11KV	Siddipet	15.30	17.30	02.00		Disc failure same rectified	-
6		Regulapally	Mallamchervu	11KV	Siddipet	15.25	16.50	01.25		Insulator failure same rectified	-
7		Gurjakunta	Vechareni	11KV	Siddipet	14.25				S-ph supply OK, 3-Ph BD	-
8		Guruvannapet	Guruvannapet	11KV	Siddipet	00.00	06.55	06.55		Insulator failure same rectified	-
9		Nagapuri	Pothireddypalli	11KV	Siddipet	06.00	11.50	05.50		Disc failure same rectified	-
10		Dhoolmitta	Arjunpatla	11KV	Siddipet	15.30				S-ph supply OK, 3-Ph BD	-
11		Marmamula	Marmamula	11KV	Siddipet	15.25	16.07	00.42		Insulator failure same rectified	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Vemana Colony	Friends colony	11KV	Kukatpally	13.40	14.55	01.15	BD	11kv Pin Insultor Failure Opp 14 Homes friends Colony	-
2		K P HB	ShathaVahana colony	11KV	Kukatpally	14.26	16.15	01.49	BD	11kv Disk Failure At Ramkey Park	-
3		Nizampet	Journalist Colony	11KV	Kukatpally	14.10	15.20	01.10	BD	Due To Heavy rain	-
4		Vijayanagar	JalaKanya	11KV	Kukatpally	14.30	16.10	01.40	BD	11kv AB cable failure At pipe line Road	-
5		Vijayanagar	Jayanagar	11KV	Kukatpally	13.15	14.40	01.25	BD	Due To Heavy rain	-
6		Vijayanagar	Sapathagiri Colony	11KV	Kukatpally	13.20	15.50	02.30	BD	Tree Branches Fallen on The 11kv Line Near Reliance HUB	-
7		Suraram	Matrix	11KV	Jeedimetla	13.50	14.50	01.00	BD	TF HG fuse failure At golden Packing	-
8		Dulapally	Dulapally Village	11KV	Medchal	13.40	17.12	03.32	BD	Tree fallen on the 11KV Line at Kartheekavanam	-
9		Dulapally	Karteekavanam	11KV	Medchal	13.40	16.17	02.37	BD	No Fault	-
10		Kompally	Kompally	11KV	Medchal	13.53	17.35	03.42	BD	Tree fallen on the 11KV Line at Sureka Hosptial & Hanuman Temple	-
11		Petbasheerabad	Balaji Hospital	11KV	Medchal	13.40	19.10	05.30	BD	Tree fallen on the 11KV Line at NCL Colony	-
12		Petbasheerabad	Salmon Belmor	11KV	Medchal	13.45	19.20	05.35	BD	Tree fallen on the 11KV PHR Function Hall	-
13		Petbasheerabad	GBR Club	11KV	Medchal	14.35	19.30	04.55	BD	Tree fallen on the 11KV Line at Srinkath Nursery	-
14		Subhash Nagar	Jairam Nagar	11KV	Medchal	14.30	15.30	01.00	BD	Bird fallen on the 11KV Line at JK Nagar	-
15		Subhash Nagar	Jeedimetla	11KV	Medchal	14.30	15.15	00.45	BD	Tree fallen on the 11KV Line at Jeedimetla	-
16		HMT	Venkanna Hills	11KV	Medchal	13.40	15.45	02.05	BD	Tree fallen on the 11KV Line at Venkanna Hills	-
17		Subhash Nagar	Bank Colony	11KV	Medchal	14.30	17.10	02.40	BD	11KV Line cut and replaced at SBI Bank	-
18		Kompally	Aparna	11KV	Medchal	18.40	19.40	01.00	BD	Tree fallen on the 11KV Line at Aparna	-
19		Laxmapur	Naryanapur	11KV	Medchal	15.20	17.40	02.20	BD	5Nos 11KV Pin Insulator failed at Narayanapur Village	-
20		Town Medchal	Balaji Nagar	11KV	Medchal	13.58	15.10	01.12	BD	Tree fallen on the 11KV Line at Mukunda Theatre	-
21		Medicity	Rajabollaram	11KV	Medchal	17.05	18.15	01.10	BD	11KV Pin Insulator failed at Ganapuram Village	-
22		Kandlakoya	Kandlakoya	11KV	Medchal	14.50	17.05	02.15	BD	11KV Pin Insulator failed at Cheruvukatta	-
23		Kandlakoya	KV Reddy Nagar	11KV	Medchal	14.45	17.30	02.45	BD	Tree fallen on the 11KV Line at at Bio Sakshi dhaba	-
24		Devarayamjal	DMC	11KV	Medchal	13.30	16.00	02.30	BD	Tree fallen on the 11KV Line at DMC	-
25		Kandlakoya	Saigeetha Ashramam	11KV	Medchal	14.50	21.50	07.00	BD	7 Nos 11KV Pole damaged at Kompally Main road	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	IDA Uppal	Srikrishna	11KV	Habsiguda	05.02	06.15	01.13		Tree branches fallen on 11KV line near Oxico Company at IDA Uppal	-
2		St.No.08	Laxmi Nagar	11KV	Habsiguda	12.58	14.55	01.57		Tree branches fallen on 11KV line at Laxmi Nagar Colony	-
3		Kushaiguda	Kushaiguda	11KV	Sainikpuri	00.45	02.25	01.40		Lorry Dashed to 11Kv pole and pin Insulator failed near Vimal Show Room (AE)	-
4		Kushaiguda	Kushaiguda	11KV	Sainikpuri	13.33	14.20	00.47		Tree branches fallen on 11Kv line at Kushaiguda Industry (L.Insp Prathap Reddy)	-
5		Sainikpuri	Eshwarpuri	11KV	Sainikpuri	13.20	14.50	01.30		11Kv line cut at Esharpuri Lake (AE/SKP)	-
6		Sainikpuri	Sainikpuri	11KV	Sainikpuri	13.35	14.55	01.20		Ground petrolling done but no visible fault found (LM Chandu/Anil)	-
7		AS Rao Nagar	Maruthi Nagar	11KV	Sainikpuri	13.36	15.42	02.06		11Kv Insulator failed at E-Seva (LM Srinivas) due to Heavy Rain	-
8		Narapally	Prathap Singaram	11KV	Keesara	15.10	16.35	01.25		11KV Disc failed at Korremula Village	-
9		P&T Colony	NIN	11KV	Keesara	14.00	14.40	00.40		11KV Pin Insulator failed at NIN Colony	-
10		Chakripuram	S V Nagar	11KV	Keesara	13.54	15.30	01.36		11KV Jumper cut at S V Nagar Road No.02	-
1	HYD N	Zamistanpur	S.P.College	11KV	V	13.17	15.38	02.21	EL	No Visible Fault (Due to rain)	-
2		Zamistanpur	MCH Park	11KV	V	13.18	15.30	02.12	EL	Tree branches fallen on lines at MCH Park	-
3		Chilkaiguda	Rajya Laxmi Housing Corporation	11KV	V	13.22	15.20	01.58	EL	DTR Fault at Rajya Laxmi Housing Corporation	-
4		Bansilalpet	Viceroy	11KV	V	13.22	15.06	01.44	EL,OL-Rph	Tree branches fallen on lines at Zeera Club	-
5		Bansilalpet	Naganna Kunta	11KV	V	13.20	16.30	03.10	All Indication	Tree branches fallen on lines at Swastik Hotel	-
6		Patigadda	Jeera	11KV	V	13.23	15.00	01.37	EL	Tree branches fallen on lines at Rani Gunj	-
7		Addagutta	Addagutta	11KV	C-VI	13.25	15.45	02.20	EL	Auto recloser tripped at Bharath Petrol Pump	-
8		R.P.Nilayam	Naga Devatha Temple	11KV	C-VI	13.25	16.30	03.05	EL	Tree branches fallen on lines at Naga Devatha Temple & HT Jumper cut at Alwal Railway Track	-
9		Bhudevi Nagar	Maruthi Nagar	11KV	C-VI	13.40	15.05	01.25	EL,OL	Pin Insulator flash over at Maruthi Nagar	-
10		I.D.P.L	Bala Nagar	11KV	VI	13.25	14.25	01.00	EL	No Visible Fault (Due to rain)	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD S	Malakpet B-Block	C-Quarters	11KV	VIII	13.35	14.47	01.12	OL-Bph	DTR fault at C-Quarters	-
2		Chanchalguda	Kurmaguda	11KV	VIII	16.47	18.05	01.18	OL-Rph	Pin Insulator flash over at Matha Temple	-
1	HYD C	Indira Park	Indian Express	11KV	I	09.15	10.40	01.25	EL	DTR Cable End Kit failed at Love Bird	-
2		Jawahar Nagar	J.N.Home	11KV	I	13.25	15.24	01.59	EL	Tree branches fallen on lines at SRT 147	-
3		Chilalguda	Bholakpur	11KV	I	14.30	16.00	01.30	EL,OL-Rph	O/G Yph Insulator flash over at SS	-
4		Zamistanpur	Dayara Market	11KV	II	13.05	14.05	01.00	EL	No Visible Fault (Due to rain)	-
5		Batkammakunta	C.E.Colony	11KV	II	13.07	15.58	02.51	EL	Jumper cut at Nandaraj Goud DTR	-
6		Amberpet	Golnaka	11KV	II	13.10	14.55	01.45	EL,OL	Tree branches fallen on lines at Golnaka	-
7		Batkammakunta	Ramalayam	11KV	II	13.08	15.23	02.15	EL	Tree branches fallen on lines at Ramalayam	-
8		Batkammakunta	Ayyappa Temple	11KV	II	13.00	15.50	02.50	EL	Pin Insulator flash over at Ayyappa Temple	-
9		Amberpet	Amberpet	11KV	II	13.00	16.55	03.55	EL,OL-Rph	Tree branches fallen on lines at Ambepet PS	-
10		Fever Hospital	Nalla Kunta	11KV	II	13.25	15.30	02.05	EL	Lizard fallen on O/G AB Switch at SS	-
11		Industrial Area	Mother Dairy	11KV	II	13.25	15.15	01.50	All Indication	Tree branches fallen on lines at Nala	-
12		Golconda	Narayanamma College	11KV	VII	14.40	16.35	01.55	EL,OL-Bph	O/G Cable fault	Arranged B/F on 11KV Brindavan Colony fdr