

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		2		2				1No 33KV Feeders Still
2	NLG	144	988	1	3	1	3	1	3			
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	6	3	6	3	6	0	0	
	Grand Total	1082	6468	4	10	3	10	3	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	220KVSS Palkonda	Bhoothpur	33KV	Mahabubnagar	22.20	02.14 (08.10.19)	04.34	E/L	No visible fault		No
2		220KVSS Palkonda	Janampet	33KV	Mahabubnagar	22.20		01.40	E/L & O/L	Not Rectified Due to Heavy Rain & wind		No
3		Nagarkurnool	Nagarkurnool	33KV	Peddakothapally	22.53	05.46 (08.10.19)	06.53	O/L	No visible fault		No
1	NLG	Suryapeta	Chandupatla	33KV	Suryapeta	04.00	08.10	04.10	EL/OL	33 KV DISK FAILED		-

TSSPDCL - LMRC / Corporate office

Date: 07.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Jalalpuram	Velishala X Road	11KV	Suryapeta	03.30	08.00	04.30	E/L	Insulator flashover	-
2		Raghunadapalem	Raghunadapalem	11KV	Huzurnagar	19.00	20.40	01.40	EL	Due to 11kv insulator failure	-
3		Thurkapally	M.Gowraram	11KV	Nalgonda	13.00	15.30	02.30	EL	11KV Line Jumper Cut	-
1	SDPT	Dhoolmitta	Arjunpatla	11KV	Husnabad	09.00	12.00	03.00		BD,Conductor snapped	
2		Akkannapet	Pakilnayak Thanda	11KV	Husnabad	08.10	10.26	02.16		BD,HT/LT	
3		Gurjakunta	Vechareni	11KV	Husnabad	07.30	10.40	03.10		BD,Insulator failure	
1	RR S	Ayyappa Society	Allapur	11KV	Gachibowli	06.30	07.30	01.00		11kv UG Cable damaged at Police controlroom Ayyappa Society	-
1	RR E	Malkajiri	Hanumanpet	11KV	Sainikpuri	14.20	14.57	00.37		Bird fallen on 11Kv line at MK Nagar (AE/OP)	-
2		Chakripuram	SV nagar	11KV	Keesara	14.00	14.40	00.40		Tripped on EL/OL line petroling no visiable falt found	-
1	HYD N	Zamistanpur	Sanjeevapuram	11KV	Sec-Bad	07.03	08.55	01.52	EL,OL-Y&Bph	DTR fault at A.K Functional Hall (07:58 Hrs Partial feeder charged OK)	-