

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1	3	1	3	1	3			
7	RR(E)	168	403	3	6	3	6	3	6			
8	Hyd	194	1044		8		8		8			
	Total	606	3055	4	18	4	18	4	18	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	14	2	14	2	14	2			
2	NLG	144	988		4		4		4			
3	MDK	107	933									
4	SDPT			1		1		1				
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	15	6	15	6	15	6	0	0	
	Grand Total	1082	6468	19	24	19	24	19	24	0	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Peddakothapally	33KV	Nagarkurnool	22.53	09.42	10.49	O/L	No Visible Fault Due to Heavy Rain & wind		No
2		220KVSS Palkonda	Bhoothpur	33KV	Jadcherla	22.20	09.48	11.28	E/L	Due to Heavy Rain & Insulator Replacement		No
3		220KVSS Palkonda	Janampet	33KV	Jadcherla	22.20.00 07.10.19	09.48 08.10.19	11.28	E/L & O/L	Due to Heavy Rain & Insulator Replacement		No
4		220KVSS Palkonda	Bhoothpur	33KV	Jadcherla	17.25	00.06	06.41	E/L	Due to Rain & Alternate Supply Taken to 33KV Janampet Feeder		Alternate Supply Taken to 33KV Janampet Feeder
5		220KVSS Palkonda	Janampet	33KV	Jadcherla	17.04	22.25	05.21	E/L	Insulator Replacment		No
6		Mahabubnagar	Machanpally	33KV	Mahabubnagar	18.20	19.03	00.43	O/L	Machanpally Loads Tag on to 33KV Hanwada Feeder		Alternate Supply Taken to 33KV Hanwada Feeder
7		Achampet	Veltoor	33KV	Nagarkurnool	02.50	08.10	05.20	E/L	No Visible Fault Due to Heavy Rain		NO
8		Achampet	Nadimpally	33KV	Nagarkurnool	01.40	07.45	06.05	E/L	No Visible Fault Due to Heavy Rain		NO
9		Thirumalaipally	Willamkonda	33KV	Wanaparthi	00.35	01.00	00.25	E/L	Due to Rain & Alternate Supply Taken to 33KV Pebbaire Feeder		Alternate Supply Taken to 33KV Pebbaire Feeder in 132KV SS Wanaparthi
10		Wanaparthi	Peddmandaddi	33KV	Wanaparthi	00.30	07.30	07.00	E/L	No Visible Fault Due to Heavy Rain		No
11		Ghanpur	Kamaludinnpur	33KV	Wanaparthi	00.16	07.54	07.38	E/L	Jumper removing at Kamaludinpur Tapping		No
12		Ghanpur	Kamaludinnpur	33KV	Wanaparthi	18.07	19.12	01.05	E/L	No Visible Fault Due to Rain		No
13		Kothur	Sangem	33KV	Shadnagar	14.50	17.35	02.45	E/L	Jumper connecting at HBL Companyat Kothur		No
14		Kothur	Natco Chemical	33KV	Shadnagar	15.40	18.55	03.15	E/L	Replacement of Disc Insulator near byepas Road at Kothur		No
1	SDPT	Husnabad	Potharam	33KV	Husnabad	04.40	05.45	01.05		No Visible Fault Due to Rain		-
1	RR N	132KV Medchal	33KV Kompally	33KV	Medchal	17.38	20.08	02.30		33KV Pin Insulator failed at Kompally		-
1	RR E	Nagole	St.No-8	33KV	Habsiguda	18.15	22.47	04.32		33KV Jumper Cut in SS Yard		-
2		Nagole	NGRI	33KV	Habsiguda	18.27	18.36	00.09		33KV Feeder Break Down and Alternate Supply from 18:36 from 220KV Moulali from 33KV Azamabad		-
3		Nagole	Uppal	33KV	Habsiguda	18.15	21.10	02.55		33KV Feeder Break Down and Alternate Supply from 21:10 from 220KV Moulali from 33KV NGRI		-

TSSPDCL - LMRC / Corporate office

Date: 08.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Midjil	Kothur	11KV	Jadcherla	03.10	07.40	04.30		11KV Disc Failure Near Mallapur(Vi).	-
2		Addakal	C M Ched	11KV	Jadcherla	22.20	08.10	09.50		11KV Disc Failure Near Addakal(Vi).	-
1	NLG	Muppam	Yerrabelly	11KV	Miryalguda	16.30	17.10	00.40	EL	11 KV Pin insulator failure	-
2		Jalapuram	Velishala X Road	11KV	Suryapet	03.30	08.00	04.30	EL	Insulator flashover	-
3		Mukundhapuram	Dacharam	11KV	Huzurnagar	06.00	09.00	03.00	EL	Due to 11Kv Jumper cutted	-
4		Nadigudem	Lift	11KV	Huzurnagar	12.30	15.30	03.00	EL	Due to 11Kv line cutted	-
1	RR S	Nanakramguda	N'Widia	11KV	Gachibowli	17.15	20.23	03.08		11kv Jumper touched to Cros aram at Uruksa and 11kv Disk failed at Continetal hospital	-
1	RR N	Bowrampet	Bowrampet Village	11KV	Jeedimetla	17.31	18.31	01.00		Lv-II pin insulter failure in SS	-
2		Bowrampet	Coco- Cola	11KV	Jeedimetla	17.31	18.31	01.00		Lv-II pin insulter failure in SS	-
3		GP Pally	Maisammaguda	11KV	Medchal	13.10	14.25	01.15		Tree fallen on the 11KV Line at Satyam Forest	-
1		Idauppal	Srikrishna	11KV	Habsiguda	18.20	21.40	03.20		Disk fail at Organic company	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
2	RR E	Uppal Kalas	Market	11KV	Habsiguda	18.10	21.30	03.20		Tree fallen on 11kv line at main raod	-
3		Uppal Kalas	Shanthi nagar	11KV	Habsiguda	18.10	21.28	03.18		Coconut tree fallen on line Ab swicth at shanthi nagar	-
4		Boduppal	Indra nagar	11KV	Habsiguda	22.30	23.00	00.30		Insulator fail at Indra nagar kallva	-
5		Uppal	Raghavendra	11KV	Habsiguda	21.10	23.10	02.00		Iron pole fallen down near SS yard	-
6		Uppal	Adarsh nagar	11KV	Habsiguda	21.25	00.30	03.05		11KV pin insulaotr fail at Srinivas height near	-
1	HYD N	MLA Colony	Lotus Pond	11KV	Banjarahills	14.25	15.30	01.05	EL	Pin Insulator flash over at Manemma House	-
2		MLA Colony	Kalinga	11KV	Banjarahills	14.35	15.40	01.05	All Indication	No Visible Fault	-
1	HYD C	Golconda	Darga OH	11KV	Mehdipatanam	05.12	06.50	01.38	EL,OL-R&Bph	AB Cable fault at Vali School & Pin Insulator flash over at Erra Kunta	Arranged B/F on 11KV O.U.Colony feeder
2		I.T.I Mallepally	Anjuman	11KV	Mehdipatanam	13.59	15.13	01.14	EL,OL	Pin Insulator flash over at Milan Theatre	-
3		Asif Nagar	Military	11KV	Mehdipatanam	14.19	16.10	01.51	EL,OL	CT PT fault Jungle Bit	-
4		Asif Nagar	N.S.F Colony	11KV	Mehdipatanam	14.20	15.35	01.15	EL,OL	Tree branches fallen on lines at NSF Colony	-
5		Asif Nagar	Padmanabha Nagar	11KV	Mehdipatanam	14.28	15.40	01.12	EL,OL	Disc Insulator flash over at Padmanabha Nagar	-
6	Indira Park	R.K.Mutt	11KV	Saifabad	15.40	16.43	01.03	EL	DTR fault at Reliance	-	