

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		6		6		6			
7	RR(E)	168	403		14		14		14			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	22	0	22	0	22	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	8	5	8	5	8	5			
2	NLG	144	988		9		9		9			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	8	15	8	15	8	15	0	0	
	Grand Total	1082	6468	8	37	8	37	8	37	0	0	

## TSSPDCL - LMRC / Corporate office

Date: 09.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kodangal	Kothur	33KV	Vikarabad	16.43	20.30	03.47	EL	Flash Over Disc Replaced Bomraspet to Kothur Bit not rectified	Kothur	-
2		Balanagar	G.R Cable	33KV	Jadcherla	07.44	08.48	01.04	EL	Isolator Opened at Ranga Reddy Guda	G.R Cable	-
3		Balanagar	G.R Cable	33KV	Jadcherla	16.00	17.25	01.25	EL	Tree follen on the line near Dhindi Rubber	G.R Cable	-
4		Thirumalaipally	Veltoor	33KV	Wanaparthy	13.25	13.58	00.33	EL	No Visible Fault Due to Heavy Rain	Veltoor	Alternate Supply Arranged from 33KV Kothakota at 13:58Hrs
5		leeza	Venkatapuram	33KV	Gadwal	18.35	22.30	03.55	EL	Jumpers open at Venkatapuram SS	Venkatapuram	-
6		Shadnagar	Salasar	33KV	Shadnagar	15.50	19.30	03.40	EL & OL	R Phase Pin Insulator Failed at Mogligidda Village	Salasar	-
7		Sri Rangapur	Kondurgu	33KV	Shadnagar	16.35	17.20	00.45	EL	No Visible Fault Due to Rain	Kondurgu	-
8		Sri Rangapur	Kondurgu	33KV	Shadnagar	22.54	00.10	01.16	EL	33KV Insulator Replacement	Kondurgu	-

## TSSPDCL - LMRC / Corporate office

Date: 09.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Donur	Singamdoddi	11KV	Jadcherla	00.00	08.04	08.04		11 KV insulater fail near singamdoddi.	-
2		Pollepally	Udandapur	11KV	Jadcherla	11.09	12.05	00.56		breaker problem at 33/11 kv pollepally.	-
3		Nawabpet	Rudraram	11KV	Jadcherla	06.50	10.06	03.16		11 KV wire cut near Rudraram.	-
4		Nawabpet	Kondapur	11KV	Jadcherla	06.52	11.48	04.56		11 KC disk fail near Kondapur.	-
5		Karkonda	Khanapur	11KV	Jadcherla	06.49	10.30	03.41		11 KV insulater fail near Khanapur.	-
1	NLG	Turkapally	Turkapally	11KV	Nalgonda	05.10	12.30	07.20	EL	Tree branch fallen	-
2		Mupparam	Yerrabelli	11KV	Miryalguda	06.00	07.43	01.43	EL	11KV Insulator failed	-
3		Utlapally	Yadgarpally	11KV	Miryalguda	03.00	05.45	02.45	EL	11KV Insulator failed	-
4		Damercherla	Narsapoor	11KV	Miryalguda	06.45	07.26	00.41	EL	11KV Conductor snapped	-
5		Ananthagiri	V.R.Puram	11KV	Huzurnagar	19.00	20.35	01.35	EL	Due to 11Kv disk failed	-
6		Gaddipaly	Gaddipally	11KV	Huzurnagar	09.00	10.45	01.45	EL	Due to 11Kv line cutted	-
7		Anantharam	Hanmapuram	11KV	Bhongir	06.00	08.50	02.50	EL	11kv Disc Failed	-
8		Motakondur	Motakondur	11KV	Bhongir	07.00	16.00	09.00	EL	11kv Postoff Insulator Failed	-
9		Arror	AR.Pally	11KV	Choutuppal	06.20	09.20	03.00	EL	11kv Insulator Failed	-
1	MDK	Inole	Indresham	11KV	Patancheru	17.35	19.00	01.25		B/D due to Jumper cut	-
1	RR N	Aleap	Punchavati	11KV	Jeedimetla	03.20	04.20	01.00	EI/OL	11kv Jumper cut at Punchavathi Colony	-
2		UMCC	RM Nagar	11KV	Medchal	09.00	09.25	00.25	BD	No Fault	-
3		Dulapally	IDA-I	11KV	Medchal	14.35	16.24	01.49	BD	11KV Disc Failed at Standard Laboratory	-
4		ICICI	Unique-I	11KV	Medchal	19.04	20.50	01.46	BD	No Fault	-
5		Aliabad	HBL	11KV	Medchal	19.20	20.28	01.08	BD	No Fault	-
6		Devarayamjal	DMC	11KV	Medchal	18.10	20.35	02.25	BD	11KV Pin Insulator failed at Eetela Rajendhar Form house	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Uppal	Bank colony	11KV	Habsiguda	01.40	05.00	03.20		Tree branches fallen on 11kv line at Raghavendra nagar & Jumper cut at LF Jr College	-
2		Mallapur	Mallapur (V)	11KV	Habsiguda	03.00	04.30	01.30		11KV Jumper cut at Baba Nagar Govt School	-
3		Uppal Bhagath	Saraswathi Nagar	11KV	Habsiguda	15.29	17.00	01.31		Line patrolling but no visible fault	-
4		Uppal	Adarsha Nagar	11KV	Habsiguda	15.50	16.40	00.50		25KVA DTR Brass patti cut at Srinivasa Heights Opposite	-
5		NGRI	Scientist Colony	11KV	Habsiguda	15.01	17.40	02.39		11KV Post of Insulator failed near St.No.02 HBG & 11KV Cable failed near Whitus Hospital	-
6		Mallapur	IDA	11KV	Habsiguda	07.00	07.40	00.40		CTPT Fault in Pinakini Company	-
7		Mallapur	IDA	11KV	Habsiguda	17.25	18.45	01.20		11KV Pin Insulator failed,Cable burnout & Brass patti cut at Pinakini Company	-
8		Uppal Bhagath	Saraswathi Nagar	11KV	Habsiguda	22.30	00.25	01.55		Tree fallen on 11kv line at Survey of India	-
9		Chakripuram	Shilpa	11KV	Keesara	01.35	05.50	04.15		11KV Pin Insulator failed near Modi Building	-
10		Keesara	Bogaram	11KV	Keesara	04.20	09.50	05.30		11KV Disc failed at Keesara Main Road	-
11		Ghatkesar	HPCL	11KV	Keesara	13.00	15.00	02.00		Line patrolling but no visible fault	-
12		Singapur	IT Park	11KV	Keesara	01.15	03.05	01.50		Line patrolling but no visible fault	-
13		Narapally	AP Meat	11KV	Keesara	03.45	05.30	01.45		11KV Disc failed at Baba Nagar	-
14		P&T Colony	NIN	11KV	Keesara	15.55	18.55	03.00		Line patrolling but no visible fault	-
1	HYD N	K.I.M.S	Krishna Nagar	11KV	V	14.42	16.25	01.43	EL,OL-Rph	Disc flash over at Sindhi Bank	-
2		Nehru Nagar	West Marredpally	11KV	C-VI	15.30	17.30	02.00	EL	Big tree fallen on lines at Megana Suresh Apt	-